

SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Crawford, Murphy, and Tilly, Inc.		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
REPORT NUMBER(S) 2008-001			
3. DOCKET NUMBER(S) 03037139	4. LICENSE NUMBER(S) 12-18642-02	5. DATE(S) OF INSPECTION September 22, 2008	
6. INSPECTION PROCEDURES USED 87124 (11/25/03)		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT David Earles, RSO	4. TELEPHONE NUMBER 217-787-8050
------------------------------------	-------------------------	---	--



Main Office Inspection

Next Inspection Date: **September 2013**

Field Office

Temporary Job Site
Inspection

PROGRAM SCOPE

The licensee is authorized to possess and use Troxler portable moisture density gauges at temporary job sites anywhere in the United States where the NRC maintains regulatory jurisdiction. The gauges are used at temporary job sites in Missouri. At the time of the inspection, 2 gauges were being used in the Kansas City, MO (306 miles) and Lake of the Ozarks, MO, (248 miles) too far away to attempt a temporary jobsite inspection.

Performance Observations

During the inspection, the inspector reviewed and discussed with the RSO: (1) Two tangible barriers required for gauge security and padlocks; (2) DOT requirements, hazmat recertification (every two years) and tests; (3) refresher training for gauge users; (4) dosimetry and records; (5) leak tests and inventories; (6) security of licensed material at each authorized storage facility; (7) survey meter availability; and (8) emergency procedures;