

**Facility Support Services, LLC**  
Environmental & Safety/Health Consulting Engineers

**Mr. Thomas Thompson**  
U.S. Nuclear Regulatory Commission  
Region 1, DNMS  
475 Allendale Road  
King of Prussia, PA 19406

October 8, 2008

**Re: Swiss Army Brands, Inc.**  
65 Trap Falls Road, Shelton, Connecticut

*p-7*  
*06-28699-03*  
*03035869*

2008 NOV -3 AM 10:51

RECEIVED  
REGION 1


**Dear Mr. Thompson,**

Per your request, Facility Support Services is sending you the following revisions for the Swiss Army Brands, Inc. facility, 65 Trap Falls Road, Shelton, Connecticut Decommissioning Report:

- During the decommissioning of the Swiss Army Brands, Inc. facility, 65 Trap Falls Road, Shelton, Connecticut, the racks and mezzanine areas were deconstructed by a construction contracting company. The construction contracting company deconstructed mezzanine G without approval from Facility Support Services. As a sample located in mezzanine G had high tritium levels, all of the beams and other structures located in this mezzanine were decontaminated. Random wipe sampling was then conducted as post decontamination samples.
- I have reviewed our field sampling location maps and located sample number 2902 in the watch repair room. I have attached a revised Figure 3: Watch Repair Area Sampling Locations to this letter. Sample number 2902 is located above Station 9.

If you may have any questions or require further information, please feel free to contact me at (203) 288-1281.

Sincerely,




Maria Sinnamon  
Environmental Project Manager

attachment

2685 State Street • Hamden, CT  
Phone: (203) 288-1281 • Fax: (203) 248-4409  
Toll Free: (866) 377-7495

*142208*  
NMSS/RGN1 MATERIALS-002

# WATCH REPAIR AREA SAMPLING LOCATIONS



NOT TO SCALE

Figure 3  
Swiss Army Brands, Inc.  
65 Falls Traps Road, Shelton, CT