1/17/92

Characterization for radionuclides inside and out
Ground Penetrating Radar to find the septic system
and the sedimentation pits.

B/147

1/17/92

Don Shabot Bob Berlin

Provided background of the project

ground water flows from the lake to the stream



Expect to close operations at the site by the end of the year

1957 – 1962 nuclear fuel element operation

DE Make piece
telecon HQ EPA R1
12/23/91

Public meeting with Public after issuance of the EPA order.

NRL to meet with Englehard soon within a month.

Englehard has been very cooperative with EPA

Soil contamination
Ground water.

EPA order to be issued in Feb 1992
negotiation could take months
90 days after the final order is issued the characterization ~~short~~ study proposal should be ready

NMSS attorney Mike Finkelstein ~~301~~ 96V-1535
301 504-1535

EPA contact will be with Jack Parrott

NRL to set up meeting in January

Don Chabot Englehard Industries 508-695-7811

Hazardous Waste
Mass DEP
Chernick

State of Mass has not been involved 21 E Program
EPA is taking the lead

The is a municipal well feild accross the lake from the incinerator site

trash incinerator - currently
hazardous waste incinerator 1976-1982
radioactive waste 1960 — ? ash stored onsite

Facility 14 acres fenced area
ground water contamination

Don Chabot to determine with the methodology

Jeff Barrett

Plainville toxic waste + Radiation Watch Group

508 - 699 - 8058

61 Spring Street
Plainville Mass 02762

EPA + DEP Phase III cleanup.

$200^{\pm 37}$ pCi/l α Well MW-05
$111^{\pm 16}$ pCi β

7/31/90 Study

Well MW3 39.6 ± 7 α well water
36.9 ± 5.6 β

W-4 34.4 ± 6.7 α
35.9 ± 5.0 β

Closed Sanitary Landfill incinerator used 1952-1961
on Carrol Street in Plainville