Enclosure 4

VIRGIL C. SUMMER NUCLEAR STATION

UNIT 1 -- SITE EXCAVATION

GENERAL SITE EXCAVATION OF OVERBURDEN MATERIALS

AERIAL VIEW OF POWERBLOCK EXCAVATION (CONTAINMENT BUILDING)



POWERBLOCK EXCAVATION TO BEDROCK – NORTHWEST VIEW

(ACROSS AUXILIARY BUILDING TO MAN STANDING AT CONTAINMENT BUILDING)

POWERBLOCK EXCAVATION TO BEDROCK – SOUTHWEST VIEW

(LOOKING AWAY FROM CONTAINMENT BUILDING)



NEAR VIEW OF VARIABLE ROCK STRUCTURE (WITH DIABASE DIKE)

POWERBLOCK EXCAVATION TO BEDROCK – SOUTH VIEW

(SHEAR FRACTURE RUNNING FROM NE/SW ACROSS CONTAINMENT BUILDING)



SIDE SLOPE OF POWERBLOCK EXCAVATION – TRANSITION OF ROCK TO SOILS



TYPICAL ROCK SURFACE VIEW OF POWERBLOCK EXCAVATION