





**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE City of Kirksville REPORT NUMBER(S) 2008-002		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-17623	4. LICENSE NUMBER(S) 24-18995-01	5. DATE(S) OF INSPECTION 12/17/08	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Todd Barnes – RSO	4. TELEPHONE NUMBER 660-627-1272
-----------------------------	------------------	--	-------------------------------------

Main Office Inspection      Next Inspection Date: 6/2013

Field Office

Temporary Job Site Inspection

**PROGRAM SCOPE**

The licensee is authorized to possess Troxler moisture/density gauges. The licensee possessed one troxler moisture/density gauge. The licensee had two trained authorized users. The gauge was normally used March through November during construction season. This inspection was to follow up on an escalated enforcement action regarding a security violation identified during a routine inspection on June 26, 2008. The inspection only focused on the security violation's corrective actions.

**Observations and Findings**

The licensee secured the gauge as described in the corrective actions via lock and chain to the gauge transportation case which was stored in a locked room. Only authorized individuals had access to room and gauge chain lock keys. The inspector interviewed the radiation safety officer and senior management on site; All were aware of the security requirements both while in storage in the main office and in the field.