SUB-AREA C

SUB-AREA D

SUB-AREA E

SUB-AREA G

BERM

SUB-AREA H

URANIUM WASTE POND #1 (BACKFILLED 1978)

SUB-AREA O

BURIAL AREA #4 HOLDING POND

SUB-AREA N

BURIAL AREA #2 (NORTH FIELD)

SUB-AREA M

NORTH INCINERATOR/ BURIAL AREA #3

SUB-AREA I

SUB-AREA I

PLUTONIUM BUILDING

SUB-AREA L

WEST SANITARY LAGOON (BACKFILLED 1993)

EAST SANITARY LAGOON (BACKFILLED 1993)

PLUTONIUM WASTE POND (BELOW) (BACKFILLED 1978)

NEW LINED SANITARY LAGOON (ABOVE)

SUB-AREA A

WAREHOUSE BLDG. #4

SUB-AREA K

URANIUM BLDG. #1

SUB-AREA N

D-01

NOTES
URANIUM (pCi/G U).

CIMARRON GAMMA SPEC SOIL COUNTER.

SITE SOIL BACKGROUND OF APPROX. 4.0 pCi/g U, NOT SUBTRACTED.

20 0 20
SCALE IN METERS

LEGEND
- 6 URANIUM 1 – 30 pCi/g U
- 58 URANIUM 31 – 100 pCi/g U
- 129 URANIUM 101 – 300 pCi/g U
- 327 URANIUM > 300 pCi/g U
- R HIT ROCK– NO SAMPLE

REV.	DESCRIPTION	DRWN BY:	CK'D BY:	APP'D BY:	DATE
0	DRAWING ISSUED.	JE	WR	JL	11/2/98

CIMARRON CORPORATION

CIMARRON FACILITY
PHASE II – SUB-AREA H
POST-REMEDIATION – AFFECTED AREA
SOIL SAMPLE RESULTS (1998)
SOIL SAMPLE ALIQUOT: SURFACE (0–6")

DRWN. BY	DATE	CHKD. BY	DATE	SCALE:
JE	7/25/98	WR	11/2/98	AS SHOWN

JOB NO.	DRAWING NO.	REV.
	98POAHASSS–0	0

...\CIMARRON\SUBAREAH\AFFECTED_AREA\SURFACE\98HSURSS