SUB-AREA C

SUB-AREA D

SUB-AREA E

SUB-AREA G

SUB-AREA H

URANIUM WASTE POND #1 (BACKFILLED 1978)

SUB-AREA O

BURIAL AREA #4 HOLDING POND

SUB-AREA N

SUB-AREA M

BURIAL AREA #2 (NORTH FIELD)

NORTH INCINERATOR/ BURIAL AREA #3

SUB-AREA I

SUB-AREA I

PLUTONIUM BUILDING

WEST SANITARY LAGOON (BACKFILLED 1993)

SUB-AREA L

EAST SANITARY LAGOON (BACKFILLED 1993)

PLUTONIUM WASTE POND (BELOW) (BACKFILLED 1978)

NEW LINED SANITARY LAGOON (ABOVE)

SUB-AREA A

SUB-AREA I

WAREHOUSE BLDG. #4

SUB-AREA K

SUB-AREA N

URANIUM BLDG. #1

D-10

NOTES

URANIUM (pCi/G U).

CIMARRON GAMMA SPEC SOIL COUNTER.

SITE SOIL BACKGROUND OF APPROX. 4.0 pCi/g U, NOT SUBTRACTED.

20 0 20

SCALE IN METERS

LEGEND

6 URANIUM 1 – 30 pCi/g U

58 URANIUM 31 – 100 pCi/g U

129 URANIUM 101 – 300 pCi/g U

327 URANIUM > 300 pCi/g U

R HIT ROCK– NO SAMPLE

| REV. | DESCRIPTION | DRWN BY: | CK'D BY: | APP'D BY: | DATE |
|---|---|---|---|---|---|
| 0 | DRAWING ISSUED. | JE | WR | JL | 11/2/98 |

CIMARRON CORPORATION

CIMARRON FACILITY
PHASE II – SUB-AREA H
POST-REMEDIATION DRAINAGE
SOIL SAMPLE RESULTS (1998)
SOIL SAMPLE ALIQUOT: SURFACE (0–6")

| DRWN. BY | DATE | CHKD. BY | DATE | SCALE: |
|---|---|---|---|---|
| JE | 7/16/98 | WR | 11/2/98 | AS SHOWN |

| JOB NO. | DRAWING NO. | REV. |
|---|---|---|
| | 98POAHDSSS–0 | 0 |

...\CIMARRON\SUBAREAH\DRAINAGE\SURFACE\98HDRNSS