SUB-AREA C

SUB-AREA D

SUB-AREA E

SUB-AREA G

SUB-AREA H

SUB-AREA I

SUB-AREA I

SUB-AREA I

SUB-AREA K

SUB-AREA L

SUB-AREA M

SUB-AREA N

SUB-AREA N

SUB-AREA O

SUB-AREA A

URANIUM WASTE POND #1 (BACKFILLED 1978)

BURIAL AREA #4 HOLDING POND

BURIAL AREA #2 (NORTH FIELD)

NORTH INCINERATOR/ BURIAL AREA #3

WEST SANITARY LAGOON (BACKFILLED 1993)

EAST SANITARY LAGOON (BACKFILLED 1993)

PLUTONIUM WASTE POND (BELOW) (BACKFILLED 1978)

NEW LINED SANITARY LAGOON (ABOVE)

PLUTONIUM BUILDING

WAREHOUSE BLDG. #4

URANIUM BLDG. #1

D-13

NOTES:

INSTRUMENT: LUDLUM 2221, S/N 97264, LEAD-UNSHIELDED 3" X 1/2" NaI DETECTOR.

BACKGROUND: 6244 CPM

INSTRUMENT: LUDLUM 2220, S/N 48395, LEAD-SHIELDED 3" X 1/2" NaI DETECTOR.

BACKGROUND: 3500 CPM

LEGEND

3560 < 12488 CPM

12620 > 12488 CPM

W WATER

NORTH

20 0 20

SCALE IN METERS

REV.	DESCRIPTION	DRWN BY:	CK'D BY:	APP'D BY:	DATE
0	DRAWING ISSUED.	JE	WR	JL	11/2/98

CIMARRON CORPORATION

CIMARRON FACILITY
PHASE II - SUB-AREA H
POST-REMEDIATION DRAINAGE
GAMMA SURVEY (1998)
READINGS IN CPM (3" DET.) AT SURFACE

DRWN. BY	DATE	CHKD. BY	DATE	SCALE:
JE	7/16/98	WR	11/2/98	AS SHOWN

JOB NO.	DRAWING NO.	REV.
	98POAHDS3D-0	0

...\CIMARRON\SUBAREAH\DRAINAGE\SURFACE\98HDRN3D