SUB-AREA D

SUB-AREA E

SUB-AREA H

SUB-AREA G

BERM

EAST DRAINAGE

MIDDLE DRAINAGE

URANIUM WASTE POND #1 (BACKFILLED 1978)

URANIUM WASTE POND #2 (BACKFILLED 1978)

D-15

LEGEND

- 6 — URANIUM, 1 – 30 pCi/g U
- 58 — URANIUM, 31 – 100 pCi/g U
- 129 — URANIUM, 101 – 300 pCi/g U
- 327 — URANIUM, > 300 pCi/g U
- R — HIT ROCK – NO SAMPLE

NOTES

URANIUM (pCi/g U).
CIMARRON GAMMA SPEC SOIL COUNTER.
SITE SOIL BACKGROUND OF APPROX. 4.0 pCi/g U, NOT SUBTRACTED.

SCALE IN METERS 15 0 15

REV.	DESCRIPTION	DRWN BY:	CK'D BY:	APP'D BY:	DATE
0	DRAWING ISSUED.	JE	WR	JL	11/2/98

CIMARRON CORPORATION

CIMARRON FACILITY
PHASE II – SUB-AREA H
POST-REMEDIATION – DRAINAGE/BOUNDARY
SOIL SAMPLE RESULTS (1998)
SOIL SAMPLE ALIQUOT: 0-6"

DRWN. BY	DATE	CHKD. BY	DATE	SCALE:
JE	8/20/98	WR	11/2/98	AS SHOWN

JOB NO.	DRAWING NO.	REV.
	98POAHDBSS-0	0

...\CIMARRON\SUBAREAH\BERM98\SBAREASS