SUB-AREA D

SUB-AREA E

SUB-AREA H

SUB-AREA G

BERM

EAST DRAINAGE

MIDDLE DRAINAGE

URANIUM WASTE POND #1 (BACKFILLED 1978)

URANIUM WASTE POND #2 (BACKFILLED 1978)

15 0 15

SCALE IN METERS

NOTES:

INSTRUMENT: LIUDLUM 2220, S/N 48395, LEAD-SHIELDED 3" X 1/2" NaI DETECTOR.
BACKGROUND: 3500 CPM
INSTRUMENT: LIUDLUM 2220, S/N 97264, LEAD-UNSHIELDED 3" X 1/2" NaI DETECTOR.
BACKGROUND: 6940 CPM

LEGEND

3560 ≤ 13880 CPM
16250 > 13880 CPM

REV.	DESCRIPTION	DRWN BY:	CK'D BY:	APP'D BY:	DATE
0	DRAWING ISSUED.	JE	WR	JL	11/2/98

CIMARRON CORPORATION

CIMARRON FACILITY
PHASE II - SUB-AREA H
POST-REMEDIATION - DRAINAGE/BOUNDARY
GAMMA SURVEY (1998)
READINGS IN CPM (3" DET.) AT SURFACE

DRWN. BY	DATE	CHKD. BY	DATE	SCALE:
JE	8/20/98	WR	11/2/98	AS SHOWN

JOB NO.

DRAWING NO: 98POAHDB3D-0

REV: 0

...\CIMARRON\SUBAREAH\BERM98\SBAREA3D

D-18