

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Livingston County Road Commission REPORT NUMBER(S) 2009001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-17920	4. LICENSE NUMBER(S) 21-20064-01	5. DATE(S) OF INSPECTION 03/ 5 /09	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 02.03 thru 02.11; 02.13 thru 02.14;02.16 thru 02.19; and 02.21		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Fred Marr	4. TELEPHONE NUMBER 517.546.4250
--------------------------------	----------------------	--------------------------------------	---

Main Office Inspection Next Inspection Date: 3/2014

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is the county road commission that employs 126 individuals. The licensee possesses two Troxler 3400 moisture density gauges, for use daily/weekly during the construction season (May-November) for soils engineering projects. Currently, the licensee employs five authorized gauge users who have completed manufacturers training. The gauges are stored in a locked room in the licensee's office in Howell, Michigan.

Performance Observations

At the time of this inspection, the gauges were not in use. The operator possessed required shipping papers which contained all appropriate information and demonstrated that the gauges were accessible in the transport vehicle. The authorized user demonstrated how the gauge/case were locked and chained to the rear of the vehicle during transport. The authorized user demonstrated an adequate level of understanding of emergency and handling procedures during the interview. Security during transport and at the job-site was described with no problems noted. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Livingston County Road Commission REPORT NUMBER(S) 2009001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-17920	4. LICENSE NUMBER(S) 21-20064-01	5. DATE(S) OF INSPECTION 03/ 5 /09	
6. INSPECTION PROCEDURES USED 87124		7. INSPECTION FOCUS AREAS 02.03 thru 02.11; 02.13 thru 02.14; 02.16 thru 02.19; and 02.21	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Fred Marr	4. TELEPHONE NUMBER 517.546.4250
----------------------------	------------------	----------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 3/2014

Field Office

Temporary Job Site Inspection

PROGRAM SCOPE

~~Portable Gauge Programs~~ 0/5

Program Scope

The licensee is the county road commission that employs 126 individuals. The licensee possesses two Troxler 3400 moisture density gauges, for use daily/weekly during the construction season (May-November) for soils engineering projects. Currently, the licensee employs five authorized gauge users who have completed manufacturers training. The gauges are stored in a locked room in the licensee's office in Howell, Michigan.

Performance Observations

At the time of this inspection, the gauges were not in use. The operator possessed required shipping papers which contained all appropriate information and demonstrated that the gauges were accessible in the transport vehicle. The authorized user demonstrated how the gauge/case were locked and chained to the rear of the vehicle during transport. The authorized user demonstrated an adequate level of understanding of emergency and handling procedures during the interview. Security during transport and at the job-site was described with no problems noted. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.