

HLWYM HEmails

From: James Winterle
Sent: Monday, October 04, 2004 5:38 PM
To: 'Tech_Group'
Subject: Photos from Alcove 7

FYI. To anyone who is interested. I received a CD-ROM with photos taken by Jack Parrot during the September 2004 entry into Alcove 7. These photos can be found on S:/jwinterle/Alcove 7 Photos. This entry followed an approximately one-year period without active ventilation. At the time the pictures were taken, the alcove was being ventilated to reduce radon levels, but ventilation was only turned on just prior to the entry. No active dripping was observed, but photos show some areas of damp drift walls, some condensation on electric lines, and the ubiquitous rust and mold caused by the damp conditions. Also, one or two good photos of the Ghost Dance Fault.

I will delete these photos on from the shared drive on Friday to free up disk space, but you can get the CD from me at any time.

Jim Winterle

Southwest Research Institute
CNWRA, Bldg. 189A
6220 Culebra Road
San Antonio, TX 78238

ph: 210.522.5249

Hearing Identifier: HLW_YuccaMountain_Hold_EX
Email Number: 1657

Mail Envelope Properties (005401c4aa5a\$6c57f9e0\$a5c8a281)

Subject: Photos from Alcove 7
Sent Date: 10/4/2004 5:38:01 PM
Received Date: 10/4/2004 5:35:58 PM
From: James Winterle

Created By: jwinterle@cnwra.swri.edu

Recipients:
"Tech_Group" <Tech_Group@cnwra.swri.edu>
Tracking Status: None

Post Office: cnwra.swri.edu

Files	Size	Date & Time
MESSAGE	946	10/4/2004 5:35:58 PM

Options
Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received: