

Figure 2-15. Failure stress vs. time-to-failure for second round testing of 185 Keno specimens. Forty one specimens have failed as of December 2003.




Figure 2-16. Specimen 45 (run 2): 316 NG as-received specimen; no signs of corrosion after 2462 hrs exposure at 70 ksi.




Figure 2-17. Specimen 100 (run 2): C-22 as-rec + HT1 (TCP) . No signs of corrosion after 2462 hrs at 93 ksi




Figure 2-18. Specimen 87 (run 2): C-22 as-received; no signs of corrosion after 2462 hrs at 100 ksi