B/46

Drilling on RTI property
behind irradiator building

29-20900-01 4/22/96

Looking ~~south~~ NW on unrestricted
area on RTI property.
Taking split samples 4/22/96.



Looking North at Lake Denmark
on RTI's property. 4/22/96.

Licensee contractor collecting soil
sample for analysis 4/22/96

RTI INC.

Split spoon displaying soil to be analyzed from NE corner of fenced area of property at RTI, Rockaway NJ.
4/22/96.

Drilling @ 40 yards from northeast corner of RTI fenced area. 4/22/96.



Drilling on NE area of RTI fenced property. 4/22/96.
(split samples being collected)