

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Ritz & Jens, Inc. REPORT NUMBER(S) 2009-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-31479	4. LICENSE NUMBER(S) 24-26114-01	5. DATE(S) OF INSPECTION Jan. 7, 2010	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Donald Eskridge	4. TELEPHONE NUMBER 314.993.4132
----------------------------	------------------	----------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: Jan. 2015

Field Office

Temporary Job Site Inspection

PROGRAM SCOPE

The licensee is a civil engineering firm located in St. Louis, Missouri. They perform soil density and asphalt testing in greater St. Louis Missouri area. The licensee has four Troxler model 3440 series gauges. The gauges are normally stored at the licensee's facility or at the project office for temporary job sites. For temporary job sites, the gauges are stored in the construction trailers. The licensee does not perform any service or maintenance activities on the gauges. The licensee employs three gauge users who have completed the manufacturer's training.

Performance Observations

There were no temporary job sites at the time of the inspection. Interviews of licensee personnel indicated an adequate level of knowledge of radiation safety.

Independent surveys of the gauge storage area indicated that there were two locks securing the storage area. Personnel were badged and had minimal exposures. The licensee secures the gauges in open bed pick up trucks using two locks and two chains. The gauge cases are also locked.

Handwritten signature/initials