

## UNITED STATES ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE REGION V 2111 BANCROFT WAY BERKELEY, CALIFORNIA 94704

TELEPHONE: 841-5121

July 14, 1969

J. P. O'Reilly, Chief Reactor Inspection and Enforcement Branch Division of Compliance, Headquarters

ELECTRIC STEEL CORPORATION (ESCO) VENDOR INSPECTION PRIMARY SYSTEM BUMPS
DOCKET NOS. 20-247 AND 50-286

The ESCO Corporation plant facilities located in Portland, Oregon, were visited by W. E. Vetter and Uldis Potapovs on June 10-11, 1969. The purpose of the visit was to review and evaluate ESCO's electroslag (E-S) welding programs. In order to take maximum advantage of the time allotted to the review and evaluation effort, two general areas of interest (i.e., QA-QC and metallurgical aspects of the E-S programs) were pursued independently. W. E. Vetter covered the QA-QC aspects of the programs (Section A of this report) and U. Potapovs covered items primarily concerned with metallurgy (Section B of this report).

The results of the review and evaluation indicate that, with relatively minor exceptions, ESCO is maintaining a successful, high quality E-S welding program.

Our inspectors were well received by ESCO and were afforded complete cooperation in making key personnel available for discussion as well as making all QA-QC records and other records and documents relative to the E-S welding programs available for review.

G. S. Spencer

Mencer

Senior Reactor Inspector

Attachment:

Vendor Inspection Report No. ESCO 69-2 by W. E. Vetter and U. Potapovs, dtd 7-14-69

## DISTRIBUTION:

J. P. O'Reilly, CO:HQ (3)

E. G. Case, DRS

R. S. Boyd, DRL (2)

S. Levine, DRL (6)

D. J. Skovholt, DRL (3)

L. Kornblith, Jr., CO HQ

Regional Directors, CO

REG FILES

8111030062 690714 PDR ADDCK 05000247