

Rafael Flores Senior Vice President & Chief Nuclear Officer rafael.flores@Luminant.com Luminant Power P O Box 1002 6322 North FM 56 Glen Rose, TX 76043

T 254 897 5550
C 817 559 0403
F 254 897 6652

Ref. # 10 CFR 50.55a

CP-201000061 Log # TXX-10005

January 28, 2010

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

SUBJECT:

COMANCHE PEAK STEAM ELECTRIC STATION (CPSES) DOCKET NO. 50-446 SUBMITTAL OF UNIT 2 ELEVENTH REFUELING OUTAGE (2RF11) INSERVICE INSPECTION (ISI) SUMMARY REPORT (UNIT 2: 1998 EDITION OF ASME CODE SECTION XI THROUGH 2000 ADDENDA, INTERVAL START DATE – AUGUST 3, 2004, SECOND INTERVAL)

Dear Sir or Madam:

In accordance with 10CFR50.55a, Luminant Generation Company LLC (Luminant Power) transmits the Inservice Inspection Summary Report for the eleventh refueling outage of Comanche Peak Unit 2. The enclosed report is being provided to you pursuant to the ASME Boiler and Pressure Vessel Code, Section XI, paragraph IWA-6240(b). A copy of this report is also forwarded to the Chief Inspector in accordance with the Texas Boiler Law & Rules and Regulations, paragraph 65.100.g.4.

This communication contains no new licensing basis commitments regarding Comanche Peak Unit 2.

Should you have any questions, please contact Mr. Jack Hicks at (254)897-6725.

Sincerely,

Luminant Generation Company LLC

Rafael Flores

Fred W. Madden

Director, Oversight & Regulatory Affairs

A member of the STARS (Strategic Teaming and Resource Sharing) Alliance

A047 NRR

Callaway + Comanche Peak + Diablo Canyon + Palo Verde + San Onofre + South Texas Project + Wolf Creek

U. S. Nuclear Regulatory Commission TXX-10005 Page 2 01/28/2010

Enclosure

c - E. E. Collins, Region IV B. K. Singal, NRR Resident Inspectors, Comanche Peak A. Jones, TDLR Brian Welch ANII, Comanche Peak

FORM OAR-1 OWNER'S ACTIVITY REPORT

•

÷

Report Number	CPNPP U2 2RF11					
Owner	Luminant Power P.O. Box 1002 Glen Rose, Texas 76043					
	(Name and Address of Owner)					
Plant	Comanche Peak Nuclear Power Plant P.O. Box 1002 Glen Rose, Texas 76043					
ć	(Name and Address of Plant)					
Unit No. <u>2</u> (If applicable)	Commercial service date <u>August 3, 1993</u> Refueling outage no. <u>11</u>					
Current inspection interval	2					
•	$(1^{st}, 2^{nd}, 3^{rd}, 4^{tn}, other)$					
Current inspection period	2					
	(1 st , 2 nd , 3 rd)					
Edition and Addenda of Secti	on XI applicable to the inspection plan 1998 Edition, 2000 Addenda `					
Date and revision of inspection	on plan CPNPP ISI Program Plan, Interval 2, Rev. 3, February 28, 2008					
Edition and Addenda of Secti	on XI applicable to repairs and replacements, if different than the inspection plan <u>. Same</u>					
·.	CERTIFICATE OF CONFORMANCE					
I certify that the statements made in this Owner's Activity Report are correct, and that the examinations, tests, repairs, replacements, evaluations, and corrective measures represented by this report conform to the requirements of Section XI.						
Certificate of Authorization I	No. N/A Expiration Date N/A					
	(If applicable)					
Signed her	10h PROCUREMENT ENG & PROGRAMS MUN Date 1/18/10					
11=-11	Owner or Owner's Designee, Title					
	CERTIFICATE OF INSERVICE INSPECTION					
I, the undersigned, holding	a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province					
of <u>Texas</u> and employed by	Hartford Steam Boiler I and I Company of Connecticut of Hartford, CT. have inspected the items described in					
this Owner's Activity Report,	during the period July 1, 2008 to December 31, 2009 , and state that to the best of my					
knowledge and belief, the O	wner has performed all activities represented by this report in accordance with the requirements or Section XI.					
By signing this certificate n	either the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations, tests,					
repairs, replacement, evalua	tions and corrective measures described in this report. Furthermore, neither the inspector nor his employer shall be					
liable in any manner for any	personal injury or property damage or a loss of any kind arising from or connected with this inspection.					
R H	Commissions TX 1717					
Inspector's Signatur						
Date 19 Jk						
<u> </u>	ay be obtained from the Order Dept., ASME, 22 Law Drive, Box 2300, Fairfield, NJ 07007-2300					

OAR-1 Page 1 of **5**

TABLE 1 ABSTRACT OF EXAMINATIONS AND TESTS

. . .

Examination Category	Total Examinations Required For The Interval	Total Examinations Credited for This Period*	Total Examinations Credited (%) for The Period**	Total Examinations Credited (%) to Date for the Interval	Remarks
B-A	24	0 ·	0	4	NOTE 3
B-B	8	1	25	38	
B-D	36	4	67	39	
B-G-1	165	29	100	0	NOTES 4, 8
B-G-2	19	3 .	50	37	NOTE 4
В-К	8	3	75	63	
B-L-1	1	0	0	0	NOTES 1, 3
B-L-2	1	0	0	0	NOTES 1, 4
В-М-2	4	0	· 0	25	NOTES 1, 4
B-N-1	3	2	· 100	100	NOTE 2
B-N-2	1	1	. 100	100	NOTE 3
B-N-3	1	1	100	100	NOTE 3
B-0 ·	4	0	0	0	NOTE 3
B-P	NOTE 5	NOTE 5	NOTE 5	NOTE 5	NOTES 2, 5
B-Q	NOTE 7	NOTE 7	NOTE 7	NOTE 7	NOTE 7
C-A	19	8	80	63	
C-B	8	2	100	50	
c-c	95	29	74 [·]	57	
C-D	· 1	0	0	100	
C-G	6	1	50	50	
C-H	NOTE 5	NOTE 5	NOTE 5	NOTE 5	NOTE 5
D-A	140	34	67	54	
D-B	NOTE 5	NOTE 5	NOTE 5	NOTE 5	NOTE 5
F-A F1.10	85	21	78	46	
F-A F1.20	252	62	. 60	49	· · · · · · · · · · · · · · · · · · ·
F-A F1.30	168	44	67	58 ·	
F-A F1.40	102	23	52	54 🔅	
R∙A	144	56	98	66	NOTE 6

* This column is interpreted to represent the cumulative number of exams performed to date in this period. ** This column is interpreted to represent the cumulative percentage of scheduled exams for the interval which have been completed to date in this period.

NOTES:

1.

7.

8.

Examinations for pumps and valves are limited to components selected for examination under Examination Categories B-L-1, B-L-2, and B-M-2.

2. Examination Categories B-N-1 and B-P do not have to follow the required percentages of Table IWB-2412-1.

3. Examinations for Examination Categories B-A, B-L-1, B-N-2, B-N-3, and B-O may be deferred to the end of the inspection interval.

4. Examinations for Examination Categories B-G-1, B-G-2, B-L-2, and B-M-2 may be deferred until disassembly of a component for maintenance, repair/replacement, or volumetric examination.

5. Visual Examinations (VT-2) for system leakage tests are performed each fuel cycle, period, and interval, according to the requirements of IWA-2212 and IWA-5240. All required VT-2 examinations have been completed for this fuel cycle, except for portions of AF system in Work Order 3666622, scheduled for examination during the week of 1/04/10.

6. Examination Category R-A includes previous Examination Categories B-F, B-J, C-F-1, and C-F-2.

Examination Category B-Q, Steam Generator Tubing, is reported per the requirements of the Plant Technical Specifications.

Reactor vessel nuts and washers, Examination Category B-G-1, were replaced by hydranut assemblies during 2RF11(second outage of the second peroid), with 25% of the hydranut assemblies requiring examination in the third period. PSI of the hydranut assmblies were completed during 2RF11.

OAR-1 Page 3 of 5

TABLE 2 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE

Examination Category	ltem Number	Item Description	Flaw Characterization (IWA-3300)	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes or No)		
None for 2RF11		·				
	,		n .			
				· . ·		
		· · · · ·		· · · · · · · · · · · · · · · · · · ·		
•		·				
•	, .	n		· · · · · · · · · · · · · · · · · · ·		
		· · · ·		,		
				<u> </u>		
		· · ·		· · · · · · · · · · · · · · · · · · ·		
· .				,		
		·				

TABLE 3 ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES REQUIRED FOR CONTINUED SERVICE

Code Class	Repair, Replacement or Corrective Measure	ltem Description	Description of Work	Flaw or Relevant Condition Found During Scheduled Section XI Examination or Test (Yes/No)	Date Complete	Repair/ Replacement Plan Number
1	Replacement	Snubber Load Pin	Replaced missing load pin	No .	10/27/09	25109-001
	•					
		2 -				
•						
· · ·					L .	;
	· •					
	· ·					

OAR-1 Page 5 of 5