

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, New York 10511-1099

Docket No. 50-286 IPN-97-033 Attachment I Page 3 of 5

NYSDEC - Division of Water SPDES Compliance Information Section Bureau of Water Compliance Programs 50 Wolf Road - Room 320 Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report

Permit #0004472

Con Edison Indian Point Units 1 & 2

New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of May 1996. A Report of Noncompliance Event is attached for a non-compliance which occurred at the New York Power Authority Unit 3 Facility.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds Burns of Con Edison at (914)734-5605 or Mr. Mathew Kerns of New York Power Authority at (914)736-8452.

Very truly yours,

John McAvoy Plant Manager

Indian Point Station

Con Edison Units 1 & 2

Attachment

/kj

SECTION 1

Docket No. 50-286 IPN-97-033 Attachment I Page 4 of 5

e Department of Environmental Colembiation Division of Water New York



Report of Noncompliance Event

To: DEC Water Contact CESARE MANFREDI RWE	DEC Region: 3
Report Type: 5 Day _X' Permit Violation Order Violation Anticip	ated Noncompliance Bypass/Overflow
SECTION 2	
SPDES #: NY- 0004472 Facility: INDIAN POINT N.G.S.	
Date of noncompliance: 05 / 16 / 96 Location (Outfall, Treatment Unit, or Pr	ump Station): OUTFALL 001
Description of noncompliance(s) and cause(s): SEE ATTACHED	
Has event ceased? (7cs) (No) If so, when: 05/16/96 Was event due to plant upset	? (Yes) (NO) SPDES limits violated? (Yes); (No)
Start date, time of event: 05 / 16 / 96, 3:00 (AM) (PM) End date, time of events	
Date, time oral notification made to DEC? 05 /16 /96 4:43 (AM) (PM) DEC (
Immediate corrective actions: IMMEDIATELY SECURED TRANSFER OF SE COLLECTED AND PUMPED TO TRANSPORT VEHICLE FOR OFFST	WAGE, THE SITE SEWAGE WAS
Preventive (long term) corrective actions: THE CLEAN OUT PLUG GASKET WMAIN PLACED BACK IN SERVICE ON 5/1/	AS REPAIRED AND THE FORCED
SECTION 3	
en en la la composition de la composition della composition della	
Complete this section if event was a bypass:	
Bypass amount: Was prior DEC authorization rece	
DEC Official contacted: Date of DE	
Describe event in "Description of noncompliance and cause" area in Section 2. Detail th	ie start and end dates and times in Section 2 also-
SECTION 4	
Facility Representative: KEN PETERS Title: LICENSING	MANAGER Date: 06/17 / 96
Phone H. (914) 736 - 8029 Fax H. (914	736 8769

Docket No. 50-286 IPN-97-033 Attachment I Page 5 of 5

DESCRIPTION ON NONCOMPLIANCE(s) AND CAUSE(s) THIS NON-COMPLIANCE WAS DUE TO A FAILURE OF A GASKET SEAL ON A CLEAN OUT PLUG ON THE FORCED SEWAGE LINE FROM THE INDIAN POINT SITE TO THE SEWAGE MAIN TO THE BUCHANAN SEWAGE TREATMENT PLANT, WHICH RESULTED IN THE RELEASE OF RAW SEWAGE TO THE SITE GROUNDS. A PORTION OF WHICH ENTERED A SITE STORM WATER DRAIN WHICH GOES TO THE SITE DISCHARGE CANAL. REFERENCE SPILL NUMBER 96-02204.