Pramod Raval, M.D., P.C. 24661 Coolidge Oak Park, MI 48237

March 28, 2010

U.S. Nuclear Regulatory Commission Materials Licensing Section Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532

Dear Sir:

Please amend Byproduct material license no. 21-32401-01 for the close out of their second location and remove it from the license.

Enclosed is a copy of the close out survey for the 3120 Carpenter, Suite 313, Hamtramck, MI location.

If there are any questions please call me at (734) 455-4730 office / (734) 395-7361 cell.

Sincerely,

Ray A. Carlson, M.S. Radiation Safety Officer

## Radiological Physics Service, Inc. 3839 Napier Road - Plymouth, MI 48170

(734) 455-4730

## **CLOSE OUT SURVEY**

Pramod Raval, M.D., P.C. 24661 Coolidge Oak Park, MI 48237

License: 21-32401-01

RE: Close out survey of location

- 1. Date of Survey: March 26, 2010
- 2. Diagram of the department and the wipe test results are attached.
- 3. The survey meter readings were less than 0.02 mR/hr for all areas.
- 4. The survey meter background reading was 0.02 mR/hr.
- 5. The survey meter used was a Ludlum model 14C (S/N 160951) with an end window GM probe. It was last calibrated March 21, 2010.
- 6. The wipe tests were assayed on an Picker single-channel well counter. The minimum detectable activity for Tc-99m, Tl-201 is 61 dpm at 95% confidence.
- 7. The survey was performed by Ray A. Carlson, M.S., Medical Physicist from Radiological Physics Service, Inc. (License No.: 21-26253-01).
- 8. All sealed sources were transferred to the Oak Park, MI office..
- 9. All waste was decayed to background and disposed of properly. No patient procedures had been performed for several months.

The location is certified to be free of radioactive material and contamination and may be released for unrestricted use with the approval of the State.

All wipe tests were below the 2000 dpm limit and all GM survey meter readings were at background (0.02mR/hr).

Ray A. Carlson, M.S.

DABR, DABMP

Medical Physicist/RSO

## Radiological Physics Service, Inc. 3839 Napier Road - Plymouth, MI 48170

(734) 455-4730

## Wipe Test Results

Pramod Raval, M.D., P.C. 24661 Coolidge Oak Park, MI 48237

License: 21-32401-01

RE: Close out survey of location


Date: March 26, 2010

Area	СРМ	Nes CDM	DDM
Area	CPNI	Net CPM	DPM
Background	215		
1	205	0	0
2	205	0	0
3	205	0	0
4	205	0	0
5	205	0	0
6	205	0	0
8	205	0	0

- All wipes were below the 2000 DPM limit.
- All wipe areas were surveyed with a GM survey meter and all areas recorded less than 0.02 mR/hr. Wipes were then analyzed in well counter.

Ray A. Carlson, M.S. DABR, DABMP

Medical Physicist/RSO



OUT SIDE ( 3 RD FLOOR )

Exam Room	TREADMILL ROOM  (b)	2	OLD (AMERA ROUM		EXAM	
	(5)	0		3		
Hallway						

THE ROOMS ARE TOTALLY EMPTY, THERE ARE
NO COUNTER TOPS.

FAX

E

To: NRC MATERIALS
Fax #: 630-515-1078
Subject: AMENDMENT

LLCRNSING

Subject:

Date:

3/28/10

Pages: 5, including this cover sheet.

**COMMENTS:** 

Ray A. Carlson, M.S. Cell: (734) 395-7361

\*

Dan L. Marx, M.S. Cell: (803) 549-2187

Laura Smith, M.S. Cell: (586) 215-5947

Vince McCormick, M.S. Cell: (734) 395-9323

Radiological Physics Service, Inc. 3839 Napler Road Plymouth, Mi 48170

> (734) 455-4730 FAX: (734) 453-8851