

**APPENDIX E**

**Geotechnical Investigation Summary Report**

## TABLE OF CONTENTS

	Page
1.0 INTRODUCTION.....	1
2.0 GEOLOGIC SETTING .....	1
3.0 SITE GEOTECHNICAL INVESTIGATIONS.....	1
4.0 SUBSURFACE CONDITIONS .....	2
4.1 SOIL CONDITIONS.....	2
4.2 BEDROCK CONDITIONS .....	3
4.3 GROUNDWATER .....	3
5.0 PRELIMINARY FOUNDATION RECOMMENDATIONS.....	3
5.1 FOUNDATIONS ON ROCK.....	3
5.2 FOUNDATIONS ON SOIL.....	3
5.3 CORROSION PROTECTION.....	4
5.4 SEISMIC SITE CLASS .....	4
5.5 LIQUEFACTION .....	4
6.0 RECOMMENDATIONS FOR ADDITIONAL WORK.....	4
7.0 BORING LOGS .....	13
7.1 NOVEMBER 2007 – SOIL.....	13
7.2 MAY 2008 – SOIL .....	33
7.3 APRIL – MAY 2008 – ROCK CORING.....	43
8.0 LABORATORY RESULTS .....	110
8.1 NOVEMBER 2007 RESULTS .....	110
8.2 MAY 2008 RESULTS .....	118

## **LIST OF TABLES**

Table E.1 Summary of Laboratory Soil Index Testing

Table E.2 Summary of Chemical Testing

## **LIST OF FIGURES**

Figure E.1 Boring Location Plan

## **1.0 INTRODUCTION**

This report presents the geotechnical site exploration results and preliminary foundation recommendations for the proposed 240 ha (600-acre) Eagle Rock Enrichment Facility site (EREF) located in Bonneville County, Idaho. MWH (Montgomery Watson Harza) under contract to AREVA performed various subsurface investigations between November 2007 and May 2008 as part of a larger environmental study for the proposed facility. The portions of that study that provide applicable geotechnical information are summarized and provide the basis for the recommendations included herein.

The proposed site is approximately 27 km (17 miles) west of Idaho Falls, Idaho, and occupies the SW $\frac{1}{4}$  of section 13, the SE $\frac{1}{4}$  of section 14, the NE $\frac{1}{4}$  of section 23, and the NW $\frac{1}{4}$  of section 24, Township 3 N, Range 34 E. The site ranges in elevation from 1,556 to 1,600 m (5,106 to 5,250 feet).

## **2.0 GEOLOGIC SETTING**

The site is located in the eastern Snake River Plain, part of an extensive topographic depression in southern Idaho that covers about 40,400 km $^2$  (~ 15,600 mi $^2$ ). Quaternary basalt flows cover approximately 95% of the surface of the plain. Interbeds of sand, silt, and clay, with smaller amounts of volcanic ash occur between the flows.

## **3.0 SITE GEOTECHNICAL INVESTIGATIONS**

MWH conducted several investigations at the site in the last quarter of 2007 and second quarter of 2008 including two soil boring programs with laboratory testing, a well drilling program that included rock coring, and a geologic mapping which provided information applicable to foundation design.

The first investigation consisted of 20 borings drilled to bedrock November 27, 2007. These borings are located in a rectangular area immediately to the west of the portion of the site currently proposed for the EREF structures (see Figure E.1). These borings are designated BH1 to BH20 and range in depth from 0.76 to 4.27 m (2.5 to 14 feet) below ground surface. Andrew Well Drilling drilled these borings using a 108mm (4.25-inch) inside diameter (ID), 209mm (8.25-inch) outside diameter (OD) continuous-flight hollow stem auger with a truck-mounted CME-85 drill rig. Standard Penetration Test (SPT) samples were collected using a 38.1mm (1.5-inch) ID, 50.8mm (2-inch) OD split spoon sampler driven 457mm (18 inches) with a 63.5 kg (140-pound) safety hammer free-falling 762mm (30 inches) in accordance with ASTM D1566-99. In addition, a Dames & Moore 61.7mm (2.43-inch) ID, 63.5mm (2.5-inch) OD sampler was driven 304.8mm (12 inches) using a 63.5 kg (140-pound) safety hammer free falling 762mm (30 inches). Samples were collected approximately every 1.52m (5 feet) for the full length of each boring. A qualified field engineer recorded the number of hammer blows required to drive both the split spoon sampler and the Dames & Moore sampler each 152mm (6-inch) increment over the sampling intervals. The material encountered in each boring was logged and classified in accordance with the Unified Soil Classification System. Dames & Moore tube samples were preserved and transported per ASTM-D4220-95. Material collected as part of the SPT sampling was stored in airtight bags. The boring locations are shown on Figure E.1 and the boring logs are presented in Section 7.0.

As part of the November 2007 subsurface exploration, 8 soil samples were tested at Terracon Laboratories of Fort Collins, CO. Analyses included testing for natural moisture content (ASTM D2216-98), grain size analysis (ASTM D422-63R02), and Atterberg limits (ASTM D4318-00).

Terracon also performed three natural dry density tests (ASTM D2216-98) and one swell consolidation test (ASTM D2435-02) on these samples. The laboratory results are included in Section 8.0, and the results of the index testing are shown on Table E.1

Between April 21 and May 8, 2008, Crux Subsurface Inc, continuously cored the bedrock using an HQ core barrel and 1.52 m (5 foot) runs to a total depth of 222.65 m (730.5 feet) as part of the construction of a groundwater monitoring well. This well is identified as GW-1 and is one of a series of wells constructed as part of a hydro geological investigation. It was the only well cored at that time. The groundwater well locations, including GW-1, are shown on Figure E.1. The GW-1 core log is included in Section 7.0.

Subsequent to the November 2007 drilling, the proposed facility location was moved approximately 1,220m (4,000 feet) to the east. Between May 12 and May 13, 2008, an additional 10 borings were drilled to better define subsurface conditions at the adjusted facility location. These borings are designated as BH21 to BH30 and ranged in depth from 0.15 to 6.2 m (0.5 to 20.5 feet). Andrew Well Drilling Service drilled and sampled to bedrock using the same-sized hollow stem augers, sampling equipment and intervals as in the previous investigation. The borings are shown on Figure E.1 and the boring logs are included in Section 7.0.

As part of the May 2008 subsurface investigation, 11 soil samples were selected for laboratory analysis at Terracon Laboratories (Fort Collins, CO). Analyses performed included 9 natural moisture content tests (ASTM D2216-98), 4 Atterberg limit tests (ASTM D4318-00), 2 specific gravity tests (ASTM D854-06), 2 swell consolidation tests (ASTM D2435-02), 2 proctor compaction tests (ASTM D1557-02), and 2 Resistance R-Value tests (ASTM D2844-01). In addition, Terracon also performed 2 pH tests [AASHTO T289-91-UL (2004)], 2 resistivity tests [AASHTO T288-91-UL (2004)], and 2 tests for water soluble sulfate [AASHTO T290-95-UL (2003)]. The laboratory results are included in Section 8.0, and the results of the index testing are shown on Table E.1. The results of the chemical testing are shown on Table E.2.

In addition to the subsurface investigations, soil and bedrock mapping was also performed between May 14 and May 16. This mapping provided some additional information regarding the site bedrock structure, overburden, and site drainage patterns.

## 4.0 SUBSURFACE CONDITIONS

### 4.1 SOIL CONDITIONS

Soils at the site are reported to be of eolian origin and directly overlie basalt lava flows. Soil generally ranges in thickness from 0 to 4.3m (0 to 14 feet), although soil was found approximately 6.2 m (20.5 ft) thick at BH30. Basalt outcrops are intermittently exposed and in total comprise about 14% of the site ground surface area.

Field identification and laboratory testing indicate that the soil is primarily lean clay and lean clay with sand (CL) with colors such as light tan, tan, light brown, and dark brown. The natural moisture content ranges from 9.6 to 19% and the Plasticity Index (PI) ranges from 10 to 24.

The Standard Penetration Test (SPT) field N-values ranged from 1 to 43 suggesting a low plasticity clay that ranges from very soft to hard. The median value (18 blows per ft) suggests a medium stiff clay. Because rock fragments were noted in samples associated with high blow counts, it is possible that these high values are biased and do not reflect soil strength. The natural dry density ranged from 1.30 to 1.79 g/cm<sup>3</sup> (81.2 to 112 lbs/ft<sup>3</sup>).

The compression index, Cc, from consolidation tests ranged from 0.114 to 0.26, which is similar to wind-blown deposits (Winkerton and Fang 1975, Table 2.40). Some of these tests suggest that a potential for collapse exists.

## **4.2 BEDROCK CONDITIONS**

Geologic mapping of the bedrock exposures indicates that the basalt is strongly vesicular and includes discontinuities such as strongly developed columnar jointing and numerous cavities. Several collapsed lava tubes filled with rubble were reported in the site area.

Rock Quality Designations (RQD) for one deep cored boring indicate that the bedrock ranges from fair to excellent quality (64% to 100%) within the top 30 m (100 ft) of the boring. Several localized zones of broken rock and soil were observed at considerably greater depths. A fractured interval between 69 m (225 ft) and 70 m (230 ft) yielded an RQD of 0 and a 2.5 m (8 ft) layer of soil was encountered between 123 m (403 ft) and 125 m (410 ft). Thinner layers of soil were encountered between 18.6 m (61 ft) and 19.5 m (64 ft) and 59.1m (194 ft) and 60.8 m (199.5 ft). The depths of these zones greatly exceed the anticipated depth of influence of foundations and will not negatively impact the capacity of the rock to provide adequate bearing.

## **4.3 GROUNDWATER**

Groundwater was not encountered during the subsurface investigations that were limited to the surface soils. Groundwater was encountered in the observation wells at depths greater than 150 m (500 ft).

# **5.0 PRELIMINARY FOUNDATION RECOMMENDATIONS**

## **5.1 FOUNDATIONS ON ROCK**

It is expected that most of the heavy structures at the site will be founded directly on the bedrock. Basalt of this nature typically provides adequate support for footings, mats, and deep foundations with the loads similar to those anticipated for the EREF structures. NAVFAC (1986a) presents presumptive allowable bearing pressures for spread footings that range from 960 to 7,660 kPa (10 to 80 tsf) for rock with consistency varying from soft to hard. Peck, Hanson and Thornburn (1974) present allowable contact pressures on jointed rock as a function of RQD. An allowable contact pressure of 960 kPa (10 tsf) is recommended for an RQD of zero. Peck, Hanson and Thornburn (1974) also note that the allowable contact pressure beneath foundations is governed exclusively by the settlement associated with the defects in the rock, and not by strength. Therefore, the allowable loading on the rock will be governed by the allowable settlement and is expected to be far less than the allowable loading when only bearing capacity (strength) is considered. Settlement evaluation will consider the allowable total and differential settlement of equipment and buildings.

## **5.2 FOUNDATIONS ON SOIL**

Other support alternatives for heavy structures to be considered at the final design stage will be removal of unsuitable surface soils and backfilling with structural or engineered fill. Modified Proctor tests performed on site soils resulted in maximum dry densities of 1.78 and 1.80 g/cm<sup>3</sup> (111 and 112.5 lbs/ft<sup>3</sup>) at optimum moisture contents of 14 and 14.5%. Because the site soil is generally classified as low plasticity clay it is unlikely to be suitable for use as structural fill. The structural fill requirements will be detailed at the final design stage but suitable materials will include crushed rock, well graded gravel and sand mixtures.

Lightly loaded, non-settlement sensitive structures, may potentially be founded directly on the site soil. If this option is considered further, the bearing capacity of the in situ soil including the potential for collapse will be evaluated.

Two resistance R-value tests were performed on samples taken from depths of 0.3 m (1 foot) and 1.5 m (5 feet). The R-values for these samples were 17 and 16 respectively at 2,069 kPa (300 psi) exudation pressure. These values are at the upper limit of the typical range (5-15) of R-values for clays and suggest a CBR value between 7 and 10 (Yoder 1975, Figure 15.5).

Pavement design will be performed in conjunction with an analysis of the expected loads on the roads.

### **5.3        CORROSION PROTECTION**

The Federal Highway Administration uses the following criteria to indicate a potentially corrosive environment: soil resistivity values less than 2000 ohm-cm, soil pH less than 5, sulfate above 200 ppm and chloride above 100 ppm (FHWA 2000). Tests on two samples yielded resistivity values of 1229 Ohm-cm and 245 Ohm-cm and water soluble sulfate values of 100 and 1700 ppm. The low resistivity values and high sulfate concentrations suggest an environment with corrosion potential and may warrant further investigation. The pH of the soil was 8.36.

### **5.4        SEISMIC SITE CLASS**

The 2006 edition of the International Building Code defines site classes based on the material present in the upper 30.5m (100 feet) of the soil profile and the overall soil stiffness as indicated by shear wave velocity, SPT blow counts, or average undrained shear strength. Based on geologic maps and local soil investigations, it is estimated that the Site Class D applies for structures founded on the native soils and that Site Class C applies for structures founded on rock (MWH 2008b). Further testing is required to determine if the site meets the requirements of Site Class B or A.

### **5.5        LIQUEFACTION**

It is expected that the final design subsurface information will confirm that there is no need to perform a liquefaction analysis. Liquefaction potential is greatest where the groundwater level is shallow and saturated loose fine sands occur within a depth of about 15 m (50 ft). Groundwater was encountered in the observation wells at depths of more than 150 m (500 ft). The surface soils at the site are dry and partially saturated. Therefore, potential for liquefaction of the surface soils with groundwater at these depths appears highly unlikely. If required, the assessment of soil liquefaction potential will be performed using the applicable guidance of Regulatory Guide 1.198, Procedures and Criteria for Assessing Seismic Soil Liquefaction at Nuclear power Plant Sites, dated November 2003 (NRC, 2003).

## **6.0        RECOMMENDATIONS FOR ADDITIONAL WORK**

Additional soil borings and rock coring will be performed at the site to support final design. Laboratory testing of soil and rock samples and additional in-situ tests will be performed as necessary to determine static and dynamic soil and rock properties. This information will be used to evaluate foundation bearing capacity, estimated settlement and provide geotechnical input for soil/rock structure interaction analysis. It is expected that the final design subsurface information will confirm that there is no need to perform a liquefaction analysis.

## REFERENCES

- ASCE (1996).** Rock Foundations, Technical Engineering and Design Guides as Adapted from the U.S. Army Corps of Engineers, NO. 16, American Society of Civil Engineers, New York, NY.
- AASHTO (2003).** Standard Method of Test for Determining Water-Soluble Sulfate Ion in Soil. Designation T 290-95 (2003).
- AASHTO (2004a).** Standard Method of Test for Determining Minimum Laboratory Soil Resistivity. Designation T 288-91 (2004).
- AASHTO (2004b).** Standard Method of Test for Determining pH of Soil for Use in Corrosion Testing. Designation T 289-91 (2004).
- ASTM (1995).** Standard Practices for Preserving and Transporting Soil Samples D 4220-95. Approved April 15, 1995, published January 1995.
- ASTM (1999a).** Standard Test Method for Laboratory Determination of Water (Moisture) Content of Soil and Rock by Mass. Designation D 2216-98. Approved February 10, 1998, published January 1999.
- ASTM (1999b).** Standard Test Method for Penetration Test and Split-Barrel Sampling of Soils D 1586-99. Approved January 10, 1999, published March 1999.
- ASTM (2000a).** Standard Practice for Classification of Soils for Engineering Purposes (Unified Soil Classification System). Designation D 2487-00. Approved March 10, 2000, published May 2000.
- ASTM (2000b).** Standard Test Method for Liquid Limit, Plastic Limit, and Plasticity Index of Soils. Designation D 4318-00. Approved June 10, 2000, published September, 2000.
- ASTM (2002).** Standard Test Method for Resistance R-Value and Expansion Pressure of Compacted Soils. Designation D 2844-01. Approved November 10, 2001, published February 2000.
- ASTM (2003a).** Standard Test Method for Laboratory Compaction Characteristics of Soil Using Modified Effort (56,000 ft-lbf/ft<sup>3</sup> (2,700 kN-m/m<sup>3</sup>)). Designation D1557-02. Approved November 10, 2002, published January 2003.
- ASTM (2003b).** Standard Test Method for Particle-size Analysis of Soils. Designation D 422-63. Approved November 10, 2002, published March 2003.
- ASTM (2003c).** Standard Test Method for One-Dimensional Consolidation Properties of Soils. Designation D 2435-02. Approved November 10, 2002, published January 2003.
- ASTM, 2006.** Standard Test Method for Specific Gravity of Soil Solids by Water Pycnometer. Designation D 854-06. Approved January 15, 2006, published February 2006.
- FHWA (2000).** *Micropile Design and Construction Guidelines- Implementation Manual.* Publication No. FHWA-SA-97-070. US Department of Transportation, Federal Highway Administration, Washington DC
- International Code Council (2006).** *International Building Code 2006.* Chapter 16. International Code Council Inc. Country Club Hill, IL
- MWH (2008a).** Rock Boring Log GW-1, April 21 to May 8, 2008. Fort Collins, CO.
- MWH (2008b).** Preliminary Geotechnical Report for the Proposed Eagle Rock Enrichment Facility. 19 June 2008, Revision 04 - November 26, 2008. Fort Collins, CO.

**MWH (2008c).** Proposed U.S. Enrichment Facility, Bonneville County, Idaho. Geotechnical Investigation Report. Fort Collins, CO. June 24, 2008, Revision 4 - November 26, 2008.

**MWH (2008d).** Surface Geology Mapping Summary and Field Notes. Fort Collins, CO.

**NAVFAC (1986a).** Department of the Navy, Naval Facilities Engineering Command, Foundations and Earth Structures, Design Manual 7.2, NAVFAC DM 7.2, September 1986.

**NAVFAC (1986b).** Department of the Navy, Naval Facilities Engineering Command, Soil Mechanics, Design Manual 7.1, NAVFAC DM 7.1, September 1986.

**Peck, Ralph B., Hanson, Walter E., and Thornburn, Thomas H., (1974).** Foundation Engineering, John Wiley & Sons, New York, NY.

**Winterkorn, H. F., and Fang, H. Y., (1975).** Foundation Engineering Handbook, Van Nostrand Reinhold Company, New York, NY

**Yoder, E. J., and Witczak, M.W., (1975).** Principles of Pavement Design, 2nd Edition, John Wiley & Sons Inc, New York, NY

## **TABLES**

**Table E.1 - Summary of Soil Index Property Testing**  
**(Page 1 of 1)**

Boring	Depth (m [(ft)])	Specific Gravity	Natural Moisture Content (%)	Natural Dry Density (g/cm³ [pcf])	Gradation					Atterberg Limits		Soil Type
					Gravel (%)	Sand (%)	Fines (%)	Silt (%)	Clay (%)	LL (%)	PI (%)	
BH1	3.0 [10]		15.5	1.67 [104.4]	2.1	14.3	84			35	16	CL
BH5	1.5 [5]		13.6		0.2	6	93.8	72.7	21.1	29	13	CL
BH6	1.5 [5]		9.6		4		96			31	13	CL
BH7	1.5 [5]		14.1	1.79 [112]	9		91			36	17	CL
BH10	1.5 [5]		10.9		0.1	10.9	89			29	11	CL
BH12	3.2 [10.5]		12.0	1.41 [88]	0	2	98			35	15	CL
BH14	1.5 [5]		11.8		0	6	94			27	10	CL
BH18	1.6 [5.5]		15.1		0.4	8.6	91	58.5	32.5	31	14	CL
BH22	1.5 [5]		16.3									CL
BH23	0.3 [1]						89			36	12	CL
BH23	1.5 [5]	2.69					87			33	14	CL
BH25	1.6 [5.5]	2.7	14.9				86			42	24	CL
BH28	1.5 [5]		10.6									CL
BH29	1.6 [5.5]		13.0	1.30 [81.2]								CL
BH29	3.0 [10]		16.0									CL
BH30	1.6 [5.5]		10.7	1.45 [90.4]			97			35	16	CL
BH30	3.2 [10.5]		12.7									CL
BH30	4.7 [15.5]		14.7									CL
BH30	6.2 [20.5]		19.0									CL

Specific Gravity ASTM D854-06

Natural Moisture Content ASTM D2216-98

Natural Dry Density ASTM D2216-98

Grain Size Analysis ASTM D422-63R02

Atterberg Limits ASTM D4318-00

**Table E.2 - Summary of Soil Chemical Testing**  
**(Page 1 of 1)**

Boring	Depth (ft)	Water Soluble Sulfate (ppm)	Resistivity (Ohm-cm)	pH
BH23	5	100	1,229	8.36
BH25	5.5	1,700	245	8.36

Water Soluble Sulfate

AASHTO T290-95-UL (2003)


Resistivity

AASHTO T288-91-UL (2004)

pH

AASHTO T289-91-UL (2004)

# **FIGURES**



## 7.0 BORING LOGS

### 7.1 NOVEMBER 2007 – SOIL

BH1 through BH20

SOIL BORING LOG						Boring:	<b>BH1</b>
						Sheet No.:	1 of 1
						Job No.:	
Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:	
Total Depth (ft):	11.5 ft	Depth to Water (ft):		Northing:	697370.594	Vertical Angle:	
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	584549.293	Ground Elev.:	5163.35
Notes: USCS Classification for sample taken at 10-11 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.							
Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan to lt. brown clay, dry	CL			Observations from cuttings
			5'	CL			
			Tan to lt. brown clay, dry	CL	10	7	Observations from cuttings.
			6'				
10	5153.35		Tan to lt. brown clay, dry				
			10'	CL			
			Brown clay with black basalt fragments, moist	ROCK	12	41	
			11'6"				
			Refusal				
20	5143.35						
30	5133.35						
40	5123.35						
50	5113.35						
60	5103.35						
70	5093.35						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH2**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	10.5 ft	Depth to Water (ft):		Northing:	698166.589	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	584550.606	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			Powdery Observations from cuttings
			Tan to lt. brown clay, slightly moist	CL	4	16	2" Layer of flaky, very light tan clay, dry Observations from cuttings
			Tan to lt. brown clay, dry	CL			
10	5164.7		Brown clay with black basalt fragments, moist	CL ROCK	4	51/5"	
			Refusal				
20	5154.71						
30	5144.71						
40	5134.71						
50	5124.71						
60	5114.71						
70	5104.71						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH3**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	11 ft	Depth to Water (ft):		Northing:	698968.082	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	584543.132	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			Observations from cuttings
			Lt. brown clay, slightly moist	CL	3	9	Observations from cuttings
			Tan to lt. brown clay, dry	CL	14	25	
10	5173.79		Brown clay with black basalt fragments, dry	ROCK			
			Refusal				
20	5163.79						
30	5153.79						
40	5143.79						
50	5133.79						
60	5123.79						
70	5113.79						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH4**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	12 ft	Depth to Water (ft):		Northing:	699788.587	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	584562.744	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry			CL			Observations from cuttings
			Brown, moist clay	5'		CL	6	12	Observations from cuttings
						CL			
			Tan to lt. brown clay, dry	6'					
10	5165.05					CL	8	53	
			Brown, moist clay	10'		ROCK			
			Refusal	12'					
20	5155.05								
30	5145.05								
40	5135.05								
50	5125.05								
60	5115.05								
70	5105.05								

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH5**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	8 ft	Depth to Water (ft):		Northing:	700721.325	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	584561.471	Ground Elev.:

Notes: USCS Classification for sample taken at 5-6 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry			CL			Observations from cuttings
					5'	CL	DM	25	
			Tan clay, dry		8'	ROCK			
10	5177.12		Refusal						
20	5167.12								
30	5157.12								
40	5147.12								
50	5137.12								
60	5127.12								
70	5117.12								

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH6**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	8 ft	Depth to Water (ft):		Northing:	700402.146	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	583463.980	Ground Elev.:

Notes: USCS Classification for sample taken at 5-6 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			Observations from cuttings
			Brown clay, slightly moist	CL	8	29	some organic material, grasses
10	5167.77		Refusal	ROCK			
20	5157.77						
30	5147.77						
40	5137.77						
50	5127.77						
60	5117.77						
70	5107.77						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH7**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	7 ft	Depth to Water (ft):		Northing:	699784.158	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	583438.274	Ground Elev.:

Notes: USCS Classification for sample taken at 5-6 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			
5							
10	5153.93		Brown clay, moist	CL	6	31	Observations from cuttings
10	5153.93		Refusal	ROCK			
20	5143.93						
30	5133.93						
40	5123.93						
50	5113.93						
60	5103.93						
70	5093.93						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
Project: Bonneville Idaho Site  
Feature:Boring: **BH8**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	0.5 ft	Depth to Water (ft):		Northing:	698972.681	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	583433.222	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry Refusal	CL ROCK	6"		Observations from cuttings
10	5157.09						
20	5147.09						
30	5137.09						
40	5127.09						
50	5117.09						
60	5107.09						
70	5097.09						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH9**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	8 ft	Depth to Water (ft):		Northing:	698205.143	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	583403.290	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			Observations from cuttings
					5'		
			Brown clay, moist				
					8'		
10	5167.5		Refusal	ROCK			
20	5157.5						
30	5147.5						
40	5137.5						
50	5127.5						
60	5117.5						
70	5107.5						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH10  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	14 ft	Depth to Water (ft):		Northing:	697377.148	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	583429.386	Ground Elev.:

Notes: USCS Classification for sample taken at 5-6 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			Observations from cuttings
			5'	CL			
			Tan clay, dry	CL	DM	21	Observations from cuttings
			6'				
10	5160.42		Tan to lt. brown clay, dry				
			10'	CL	12	28	
			Lt. brown clay, moist				
			14'	ROCK			
			Refusal				
20	5150.42						
30	5140.42						
40	5130.42						
50	5120.42						
60	5110.42						
70	5100.42						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH11**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	2.5 ft	Depth to Water (ft):		Northing:	697369.858	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	582255.624	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. brown clay, dry	CL			Observations from cuttings
			Refusal	2'6" ROCK			
10	5143.86						
20	5133.86						
30	5123.86						
40	5113.86						
50	5103.86						
60	5093.86						
70	5083.86						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
Project: Bonneville Idaho Site  
Feature:Boring: **BH12**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:	
Total Depth (ft):	14 ft	Depth to Water (ft):		Northing:	698189.820	Vertical Angle:	
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	582346.566	Ground Elev.:	5164.68

Notes: USCS Classification for sample taken at 10.5 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Brown clay, dry			CL			Observations from cuttings
			Lt. tan clay, dry	5'		CL	4	15	Observations from cuttings
			Tan to lt. brown clay, dry	6'		CL			
10	5154.68		Lt. brown clay, dry	10'		CL	DM	42	
			Refusal	14'		ROCK			
20	5144.68								
30	5134.68								
40	5124.68								
50	5114.68								
60	5104.68								
70	5094.68								

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH13  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	7 ft	Depth to Water (ft):		Northing:	699027.830	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	582409.000	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. brown to tan clay, dry			CL			Observations from cuttings
5161.78	5161.78		Tan clay, slightly moist	5'	CL	6	20		some organics
10			Refusal	7'	ROCK				
20	5151.78								
30	5141.78								
40	5131.78								
50	5121.78								
60	5111.78								
70	5101.78								

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH14  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	7.5 ft	Depth to Water (ft):		Northing:	699812.711	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	582346.787	Ground Elev.:

Notes: USCS Classification for sample taken at 5-6 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. brown to tan clay, dry	CL			Observations from cuttings
5	5150.75		Brown clay, moist	CL	6	16	
10	5140.75		Refusal	ROCK	7'6"		
20	5130.75						
30	5120.75						
40	5110.75						
50	5100.75						
60	5090.75						
70							

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH15**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	3.5 ft	Depth to Water (ft):		Northing:	700429.172	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	582276.876	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry	CL			Observations from cuttings
10	5145.33		Refusal	3'6"	ROCK		
20	5135.33						
30	5125.33						
40	5115.33						
50	5105.33						
60	5095.33						
70	5085.33						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH16**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	3.5 ft	Depth to Water (ft):		Northing:	700417.722	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	581254.851	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Tan clay, dry			CL			Observations from cuttings
10	5147.03		Refusal	3'6"	ROCK				outcrop of basalt @ 40' NW of boring
20	5137.03								
30	5127.03								
40	5117.03								
50	5107.03								
60	5097.03								
70	5087.03								

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH17**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	4 ft	Depth to Water (ft):		Northing:	699804.006	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	581241.975	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. tan clay, dry	CL			Observations from cuttings
10	5132.74		Refusal	4' ROCK			
20	5122.74						
30	5112.74						
40	5102.74						
50	5092.74						
60	5082.74						
70	5072.74						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH18  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	5.5 ft	Depth to Water (ft):		Northing:	699070.493	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	581204.628	Ground Elev.:

Notes: USCS Classification for sample taken at 5.5 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions		USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. brown clay, dry		CL			Observations from cuttings
5.5	5133.55		Tan clay with basalt fragments, dry	5'	ROCK			
5.5	5133.55		Refusal	5'6"	ROCK	DM	50/3"	
10	5123.55							
20	5123.55							
30	5113.55							
40	5103.55							
50	5093.55							
60	5083.55							
70	5073.55							

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH19**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	3 ft	Depth to Water (ft):		Northing:	698179.118	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared & John	Easting:	581231.495	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. tan clay, dry	CL			Observations from cuttings
10	5147.59		Refusal	3'- ROCK			
20	5137.59						
30	5127.59						
40	5117.59						
50	5107.59						
60	5097.59						
70	5087.59						



**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH20  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	11/27/2007	Date Completed:	11/27/2007	Logged By:	MMB	Checked By:
Total Depth (ft):	6 ft	Depth to Water (ft):		Northing:	697398.230	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	581275.579	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. tan clay, dry	CL			
5							
10	5138.46		Lt. brown clay, dry	5'- ROCK			
10	5138.46		Refusal	6'- ROCK	4	7	Observations from cuttings
20	5128.46						
30	5118.46						
40	5108.46						
50	5098.46						
60	5088.46						
70	5078.46						

## 7.2 MAY 2008 – SOIL

### BH21 through BH30

SOIL BORING LOG						Boring:	<b>BH21</b>
						Sheet No.:	1 of 1
						Job No.:	
Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:	
Total Depth (ft):	2 ft	Depth to Water (ft):		Northing:	697639.321	Vertical Angle:	
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	588232.531	Ground Elev.:	5179.63
Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.							
Depth (ft)	Elevation (ft)	Lithology Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. brown silty clay, moist	CL			Observations from cuttings
			Refusal	ROCK			
10	5169.63						
20	5159.63						
30	5149.63						
40	5139.63						
50	5129.63						
60	5119.63						
70	5109.63						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH22**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	10 ft	Depth to Water (ft):		Northing:	698975.895	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	588229.955	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Lt. brown silty clay, moist			CL			Observations from cuttings
5									
10	5194.89		Soils very soft, split spoon sunk 12" on the first blow. Soil is brown silty clay, moist.	5'	6'	CL	8"	1	Sample taken from inside the center pivot area
10	5184.89		Brown silty clay, moist	10'		ROCK			
20	5174.89								
30	5164.89								
40	5154.89								
50	5144.89								
60	5134.89								
70									

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH23**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	5 ft	Depth to Water (ft):		Northing:	699680.618	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	587352.350	Ground Elev.:

Notes: USCS Classification for samples taken at 1 ft and 5 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			brown silty clay, moist.	CL			Proctor samples taken from 2.5' and 5' Observations from cuttings
10	5184.98			5' ROCK			Samples from the NW side of center pivot
20	5174.98						
30	5164.98						
40	5154.98						
50	5144.98						
60	5134.98						
70	5124.98						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring: **BH24**  
Sheet No.: 1 of 1  
Job No.:

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	2.5 ft	Depth to Water (ft):		Northing:	700238.043	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	588240.236	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Brown silty clay, moist. Refusal	CL ROCK	2'6"		Basalt outcroppings to the north @5' Observations from cuttings
10	5199.66						
20	5189.66						
30	5179.66						
40	5169.66						
50	5159.66						
60	5149.66						
70	5139.66						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH25  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	05/13/2008	Date Completed:	05/13/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	7 ft	Depth to Water (ft):		Northing:	701813.501	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	588240.620	Ground Elev.:

Notes: USCS Classification for sample taken at 5.5 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			tan silty clay, dry.	CL			Sagebrush area. Observations from cuttings
			Soil is brown silty clay, moist.	5'	CL		Observations from split spoon
			Brown silty clay, moist.	6'6"	CL		Observations from cuttings
10	5190.64		Refusal	7'	ROCK		
20	5180.64						
30	5170.64						
40	5160.64						
50	5150.64						
60	5140.64						
70	5130.64						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH26  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	5.5 ft	Depth to Water (ft):		Northing:	701819.277	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	585961.373	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			tan silty clay, moist. Alligator cracking on surface.	CL			Observations from cuttings
			Brown clumpy silty clay, moist.	CL	5'		
			Refusal	ROCK	5'6"		
10	5181.4						
20	5171.4						
30	5161.4						
40	5151.4						
50	5141.4						
60	5131.4						
70	5121.4						

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

**Boring:** BH27  
**Sheet No.:** 1 of 1  
**Job No.:**

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	5.5 ft	Depth to Water (ft):		Northing:	700401.262	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	585956.338	Ground Elev.:

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			tan silty clay, dry.	CL			Sagebrush area. Observations from cuttings
5.5	5177.94		tan silty clay, powdery dry. No sample recovered. Refusal	CL ROCK	5' 5'6"		
10	5167.94						
20	5157.94						
30	5147.94						
40	5137.94						
50	5127.94						
60	5117.94						
70							





**MWH**  
MONTGOMERY WATSON HARRIS

**Project:** Bonneville Idaho Site  
**Feature:**

Boring: BH28  
Sheet No.: 1 of 1  
Job No.:

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:	
Total Depth (ft):	6 ft	Depth to Water (ft):		Northing:	698977.686	Vertical Angle:	
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	589499.646	Ground Elev.:	5175.61

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology/Graphic Symbols	Lithographic Descriptions	USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			Light brown silty clay, dry.	CL			Observations from cuttings
5165.61			tan silty clay, powdery dry. Refusal	CL ROCK		19	
5155.61							
5145.61							
5135.61							
5125.61							
5115.61							
5105.61							

**MWH**

MONTGOMERY WATSON HARZA

**SOIL BORING LOG**  
**Project:** Bonneville Idaho Site  
**Feature:**

Boring:	<b>BH29</b>
Sheet No.:	1 of 1
Job No.:	

Date Started:	05/12/2008	Date Completed:	05/12/2008	Logged By:	MMB	Checked By:
Total Depth (ft):	12 ft	Depth to Water (ft):		Northing:	697669.188	Vertical Angle:
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	585950.128	Ground Elev.: 5169.69

Notes: USCS classification was interpreted based on laboratory test results from adjacent boreholes.

Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions			USCS Class	Recovery (in)	N value	Notes and Observations (Sample/Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
0			tan to brown silty clay, moist with alligator cracking at surface.			CL			Observations from cuttings.
			Soil is tan silty clay, moist. Not much cohesion.	5'		CL	6"	33	Observations from sample.
			Brown silty clay, moist.	6'		CL			Observations from cuttings.
10	5159.69		Brown silty clay, moist, more cohesive.	10'		CL	12"	21	Observations from sample.
			Refusal	12'		ROCK			
20	5149.69								
30	5139.69								
40	5129.69								
50	5119.69								
60	5109.69								
70	5099.69								



**MWH**  
MONTGOMERY WATSON HARZA

Project: Bonneville Idaho Site  
Feature:

Boring: BH30  
Sheet No.: 1 of 1  
Job No.:


SOIL BORING LOG					
Date Started:	05/12/2008	Date Completed:	05/12/2008 <th>Logged By:</th> <td>MMB</td>	Logged By:	MMB
Total Depth (ft):	20.5 ft	Depth to Water (ft):		Northing:	701729.591
Drilling Contr.:	Andrew Well Drilling	Driller:	Jared	Easting:	584478.389
Notes: USCS Classification for sample taken at 5.5 ft was verified by laboratory testing. USCS Classifications for remainder of boring were interpreted based on laboratory test results.					
Depth (ft)	Elevation (ft)	Lithology (Graphic Symbols)	Lithographic Descriptions	USCS Class	Recovery (in)
0			tan to brown silty clay, dry	CL	
			Soil is brown clumpy silty clay, moist.	CL	6"
				CL	43
			Brown silty clay, moist.		
10	5180.33		Brown silty clay, moist.	CL	6"
				CL	11
			Brown silty clay, moist		
			Brown silty clay, moist	CL	8"
				CL	14
			Brown silty clay, moist		
20	5170.33		Brown silty clay, moist	ROCK	12
					18
			Brown silty clay, moist		
			Refusal		
30	5160.33				
40	5150.33				
50	5140.33				
60	5130.33				
70	5120.33				

## 7.3 APRIL – MAY 2008 – ROCK CORING

**GW-1**

ROCK BORING LOG								Hole No.: GW-1				
								Sheet No.: 1 of 67				
								Job No.: 1005746				
Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito					
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:						
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:						
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32							
0	Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
1				2.5/3.5 (83%)	NA					(ML) FINE SANDY SILT, DRY GRADING TO SLIGHTLY MOIST, SLIGHTLY PLASTIC MODERATE YELLOWISH BROWN 10YR 5/4, STIFF		BOX 1
2												
3												
4				1.5/1.5 (100%)	1.2/1.5 (80%)					SLIGHT WEATHERING VESICULAR OLIVINE BASALT, WK FEOL IN SOME VESICLES, HARD VERY STRONG ROCK		BEDROCK / SOIL INTERFACE
5			1	3.2/3.5 (90%)	3.2/3.5 (90%)					BROWNISH BLACK (5Y 2/1) TO BLACK (N1) GRADING TO FRESH APPROX 5° BGS VESICLES UP TO 15 mm		
6										LOST WATER CIRCULATION FLUID OUT IN FRACTURES		
7												
8			2	2.0/2.0 (100%)	1.7/2.0 (85%)					GRADING TO SMALLER VESICLES WITH FEW UP TO 10 mm		
9												
10			3									BOX 2

1005746008-A.dwg



**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 3 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito		
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:			
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:			
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32				
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Lithology (Graphic Symbol)	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
22									
-23									
-24									
-25									
-26		6	5.0/5.0 (100%)	5.0/5.0 (100%)					
-27									
-28									
-29									
-30									
-31		7	5.0/5.0 (100%)	3.2/5.0 (64%)					
-32									

1005746D008-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 4 of 67  
Job No.: 1005746

Date Started: 4/21/08	Date Completed: 5/8/08	Logged By: B. Bragdon	Checked By: K. Esposito
Total Depth (ft): 730.5	Depth to Water (ft):	Northing: 698,178.53	Vertical Angle:
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux	Easting: 584,480.21	Azimuth:
Drill Rig: Rotary Core	Core Barrel: HQ x 5'	Ground Elev.: 5176.32	
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)
33			
34			
35	8		
36		5.0/5.0 (100%)	5.0/5.0 (100%)
37			
38			
39			
40	9	5.0/5.0 (100%)	3.3/5.0 (66%)
41			
42			
43			

Lithologic Descriptions

Notes and Observations  
(Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)

Packer Test

Small Vesicles, generally 1-2 mm

BOX 5

40.5-41.4 VERY FINE SMALL VESICLES (<1 mm)

GRADES TO GREENISH GRAY (5GY 6/1) BASALT, WITH LARGE (3-15 mm) VESICLES WITH CINDERS OF DUSKY RED (10R 3/3)

GRADES TO VERY DARK GRAY (N3)

GRADES TO WEAK RED (10R 4/2)

CINDERS DUSKY RED (10R 3/3)

1005746D008-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 5 of 67

Job No.: 1005746

Date Started: 4/21/08		Date Completed: 5/8/08		Logged By: B. Bragdon		Checked By: K. Esposito					
Total Depth (ft): 730.5		Depth to Water (ft):		Northing: 698,178.53		Vertical Angle:					
Drilling Contr.: Crux Subsurface, Inc.		Driller: Brandon Gereaux		Easting: 584,480.21		Azimuth:					
Drill Rig: Rotary Core		Core Barrel: HQ x 5'		Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-44											
-45		10									
-46			5.0/5.0 (100%)	5.0/5.0 (100%)					LARGE VESICLES 4-20 mm		
-47									GRADES TO DUSKY RED (10R 3/2)		
-48											
-49											
-50		11									
-51			5.1/5.0 (100%)	4.7/5.0 (94%)							
-52									51.5-53.5 VERY FINE GRAINED BASALT, FEW 1mm VESICLES		
-53											
-54									3-5 mm VESICLES		

1005746D008-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 6 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito			
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:				
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:				
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32					
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
55										
-56		12								4/21/08
-56			4.5/5.0 (90%)	3.6/5.0 (72%)				OLIVINE BASALT, DARK GRAY (N4) SMALL VESICLES (1 mm)		
-57										BOX 7
-58								GRADES TO LARGER VESICLES (3-15 mm) AND DARK REDDISH GRAY (10R 3/1)		
-59								5-10 mm OR MORE		
-60								FRACTURE FILLED WITH SILTY FINE TO MEDIUM SAND, LOST APPROXIMATELY 0.5' OF MATERIAL WITH CIRCULATION		
-61		13						VESICULAR BASALT, DUSKY RED (2.5YR 3/2)		
-61			5.0/5.0 (100%)	4.6/5.0 (92%)				SILTY CLAY, YELLOWISH BROWN (10YR 5/4) MEDIUM PLASTICITY VERY STIFF		
-62								OLIVINE BASALT, DARK GRAY (N4) VESICLES 1-10 mm		
-63								1 mm		
-64								SILTY CLAY, AS ABOVE AT 61'		
-65		14						VESICULAR BASALT, DUSKY RED (2.5YR 3/2) VESICLES 2-10 mm		

1005746D008-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 7 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08	Logged By: B. Bragdon					Checked By: K. Esposito				
Total Depth (ft): 730.5	Depth to Water (ft):	Northing: 698,178.53					Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux	Easting: 584,480.21					Azimuth:				
Drill Rig: Rotary Core	Core Barrel: HQ x 5'	Ground Elev.: 5176.32									
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-66								1.5 mm	VERY FRACTURED OLIVINE BASALT, 1-5 mm FRACTURES, REDDISH GRAY (2.5YR NS)		
-67			4.7/5.0 (94%)	3.1/5.0 (62%)				2 mm			BOX 8
-68								2 mm			
-69								1-2 mm			
-70								1 mm	VESICLES 3-10 mm		
-71		15									
-72			4.8/5.0 (96%)	3.8/5.0 (76%)					WITH SILTY CLAY FRACTURE FILLING 2-10 mm PALE BROWN (10YR 6/3) BASALT, GRADES TO DARK GRAY (N4)		
-73								2 mm			
-74									20 mm TOTAL WITH SILTY CLAY FRACTURE FILLING		
-75									WITH SILTY CLAY FRACTURE FILLING		
-76		16						3 mm	3 mm, FEOX ALONG FRACTURE WITH TRACE CLAY		

1005746D003-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 8 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-77											
-78			5.0/5.0 (100%)	4.5/5.0 (90%)							
-79									LARGE VESICLES UP TO 20 mm ABOVE FRACTURE		
-80									LARGE VESICLES		
-81		17	5.0/5.0 (100%)	5.0/5.0 (100%)					MINOR RUBBLE WITH TRACE SILTY CLAY		
-82									OLIVINE BASALT, VERY DARK GRAY (N3) TO BLACK (N2.5) VERY FINE GRAINED FEW VESICLES OVER 3 mm		
-83											
-84											
-85		18	5.0/5.0 (100%)	5.0/5.0 (100%)					OLIVINE BASALT, VERY DARK GRAY (N3) TO BLACK (N2.5) VERY FINE GRAINED, FEW VESICLES 2 mm		
-86											
-87											
											BOX 9
											BOX 10

1005746D008-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 9 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
88											
89											
90		19									
91			4.9/5.0 (98%)	3.4/5.0 (68%)							
92											
93											
94											
95		20									
96			5.0/5.0 (100%)	3.2/5.0 (64%)							
97											
98											

The geological log diagram illustrates the rock characteristics across the core log. It features a vertical column of symbols representing different lithologies, such as basalt, olivine, and vesicles. Overlaid on this are numerous fracture symbols, including various orientations (e.g., 30°, 60°, 70°) and sizes (e.g., 1-2 mm, 2 mm, 1 mm). The structure column shows the degree of fracturing, ranging from 60° to 40°. The notes column provides detailed descriptions of the rock types and their properties at specific depths, such as 'BASALT, OLIVINE WITH 1-5 mm VESICLES VERY DARK GRAY (N3) TO BLACK (N2.5)' at 90 ft and 'VERY FRACTURED, ALL 1-3 mm' at 95 ft.

1005746D008-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 10 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
99											
100											
101		21	4.9/5.0 (98%)	3.6/5.0 (72%)					VERY FRACTURED WITH 1-3 mm FRACTURES		
102									GRADES TO VERY DARK GRAY (N3) WITH SOME DARK REDDISH GRAY (10R 3/1) MAINLY ALONG FRACTURES		
103											
104											
105											
106		22	5.0/5.0 (100%)	4.7/5.0 (94%)					BASALT, OLIVINE VERY DARK GRAY (N3) WITH BLACK (N25) ALONG FRACTURES VERY SMALL 1 mm OR LESS, VESICLES	BOX 12	
107											
108											
109											

1005746D003-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 11 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
110		23	4.8/5.0 (96%)	2.4/5.0 (48%)					VERY SMALL VESICLES (1-2 mm)		
111											
112									OLIVINE BASALT, SMALL (<1 mm) VESICLES VERY DARK GRAY (N3)		
113									VERY FRACTURED TO RUBBLE (113-115.5) SOME SILTY CLAY FRACTURE FILLING		
114										BOX 13	
115		24	5.0/5.0 (100%)	3.1/5.0 (62%)				20 mm		4/22/08	
116								20-40°			
117									BASALT, GRADES TO LIGHT GRAY (N7) 30 mm FRACTURE COATING OF SILTY CLAY, MAY HAVE WASHED OUT BY DRILLING		
118									3-5 mm VESICLES		
119									BASALT, GRADES TO VERY DARK GRAY (N3) TO DARK REDDISH GRAY (10R 3/1)		
120		25	4.9/5.0 (98%)	4.9/5.0 (98%)					3-10 mm VESICLES		

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 12 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08			Logged By: B. Bragdon			Checked By: K. Esposito				
Total Depth (ft): 730.5	Depth to Water (ft):			Northing: 698,178.53			Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux			Easting: 584,480.21			Azimuth:				
Drill Rig: Rotary Core	Core Barrel: HQ x 5'			Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-121											
-122									OLIVINE BASALT, VERY DARK GRAY (N3) WITH SOME DARK REDDISH GRAY (10R 4/1), SMALL VESICLES (1 mm OR LESS) WITH FEW UP TO 15 mm LOCALLY		
-123											BOX 14
-124											
-125		26									
-126			5.0/5.0 (100%)	4.8/5.0 (96%)					FINE GRAINED OLIVINE BASALT, VESICLES <1 mm GRADES TO REDDISH BLACK (2 5YR N2.5) TO GRAY (N5)		
-127											
-128											
-129											
-130									INCREASE IN VESICLE SIZE TO 2-10 mm, SOME CINDERS OF WEAK RED (10R 4/4) AT 130. 5		
-131		27							BASALT, GRADES TO WEAK RED (10R 4/3)		

1005746D009-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 13 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
132											
133											
134											
135		28									
136			5.0/5.0 (100%)	3.8/5.0 (76%)							
137											
138											
139											
140		29									
141			5.0/5.0 (100%)	2.8/5.0 (56%)							
142											

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 14 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-143								1 mm			BOX 16
-144								1 mm	1-2 mm WITH TRACE SILT ALONG FRACTURES		
-145		30						1 mm			
-146			4.2/5.0 (84%)	3.4/5.0 (68%)				70°	RUBBLE / MAY HAVE BEEN VOID AT 145.5-146		
-147								70°			
-148								80°			
-149											
-150		31						2 mm			
-151			5.0/5.0 (100%)	4.7/5.0 (94%)				2 mm			
-152								70°	WEAK RED (10R 4/3) 2 mm WITH SILTY CLAY ALONG FRACTURE SMALL VESICLES		
-153								50°	2 mm		
								1-3 mm	BASALT, GRADES TO GRAY (N5)		BOX 17

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Project: Areva Feature: Core Log							Hole No.: GW-1				
							Sheet No.: 15 of 67				
							Job No.: 1005746				
Date Started: 4/21/08		Date Completed: 5/8/08		Logged By: B. Bragdon		Checked By: K. Esposito					
Total Depth (ft): 730.5		Depth to Water (ft):		Northing: 698,178.53		Vertical Angle:					
Drilling Contr.: Crux Subsurface, Inc.		Driller: Brandon Gereaux		Easting: 584,480.21		Azimuth:					
Drill Rig: Rotary Core		Core Barrel: HQ x 5'		Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-154								10 mm	FRACTURE WITH SILTY CLAY OF MODERATE YELLOWISH BROWN (10YR 5/4), SLIGHT TO MEDIUM PLASTICITY		
-155		32		5.0/5.0 (100%)	4.7/5.0 (94%)						
-156											
-157											
-158									BASALT, GRADES TO WEAK RED (10R 4/2) WITH VESICLES 2-10 mm WITH CINDERS OF WEAK RED (10R 4/2) IN 10 mm VOID		
-159								1 mm	BASALT, GRADES TO DUSKY RED (10R 3/3)		
-160								3 mm	VESICLES AND VOIDS UP TO 15 mm		
-161		33		4.8/5.0 (96%)	4.1/5.0 (82%)						
-162								5 mm			
-163								3 mm			
-164								85°			
								80°			
								90°			
									LARGE VESICLES AND VOIDS UP TO 25 mm		BOX 18

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 16 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
- 165		34									
- 166			5.0/5.0 (100%)	5.0/5.0 (100%)					BASALT, DUSKY RED (10R 3/3) WITH DARK GRAY (N4), VESICLES UP TO 25 mm, GENERALLY FINE GRAINED WITH SMALL VESICLES, LESS THAN 1-2 mm		
- 167											
- 168											
- 169											
- 170		35							FINE GRAINED BASALT, VESICLES 1-3 mm FEW TO 10 mm DARK GRAY (N4) TO DARK REDDISH GRAY (10R 3/1)		
- 171											
- 172									VESICLES UP TO 20 mm 172-173 FEET		
- 173											
- 174											
- 175		36									
			5.0/5.0 (100%)	4 1/5.0 (82%)							

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 17 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-176											
-177											
-178											
-179											
-180											
-181	37		5.0/5.0 (100%)	3.1/5.0 (62%)							
-182											BOX 20
-183											
-184											
-185											
-186	38		5.0/5.0 (100%)	5.0/5.0 (100%)							

1005746D009-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 18 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
187											
188									MEDIUM GRAINED BASALT, VERY DARK GRAY (N4)		
189											
190		39									
191			5.0/5.0 (100%)	5.0/5.0 (100%)							BOX 21
192											
193									LARGER VESICLES (UP TO 10 mm)		
194									RUBBLE ABOVE CONTACT FINE SANDY SILT, RED (10R 5/8) SLIGHTLY MOIST, NON PLASTIC		
195		40									
196			5.0/5.0 (100%)	5.0/5.0 (100%)							
197									GRADES TO YELLOWISH BROWN (10YR 5/4) AT 197		
									BASALT, DARK REDDISH GRAY (10R 4/1)		
									TEST P-6 K <sub>n</sub> =2.5 E <sub>06</sub>		

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 19 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito			
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:				
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:				
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32					
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot Lithology / Graphic Symbol	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-198										
-199										
-200		41								
-201			5.0/5.0 (100%)	4.7/5.0 (94%)						
-202										
-203										
-204										
-205		42								
-206			4.4/5.0 (88%)	3.5/5.0 (70%)						
-207										
-208										

1005746D009-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 20 of 67				
							Job No.: 1005746				
Date Started: 4/21/08			Date Completed: 5/8/08			Logged By: B. Bragdon	Checked By: K. Esposito				
Total Depth (ft): 730.5			Depth to Water (ft):			Northing: 698,178.53	Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.			Driller: Brandon Gereaux			Easting: 584,480.21	Azimuth:				
Drill Rig: Rotary Core			Core Barrel: HQ x 5'			Ground Elev.: 5176.32					
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-209											
-210		43	5.0/5.0 (100%)	4.1/5.0 (82%)					VESICULAR BASALT, GRAY (N6) FINE GRAINED, SMALL VESICLES SOME UP TO 5 mm GENERALLY 1-2 mm		
-211									FRACTURED TO RUBBLE 210-210.8	BOX 23	
-212								2 mm			
-213								1 mm			
-214								5 mm	GRADES BASALT, TO DARK REDDISH GRAY (10R 4/1) AND TO LARGER VESICLES UP TO 10 mm		
-215		44	5.0/5.0 (100%)	3.5/5.0 (70%)				2 mm	FRACTURED TO RUBBLE WITH TRACE DUSKY RED (10R 3/7) CINDER'S LARGE VESICLES UP TO 20 mm SOME OLIVINE ALONG FRACTURES		
-216											
-217											
-218									GRADES TO VERY FINE GRAINED BASALT, GRAY (N6)		
-219											

1005746D009-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 21 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-220											BOX 24
-221		45	4.3/5.0 (86%)	3.3/5.0 (66%)							
-222									GRADES TO BLACK (N2.5) WITH VESICLES UP TO 15 mm		
-223											
-224									FRACTURED TO RUBBLE, LIKELY LAST 0.7' IN THIS INTERVAL. BLACK (N2.5) WITH WEAK RED (10R 4/4) CINDER SAND FRACTURE COATING		
-225		46								7/23/08	
-226			3.2/5.0 (64%)	0/5.0 (0%)							
-227											
-228									BASALT. VERY BROKEN TO RUBBLE WEAK RED (10R 4/2) SOME AREAS OF DARK GRAY (N4) SILTY CLAY COATING LOCALLY		
-229											
-230		47									

1005746DD010-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Project: Areva Feature: Core Log							Hole No.: GW-1				
							Sheet No.: 22 of 67				
							Job No.: 1005746				
Date Started: 4/21/08		Date Completed: 5/8/08		Logged By: B. Bragdon			Checked By: K. Esposito				
Total Depth (ft): 730.5		Depth to Water (ft):		Northing: 698,178.53			Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.		Driller: Brandon Gereaux		Easting: 584,480.21			Azimuth:				
Drill Rig: Rotary Core		Core Barrel: HQ x 5'		Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
- 231											BOX 25
- 232									VESICULAR BASALT, WITH VESICLES UP TO 20 mm GENERALLY 2-10 mm DARK GRAY (N4), FINE GRAINED		
- 233											
- 234									VOID		
- 235	48		5.0/5.0 (100%)	4.5/5.0 (90%)							
- 236									GRADES TO FINE GRAINED BASALT, DARK GRAY (7.5R 4/1) WITH FEW VESICLES		
- 237											
- 238									RUBBLE		
- 239											
- 240	49		5.0/5.0 (100%)	4.6/5.0 (92%)							BOX 26
- 241									FINE GRAINED BASALT, DARK GRAY (7.5R 4/1) FEW VESICLES GREATER THAN 1 mm		

1005746D010-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 23 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-242											
-243											
-244											
-245	50		4.9/5.0 (98%)	4.6/5.0 (92%)							
-246											
-247											
-248											
-249											
-250	51										
-251			5.0/5.0 (100%)	4.0/5.0 (80%)							
-252											

1005746D010-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 24 of 67				
							Job No.: 1005746				
Date Started: 4/21/08			Date Completed: 5/8/08			Logged By: B. Bragdon	Checked By: K. Esposito				
Total Depth (ft): 730.5			Depth to Water (ft):			Northing: 698,178.53	Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.			Driller: Brandon Gereaux			Easting: 584,480.21	Azimuth:				
Drill Rig: Rotary Core			Core Barrel: HQ x 5'			Ground Elev.: 5176.32					
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
- 253						SM			SILTY SAND (SM), MODERATE YELLOWISH BROWN (10YR 5/4) NON PLASTIC		
- 254							10°	2 mm	VESICULAR BASALT, BLACK (N2.5), ABUNDANT VESICLES UP TO 10 mm		
- 255								2 mm	WITH TRACE SILTY SAND ALONG FRACTURE		
- 256		52									
- 257											
- 258											
- 259											
- 260		53									BOX 28
- 261											
- 262											
- 263											

1005746D010-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 25 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
- 264											
- 265		54									
- 266			5.0/5.0 (100%)	5.0/5.0 (100%)					VESICULAR BASALT. BLACK (N2.5) TO DARK GRAY (N4) FEW VESICLES GREATER THAN 5 mm		
- 267											
- 268								2 mm			
- 269											
- 270		55							WITH TRACE YELLOWISH BROWN (10YR 5/4) SILT ALONG FRACTURE	BOX 29	
- 271			5.0/5.0 (100%)	5.0/5.0 (100%)							
- 272											
- 273									NO FRACTURES, DARK REDDISH GRAY (10R 4/1), FINE GRAINED SMALL VESICLES 1-2 mm		
- 274											

1005746D010-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 26 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08		Logged By: B. Bragdon		Checked By: K. Esposito						
Total Depth (ft): 730.5	Depth to Water (ft):		Northing: 698,178.53		Vertical Angle:						
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux		Easting: 584,480.21		Azimuth:						
Drill Rig: Rotary Core	Core Barrel: HQ x 5'		Ground Elev.: 5176.32								
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
- 275											
- 276	56		5.0/5.0 (100%)	4.3/5.0 (86%)				1 mm			
- 277											
- 278								1 mm	FINE GRAINED BASALT, WITH FEW VESICLES GREATER THAN 3 mm		
- 279											
- 280	57									BOX 30	
- 281			5.0/5.0 (100%)	5.0/5.0 (100%)							
- 282											
- 283											
- 284											
- 285	58										

1005746D010-A.dwg



## ROCK BORING LOG

Project: Areva

## Feature: Core Log

Hole No.: GW-1

---

Sheet No.: 27 of 67

Job No.: 1005746

Date Started: 4/21/08				Date Completed: 5/8/08			Logged By: B. Bragdon		Checked By: K. Esposito			
Total Depth (ft): 730.5				Depth to Water (ft):			Northing: 698,178.53		Vertical Angle:			
Drilling Contr.: Crux Subsurface, Inc.				Driller: Brandon Gereaux			Easting: 584,480.21		Azimuth:			
Drill Rig: Rotary Core				Core Barrel: HQ x 5'			Ground Elev.: 5176.32					
Depth (ft)	Elevation (ft)	Run No	Recovery (%)	RQD (%)	Fractions/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions		Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-286			5.0/5.0 (100%)	4.6/5.0 (92%)					BLACK (N2 5) BASALT, FINE GRAINED FEW VESICLES OVER 2 mm WITH FEW VUGS			
-287												
-288									SOME SILT OF YELLOWISH BROWN (10YR 5/4) IN FRACTURES AND RUBBLE		BOX 31	
-289									SOME DUSKY RED (10R 3/4) IN VUGS VOIDS			
-290		59							SOME SILT OF YELLOWISH BROWN (10YR 5/4)			
-291			5.0/5.0 (100%)	3.7/5.0 (74%)								
-292												
-293												
-294												
-295		60							LARGER VESICLES APPROX 295 DARK GRAY (N4) TO BLACK (N2 5) WITH DUSKY RED IN VOIDS			
-296			5.0/5.0 (100%)	4.3/5.0 (86%)					RUBBLE			

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Project: Areva Feature: Core Log							Hole No.: GW-1				
							Sheet No.: 28 of 67				
							Job No.: 1005746				
Date Started: 4/21/08		Date Completed: 5/8/08		Logged By: B. Bragdon			Checked By: K. Esposito				
Total Depth (ft): 730.5		Depth to Water (ft):		Northing: 698,178.53			Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.		Driller: Brandon Gereaux		Easting: 584,480.21			Azimuth:				
Drill Rig: Rotary Core		Core Barrel: HQ x 5'		Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-297											
-298											BOX 32
-299											
-300	61		4.9/5.0 (98%)	4.6/5.0 (92%)					SILT IN FRACTURE LARGE VESICLES DARK GRAY BLACK		
-301											
-302											
-303											
-304											
-305	62								RUBBLE OF DARK GRAY (N3) TO BLACK (N2.5) BASALT, WITH WEAK RED (2.5YR 4/2) IN VESICLES SAND DUSKY RED (10R 3/3) ALONG FRACTURES		
-306			5.0/5.0 (100%)	3.7/5.0 (74%)							
-307											BOX 33

1005746D010-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 29 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-308									VERY FRACTURED BASALT, WITH WEAK RED (10R 4/4) CINDERS		
-309											
-310									VERY FRACTURED, BASALT, GRADES TO DUSKY RED (10R 3/2) WITH YELLOWISH BROWN (10YR 5/4) SILTY COATING ALONG FRACTURES		
-311		63		5.0/5.0 (100%)	3.8/5.0 (76%)			70° 2.5 mm			
-312								80° 2 mm	BLACK (N2 5) BASALT, WITH DUSKY RED (10R 3/2) IN VESICLES AND VOIDS UP TO 10 mm FRACTURE COATING OF LIGHT BROWN (7.5YR 6/3) AND IRIDESCENCE COATING		
-313											
-314											
-315		64						3 mm	VOID WITH LIGHT BROWN (7.5YR 6/3) COATING VESICLES UP TO 5 mm SOME VUGS		
-316				2.0/2.5 (80%)	0.7/2.5 (28%)				RUBBLE OF DUSKY RED (10R 3/2) AND DARK GRAY (N4) BASALT, TRACE YELLOWISH BROWN (10YR 5/4) SILT		
-317											
-318		65		2.4/2.4 (100%)	2.4/2.4 (100%)				BLACK (N2 5) VESICULAR BASALT, VESICLES UP TO 5 mm	4/24/08	

1005746D010-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Project: Areva Feature: Core Log							Hole No.: GW-1				
							Sheet No.: 30 of 67				
							Job No.: 1005746				
Date Started: 4/21/08		Date Completed: 5/8/08		Logged By: B. Bragdon			Checked By: K. Esposito				
Total Depth (ft): 730.5		Depth to Water (ft):		Northing: 698,178.53			Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.		Driller: Brandon Gereaux		Easting: 584,480.21			Azimuth:				
Drill Rig: Rotary Core		Core Barrel: HQ x 5'		Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-319											
-320		66	4.2/4.6 (91%)	4.2/4.6 (91%)				2 mm	VESICULAR BASALT, VERY DARK GRAY (N3) WITH VESICLES UP TO 10 mm		SHORT CORE RUN TO CHECK DRILL BIT BOX 34
-321											
-322								5 mm	WITH TRACE YELLOWISH BROWN (10YR 5/4) SILT COATING ALONG FRACTURE		
-323											
-324		67	1.0/1.0 (100%)	1.0/1.0 (100%)							
-325		68	5.0/5.0 (100%)	4.2/5.0 (84%)					DECREASE IN VESICLES SIZE AND FINER GRAINED BASALT, VERY DARK GRAY (N3)		SHORT CORE RUN TO CHECK DRILL BIT
-326											
-327											
-328											
-329									WITH SOME YELLOWISH BROWN (10YR 5/4) COATING ALONG FRACTURES AND TRACE SILT LOCALLY		BOX 35

1005746D010-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 31 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-330		69									
-331			5.0/5.0 (100%)	4.4/5.0 (88%)					SOME GAPS AND VOIDS ALONG FRACTURES WITH YELLOWISH BROWN (10YR 5/4) SILT ALONG FRACTURE		
-332											
-333									GRADES TO VERY FINE GRAINED NO VESICLES >1 mm		
-334									VOID		
-335		70							VESICULAR BASALT, OF REDDISH GRAY (10R 3/1) WITH WEAK RED (10R 4/4) AND YELLOWISH BROWN (10YR 5/4) SILT ALONG FRACTURES. ABUNDANT VESICLES UP TO 10 mm		
-336			5.0/5.0 (100%)	4.7/5.0 (94%)					2 mm		
-337									60°		
-338									50°		
-339									1-2 mm		
-340		71							80°		
									3 mm		
										BOX 36	

1005746DD011-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 32 of 67				
							Job No.: 1005746				
Date Started:	4/21/08		Date Completed:	5/8/08		Logged By:	B. Bragdon	Checked By:	K. Esposito		
Total Depth (ft):	730.5		Depth to Water (ft):			Northing:	698,178.53	Vertical Angle:			
Drilling Contr.:	Crux Subsurface, Inc.		Driller:	Brandon Gereaux		Easting:	584,480.21	Azimuth:			
Drill Rig:	Rotary Core		Core Barrel:	HQ x 5'		Ground Elev.:	5176.32				
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-341			5.0/5.0 (100%)	4.6/5.0 (92%)				3 mm			
-342								1 mm			
-343								2 mm			
-344								1 mm	GRADES TO WEAK RED (10R 4/2) LARGE VESICLES UP TO 15 mm		
-345									GRADES TO DARK GRAY (N4) FINE TO MEDIUM GRAINED FEW VESICLES >2 mm		
-346	72		5.0/5.0 (100%)	4.7/5.0 (94%)					LARGER VESICLES AT 345.3 AND SOME WEAK RED (10R 4/3) IN VESICLES WITH SOME YELLOW BROWN (10YR 5/4) COATING ALONG FRACTURE VESICLES UP TO 10 mm		
-347								1-5 mm		BOX 37	
-348								1-10 mm			
-349								1 mm	SOME FRACTURE COATING OF YELLOW BROWN (10YR 5/4)		
-350								3 mm			
-351	73		5.0/5.0 (100%)	5.0/5.0 (100%)							

1005746D011-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 33 of 67  
Job No.: 1005746

Date Started: 4/21/08	Date Completed: 5/8/08	Logged By: B. Bragdon	Checked By: K. Esposito								
Total Depth (ft): 730.5	Depth to Water (ft):	Northing: 698,178.53	Vertical Angle:								
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux	Easting: 584,480.21	Azimuth:								
Drill Rig: Rotary Core	Core Barrel: HQ x 5'	Ground Elev.: 5176.32									
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-352											
-353											
-354											
-355	74		4.5/5.0 (90%)	4.3/5.0 (86%)				2-10 mm	GRADES TO FINE GRAINED BASALT, WITH SOME HORIZONTAL VUGS, VESICLES 1 mm OR <1 mm, DARK GRAY (N4)		
-356											
-357								10 mm	VOID WITH TRACE YELLOWISH BROWN COATING ALONG FRACTURE, BASALT, GRADES TO WEAK RED (10R 4/3) WITH VESICLES UP TO 15 mm	BOX 38	
-358								2 mm			
-359								3 mm	GRADES TO DARK REDDISH GRAY (10R 3/1) WITH VESICLES UP TO 15 mm WITH SOME BENTONITE FROM DRILLING FLUID ALONG FRACTURES		
-360	75							1 mm			
-361			5.0/5.0 (100%)	4.6/5.0 (92%)				2 mm	GRADES TO VERY FINE GRAINED BASALT		
-362									GRADES TO BASALT, WITH VESICLES UP TO 8 mm, BLACK (N2.5)		
									VOID 10-20 mm		

1005746D011-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

ROCK BORING LOG

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 34 of 67				
							Job No.: 1005746				
Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-363									GRADES TO WEAK RED (10R 4/2) WITH VESICLES UP TO 10 mm		
-364									2-5 mm TRACE YELLOWISH BROWN FRACTURE COATING, BASALT, GRADES TO DUSKY RED (10R 3/2)		
-365	76								DARK RED (10R 3/4) FRACTURE COATING, TRACE SILTY SAND OF YELLOWISH BROWN (10YR 5/4) GRADES TO RUBBLE	BOX 39	
-366			4.5/5.0 (90%)	2.8/5.0 (56%)					BASALT, GRADES TO VERY DARK GRAY (N3) WITH VESICLES UP TO 5 mm		
-367									WITH TRACE YELLOWISH BROWN (10YR 5/4) COATING ALONG FRACTURE, BASALT, GRADES TO VERY DARK GRAY (N3) WITH VESICLES 5-20 mm		
-368											
-369											
-370	77										
-371			4.9/5.0 (99%)	4.9/5.0 (99%)							
-372											
-373											

1005746D011-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 35 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08	Logged By: B. Bragdon					Checked By: K. Esposito				
Total Depth (ft): 730.5	Depth to Water (ft):	Northing: 698,178.53					Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux	Easting: 584,480.21					Azimuth:				
Drill Rig: Rotary Core	Core Barrel: HQ x 5'	Ground Elev.: 5176.32									
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-374											
-375		78									
-376			4.9/5.0 (98%)	4.9/5.0 (98%)					GRADES TO VERY FINE GRAINED BASALT, FEW VESICLES AND VOIDS UP TO 10 mm GENERALLY <1 mm		
-377											
-378											
-379											
-380		79									
-381			4.9/5.0 (98%)	4.6/5.0 (92%)					TEST P-5, k <sub>1</sub> =59 E04		
-382											
-383											
-384											

1005746D011-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

ROCK BORING LOG

Hole No.: GW-1  
Sheet No.: 36 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-385											
-386	80		5.0/5.0 (100%)	5.0/5.0 (100%)							
-387											BOX 41
-388											
-389											
-390	81		5.0/5.0 (100%)	4.3/5.0 (86%)							
-391											
-392											
-393											
-394											
-395	82		4.5/5.0 (90%)	2.8/5.0 (56%)							BOX 42 4/25/08

1005746D011-A.dwg

**MWH**


Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 37 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-396											
-397											
-398											
-399											
-400		83	4.8/4.8 (100%)	4.8/4.8 (100%)							
-401											
-402											
-403											
-404											
-405		83	4.2/5.0 (84%)	0/5.0 (0%)							
-406											
VESICULAR BASALT, DARK REDDISH GRAY (10R 3/1) WITH VESICLES AND FRACTURES OF RED (10R 4/6), VERY BROKEN 2-5 mm VUGS UP TO 20 mm											
GRADES TO VERY FINE GRAINED BASALT, WITH VERY FEW VESICLES >1 mm VERY DARK GRAY (N3) TO BLACK (N25)											
GRADES TO VESICULAR BASALT, WITH VESICLES UP TO 5-8 mm, VERY DARK GRAY (N3)											
ML/CL											
SILT/CLAY, LOW TO MEDIUM PLASTICITY LOCALLY, STRONG BROWN (SYR 5/6) WITH COARSE GRAVEL TO COBBLE SIZE BASALT											
TEST P-4 $k_0 = 3.6 \text{ cm}$											
INCREASE IN SIZE OF BASALT IN SOIL MATRIX BROWN (7.5YR 5/3)											
BOX 43											

1005746D011-A.dwg




**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 39 of 67				
							Job No.: 1005746				
Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-418											
-419											
-420		86									
-421			5.0/5.0 (100%)	3.7/5.0 (74%)							
-422											
-423											
-424											
-425		86	5.0/5.0 (100%)	4.5/5.0 (90%)							
-426											
-427											
-428											

1005746D011-A.dwg





MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 41 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-440											
-441		90	4.9/5.0 (98%)	4.6/5.0 (92%)					VESICULAR BASALT, VERY DARK GRAY (N3) WITH DUSKY RED (10R 3/2) IN VESICLES AND SOME FRACTURES VESICLES UP TO 10 mm GENERALLY 3-5 mm		
-442											
-443											
-444											
-445		91								BOX 47	
-446			5.0/5.0 (100%)	5.0/5.0 (100%)							
-447											
-448											
-449											
-450		92	5.0/5.0 (100%)	4.8/5.0 (96%)							

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 42 of 67				
							Job No.: 1005746				
Date Started:	4/21/08		Date Completed:	5/8/08		Logged By:	B. Bragdon	Checked By:	K. Esposito		
Total Depth (ft):	730.5		Depth to Water (ft):			Northing:	698,178.53	Vertical Angle:			
Drilling Contr.:	Crux Subsurface, Inc.		Driller:	Brandon Gereaux		Easting:	584,480.21	Azimuth:			
Drill Rig:	Rotary Core		Core Barrel:	HQ x 5'		Ground Elev.:	5176.32				
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-451											
-452											
-453											
-454											
-455		93									
-456			5.0/5.0 (100%)	3.1/5.0 (62%)							
-457											
-458											
-459											
-460		94	5.0/5.0 (100%)	4.1/5.0 (82%)							
-461											

FINE TO MEDIUM GRAINED BASALT, FEW 1 mm VESICLES, GRAY (N5) TO DARK GRAY (N4)

1 mm

30°

10 mm

VOID WITH RUBBLE

BOX 48

FINE TO MEDIUM GRAINED BASALT, DARK GRAY (N4) FEW VESICLES GREATER THAN 1 mm

VERY FRACTURED

INCREASE IN VESICLE SIZE TO 1-3 mm

1 mm

1 mm

1 mm

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 43 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08	Logged By: B. Bragdon	Checked By: K. Esposito								
Total Depth (ft): 730.5	Depth to Water (ft):	Northing: 698,178.53	Vertical Angle:								
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux	Easting: 584,480.21	Azimuth:								
Drill Rig: Rotary Core	Core Barrel: HQ x 5'	Ground Elev.: 5176.32									
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-462											
-463											
-464											
-465											
-466	95		5.0/5.0 (100%)	4.5/5.0 (90%)							
-467											
-468											
-469											
-470	96		5.0/5.0 (100%)	2.9/5.0 (58%)							
-471											
-472											

GRADIENTS TO MEDIUM GRAINED BASALT, DARK GRAY (N4) VESICLES 3-8 mm WITH CINDERS OF DUSKY RED (10R 3/2)

CINDERS (20 cm) DUSKY RED (10R 3/2)

GRADIENTS TO FINE GRAINED BASALT, DARK GRAY (N4), FEW VESICLES OVER 1 mm VERY BROKEN LOCALLY

INCREASE IN VESICLES SIZE TO 1-5 mm

VESICULAR BASALT, WITH VESICLES UP TO 10 mm GENERALLY 2-6 mm DARK GRAY (N4) WITH DUSKY RED (10R 3/2) IN VESICLES

BOX 49

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

ROCK BORING LOG

Rock Boring Log Data							Hole No.: GW-1		
							Sheet No.: 44 of 67		
							Job No.: 1005746		
Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito		
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:			
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:			
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32				
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-473									
-474									
-475		97	1.0/1.0 (100%)	1.0/1.0 (100%)					
-476		98	3.7/4.0 (74%)	3.3/4.0 (66%)					
-477									
-478									
-479									
-480		99	5.0/5.0 (100%)	4.0/5.0 (80%)					
-481									
-482									
-483									

BOX 50

BOX 51

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 45 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08			Logged By: B. Bragdon			Checked By: K. Esposito				
Total Depth (ft): 730.5	Depth to Water (ft):			Northing: 698,178.53			Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux			Easting: 584,480.21			Azimuth:				
Drill Rig: Rotary Core	Core Barrel: HQ x 5'			Ground Elev.: 5176.32							
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-484											
-485											
-486	100		5.0/5.0 (100%)	4.8/5.0 (98%)				1 mm	FINE GRAINED OLIVINE BASALT, DARK GRAY (N4) WITH FEW VESICLES 1-2 mm		4/26/08
-487											
-488									GRADES TO LARGER VESICLES OF 5-10 mm		
-489									20-25 mm VOID WITH CINDERS, RED (10R 4/6)		
-490	101		5.0/5.0 (100%)	4.6/5.0 (92%)				2-3 mm	VESICULAR OLIVINE BASALT, DARK GRAY (N4) WITH TRACE RED (10R 4/6) LOCALLY VESICLES 2-5 mm		
-491								2 mm			
-492								4 mm			
-493								3 mm			
-494								1 mm			
								3 mm			
								0-10°	VERY FRACTURED		
										BOX 52	

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 46 of 67				
							Job No.: 1005746				
Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-495											
-496		102	5.0/5.0 (100%)	3.3/5.0 (66%)					VESICULAR BASALT, DARK GRAY (N4) WITH SOME WEAK RED (10R 4/3) VESICLES UP TO 10 mm GENERALLY 2-5 mm, VERY FRACTURED 496.5-498.5'		
-497											
-498											
-499											
-500											
-501		103	5.0/5.0 (100%)	3.3/5.0 (66%)					LARGER VESICLES FROM 501-504', UP TO 10 mm, GENERALLY 2-5 mm WITH CINDERS OF WEAK RED (10R 4/3)	BOX 53	
-502											
-503											
-504											
-505		109	5.0/5.0 (100%)	4.8/5.0 (96%)					GRADES TO VERY FINE GRAINED BASALT, DARK GRAY (N4) WITH SOME DUSKY RED (10R 3/4) ALONG FRACTURES		

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Rock Boring Log Data							Hole No.: GW-1				
							Sheet No.: 47 of 67				
							Job No.: 1005746				
Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-506											
-507											
-508									GRADES TO GRAY (N5)		
-509											
-510	110		5.0/5.0 (100%)	3.3/5.0 (66%)				5-10 mm	WITH CINDERS OF WEAK RED (10R 4/4)		
-511									VESICULAR BASALT, DARK GRAY (N4), VESICLES 2-8 mm	BOX 54	
-512								1 mm			
-513									GRADES TO DUSKY RED (10R 3/3)		
-514								40 mm	VOID WITH CINDERS BLACK (N2.5) WITH SOME IRIDESCEENCE LOCALLY		
-515	111		5.0/5.0 (100%)	5.0/5.0 (100%)				20 mm	VESICULAR BASALT, DARK GRAY (N4), VESICLES UP TO 10 mm GENERALLY 2-5 mm		
-516									10x20 mm VOID		
									10x40 mm VOID		

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Project: Areva Feature: Core Log							Hole No.: GW-1				
							Sheet No.: 48 of 67				
							Job No.: 1005746				
Date Started: 4/21/08			Date Completed: 5/8/08			Logged By: B. Bragdon	Checked By: K. Esposito				
Total Depth (ft): 730.5			Depth to Water (ft):			Northing: 698,178.53	Vertical Angle:				
Drilling Contr.: Crux Subsurface, Inc.			Driller: Brandon Gereaux			Easting: 584,480.21	Azimuth:				
Drill Rig: Rotary Core			Core Barrel: HQ x 5'			Ground Elev.: 5176.32					
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-517											
-518											
-519											
-520		112	5.0/5.0 (100%)	4.7/5.0 (94%)							
-521											
-522											
-523											
-524											
-525		113	5.0/5.0 (100%)	4.6/5.0 (92%)							
-526											
-527											

1005746D012-A.dwg

GRADE TO FINE GRAINED BASALT, DARK GRAY (N4) WITH 1-3 mm VESICLES, GENERALLY 1 mm

BASALT, AS ABOVE WITH TRACE DUSKY RED (10R 3/2) LOCALLY ALONG FRACTURES

FEW VUGS UP TO 10 mm

BOX 55

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 49 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-528											
-529											
-530		114	5.0/5.0 (100%)	5.0/5.0 (100%)					VESICULAR BASALT, DARK GRAY (N4) FINE GRAINED, 1-3 mm VESICLES		
-531									FEW VUGS TO 8 mm	BOX 56	
-532									VOID		
-533									GRADES TO MEDIUM GRAINED BASALT, DARK GRAY (N4) TO BLACK (N2.5) WITH VESICLES		
-534									5-10 mm CINDERS RED (10R 4/6) COATING AND IN FRACTURE		
-535		115	5.0/5.0 (100%)	4.1/5.0 (82%)					BB		
-536									GRADES TO FINE GRAINED BASALT. WITH VESICLES 1-2 mm		
-537											
-538									GRADES TO MEDIUM GRAINED BASALT, WITH VESICLES		

1005746D012-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 50 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-539											
-540		116									
-541			5.0/5.0 (100%)	2.7/5.0 (54%)							BOX 57
-542											
-543											
-544											
-545		117	5.0/5.0 (100%)	5.0/5.0 (100%)							
-546											
-547											
-548											
-549											BOX 58

1005746D012-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 51 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
550											
-551		118	5.0/5.0 (100%)	4.9/5.0 (98%)							
-552											
-553											
-554											
-555											
-556		119	4.9/5.0 (98%)	4.6/5.0 (92%)							
-557											
-558											
-559											
-560		120	5.1/5.0 (102%)	4.8/5.0 (96%)							
1005746D013-A.dwg											



## ROCK BORING LOG

Project: Areva


**Feature: Core Log**

Hole No.: GW-1

Sheet No.: 52 of 67

Job No.: 1005746

Date Started: 4/21/08			Date Completed: 5/8/08			Logged By: B. Bragdon		Checked By: K. Esposito	
Total Depth (ft): 730.5			Depth to Water (ft):			Northing: 698,178.53		Vertical Angle:	
Drilling Contr.: Crux Subsurface, Inc.			Driller: Brandon Gereaux			Easting: 584,480.21		Azimuth:	
Drill Rig: Rotary Core			Core Barrel: HQ x 5'			Ground Elev.: 5176.32			
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	
561								Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)	
562									
563									
564									
565									
566		121	4.9/5.0 (98%)	2.3/5.0 (46%)					
567									
568									
569									
570		122	5.0/5.0 (100%)	4.7/5.0 (94%)					
571									



**MWH**


Project: Areva  
Feature: Core Log


ROCK BORING LOG

Hole No.: GW-1  
Sheet No.: 54 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
583											
-584									HORIZONTAL VUGS/VESICLES		
-585	125		5.0/5.0 (100%)	5.0/5.0 (100%)				5 mm		4/27/08	
-586									FINE GRAINED BASALT, DARK GRAY (N3), VESICLES LESS THAN 1 mm, FEW VUGS AND HORIZONTAL VESICLES WITH HORIZONTAL VUGS/VESICLES	BOX 62	
-587											
-588											
-589											
-590	126										
-591			5.0/5.0 (100%)	5.0/5.0 (100%)					HORIZONTAL VUGS VESICULATED BASALT, <1 mm 20° FRACTURE OFF VERTICAL FRACTURE		
-592									FRACTURE 2-3 mm		
-593											

1005746D013-A.dwg





1005746D013-A.dwg

**MWH**


Project: Areva  
Feature: Core Log

ROCK BORING LOG

Hole No.: GW-1  
Sheet No.: 57 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
616											
617											
618											
619											
620	132										
621			5.0/5.0 (100%)	4.6/5.0 (92%)							
622											
623											
624	133										
625			5.0/5.0 (100%)	4.2/5.0 (84%)							
626											

1005746D013-A.dwg



**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1		
							Sheet No.: 59 of 67		
							Job No.: 1005746		
Date Started: 4/21/08	Date Completed: 5/8/08			Logged By: B. Bragdon			Checked By: K. Esposito		
Total Depth (ft): 730.5	Depth to Water (ft):			Northing: 698,178.53			Vertical Angle:		
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux			Easting: 584,480.21			Azimuth:		
Drill Rig: Rotary Core	Core Barrel: HQ x 5'			Ground Elev.: 5176.32					
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-638									
-639									
-640	136								
-641									
-642							2-5 mm VESICLES		
-643									
-644									
-645	137		5.0/5.0 (100%)	5.0/5.0 (100%)	3.2/5.0 (64%)				4/28/08
-646									
-647							WITH HORIZONTAL VESICLES UP TO 5 mm		
-648									

1005746D013-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 60 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
*649											
-650		138	1.0/1.0 (100%)	0.6/1.0 (60%)							
-651		139	4.0/4.0 (100%)	3.4/4.0 (85%)							
-652											
-653											
-654											
-655		140	1.0/1.0 (100%)	1.0/1.0 (100%)							
-656		141	1.0/1.0 (100%)	1.0/1.0 (100%)							
-657		142	3.0/3.0 (100%)	3.0/3.0 (100%)							
-658											
-659											

Very Fine Grained Olivine Basalt, Dark Gray (N4) Vesicles of 1 mm

AS ABOVE

With Weak Red (10R 4/3) Along Fracture

BOX 69

BOX 70

1005746D013-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

Hole No.: GW-1  
Sheet No.: 61 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
660											
661		143	5.0/5.0 (100%)	5.0/5.0 (100%)					VERY FINE GRAINED BASALT, DARK GRAY (N4) TRACE VESICLES GREATER THAN 1 mm, GENERALLY LESS THAN 1 mm		
662							85°	1 mm			
663											
664											
665		144							WITH TRACE 5 mm VESICLES		
666											
667									WITH FEW 5-10 mm VESICLES FRACTURED TO RUBBLE WITH TRACE CINDERS OF WEAK RED (10R 4/4)		
668									FINE TO MEDIUM GRAINED BASALT, WEAK RED (10R 4/2), VESICLES 5-10 mm, SOME PHENOCRYSTS	BOX 71	
669											
670		145	5.0/5.0 (100%)	5.0/5.0 (100%)				85°	1 mm	GRADES TO DARK GRAY (N4) WITH FEW VESICLES UP TO 10 mm, GENERALLY 1-3 mm	

1005746D014-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

**ROCK BORING LOG**

ROCK BORING LOG							Hole No.: GW-1				
							Sheet No.: 62 of 67				
							Job No.: 1005746				
Date Started: 4/21/08	Date Completed: 5/8/08		Logged By: B. Bragdon		Checked By: K. Esposito						
Total Depth (ft): 730.5	Depth to Water (ft):		Northing: 698,178.53		Vertical Angle:						
Drilling Contr.: Crux Subsurface, Inc.	Driller: Brandon Gereaux		Easting: 584,480.21		Azimuth:						
Drill Rig: Rotary Core	Core Barrel: HQ x 5'		Ground Elev.: 5176.32								
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-671								2 mm			
-672								1 mm			
-673								1 mm			
-674								1 mm			
-675									FINE GRAINED BASALT, DARK GRAY (N4) VESICLES 1 mm OR LESS		
-676	146		5.0/5.0 (100%)	4.8/5.0 (96%)					WITH FEW VESICLES UP TO 10 mm		
-677											
-678										BOX 72	
-679											
-680	147		5.0/5.0 (100%)	2.5/5.0 (50%)					RUBBLE WITH SOME WEAK RED (10R 4/4)		
-681									GRADES TO DARK REDDISH GRAY (10Y 4/1) WITH VESICLES OF UP TO 2 mm		

1005746D014-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 63 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/Foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-682											
-683											
-684											
-685		148	5.0/5.0 (100%)	2.9/5.0 (58%)							
-686											
-687											
-688											
-689											
-690		149	5.0/5.0 (100%)	4.3/5.0 (86%)							
-691											
-692											

1005746D014-A.dwg

**MWH**

Project: Areva  
Feature: Core Log

ROCK BORING LOG

Hole No.: GW-1  
Sheet No.: 64 of 67  
Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-693								0-10°			
-694								2-3 mm			
-695	150		5.0/5.0 (100%)	3.8/5.0 (76%)				50°	BASALT, GRADES TO DARK GRAY (N4) WITH WEAK RED (10R 4/2) ALONG FRACTURES		
-696								20°			
-697								70°	RUBBLE WEAK RED (10R 4/2)		
-698								30°			
-699								40°	RUBBLE	BOX 74	
-700	151							30°			
-701			5.0/5.0 (100%)	5.0/5.0 (100%)				80°	VUGS/VOIDS UP TO 15 mm		
-702								90°	2 x 35 mm VOID		
-703								70°	FINE GRAINED BASALT, DARK GRAY (N4) WITH VUGS/VOIDS UP TO 15 mm		
								1 mm	1 mm		
								2 mm	10 x 30 mm VOID		

1005746D014-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 65 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-704											
-705		152	4.8/5.0 (96%)	4.8/5.0 (96%)					WITH VUGS AND VOIDS UP TO 15 mm	4/29/08	
-706									VESICULATED BASALT, WITH VESICLES UP TO 20 mm	BOX 75	
-707											
-708											
-709											
-710		153									
-711			5.0/5.0 (100%)	1.0/5.0 (20%)					HIGHLY FRACTURED BASALT, HORIZONTAL AND VERTICAL FRACTURES		
-712											
-713											
-714											

1005746D014-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 66 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito				
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:					
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:					
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32						
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure	Fracture Spacing	Lithologic Descriptions	Packer Test	Notes and Observations (Sample / Test Data, Water Levels, Drilling Characteristics, Casing Depths, Core Box No.)
-715											
-716		154	5.0/5.0 (100%)	1.0/5.0 (20%)					HIGHLY FRACTURED BASALT, FRACTURE 1-2 mm		BOX 76
-717											
-718											
-719											
-720											
-721		155	5.0/5.0 (100%)	4.5/5.0 (90%)					SLIGHTLY VESICULAR BASALT, WITH VESICLES GENERALLY 1 mm		
-722											
-723											
-724											
-725		156	5.0/5.0 (100%)	2.5/5.0 (50%)							

1005746D014-A.dwg



MWH

Project: Areva  
Feature: Core Log

## ROCK BORING LOG

Hole No.: GW-1

Sheet No.: 67 of 67

Job No.: 1005746

Date Started:	4/21/08	Date Completed:	5/8/08	Logged By:	B. Bragdon	Checked By:	K. Esposito
Total Depth (ft):	730.5	Depth to Water (ft):		Northing:	698,178.53	Vertical Angle:	
Drilling Contr.:	Crux Subsurface, Inc.	Driller:	Brandon Gereaux	Easting:	584,480.21	Azimuth:	
Drill Rig:	Rotary Core	Core Barrel:	HQ x 5'	Ground Elev.:	5176.32		
Depth (ft)	Elevation (ft)	Run No.	Recovery (%)	RQD (%)	Fractures/foot	Lithology (Graphic Symbol)	Structure
-726							
-727							
-728							
-729							
-730							
-731							
-732							
-733							
-734							
-735							
-736							

1005746D014-A.dwg

## **8.0 LABORATORY RESULTS**

### **8.1 NOVEMBER 2007 RESULTS**

- Summary Table
- Atterberg Limits
- Grain Size Analysis
- Grain Size Analysis with Hydrometer
- Consolidation

Specific Gravity	ASTM D854-06
Natural Moisture Content	ASTM D2216-98
Natural Dry Density	ASTM D2216-98
Grain Size Analysis	ASTM D422-63R02
Atterberg Limits	ASTM D4318-00
Consolidation	ASTM D2435-02
Proctor Compaction (Modified)	ASTM D1557-02
Resistance R-Value	ASTM D2844-01
Water Soluble Sulfate	AASHTO T290-95-UL (2003)
Resistivity	AASHTO T288-91-UL (2004)
pH	AASHTO T289-91-UL (2004)

## SUMMARY OF LABORATORY TEST RESULTS

Terracon Project No. 200075108


**Notes:** *Ward's*, *Ward's Counter* and *Swell Counter* values obtained from undisturbed samples unless otherwise noted.


Initial Water  
Initial Dry Density, Initial Water  
\* = Partially disturbed sample  
- = Compression/settlement  
NIV = no value  
NP = non-plastic

## REMARKS

- Remolded Compacted density (approximately 95% of ASTM D698 maximum density near optimum)
  - Remolded Compacted density (approximately 95% of ASTM D1557 maximum density near optimum)
  - Submerged to approximate saturation
  - Dry density and/or moisture content determined from one ring of a multi-ring sample
  - Visual Classification
  - Minus #200 Only

**terracon**








301 North Howes Street  
Fort Collins, Colorado 80521  
(970) 484-0359 FAX (970) 484-0454

CLIENT: MWH  
PROJECT:  
PROJECT LOCATION:  
SAMPLE LOCATION: BH-5 @ 5'

SAMPLED BY: Client  
DATE RECEIVED: 3-Dec-07  
REPORT DATE: 10-Dec-07  
PROJECT NO: 20075108




SAMPLE LOCATION	SOIL CLASSIFICATION		MC%	LL	PI	Cc	Cu	
BH-5 @ 5'	CL		NR	29	13	1.94	25.90	
SAMPLE LOCATION	D100	D60	D30	D10	% GRAVEL	% SAND	% SILT	
BH-5 @ 5'	9.500	0.033	0.009	0.001	0.2	6.0	72.7	21.1



301 North Howes Street  
Fort Collins, Colorado 80521  
(970) 484-0359 FAX (970) 484-0454

CLIENT: MWH  
PROJECT:  
PROJECT LOCATION:  
SAMPLE LOCATION: BH-18 @ 5.5'


SAMPLED BY: Client  
DATE RECEIVED: 3-Dec-07  
REPORT DATE: 10-Dec-07  
PROJECT NO: 20075108



SAMPLE LOCATION	SOIL CLASSIFICATION	MC%	LL	PI	Cc	Cu
BH-18 @ 5.5'	CL	NR	31	14	#N/A	#N/A

SAMPLE LOCATION	D100	D60	D30	D10	% GRAVEL	% SAND	% SILT	% CLAY
BH-18 @ 5.5'	9.500	0.020	0.004	#N/A	0.4	8.6	58.5	32.5



TC CONSOL STRAIN 20045108.GPJ TERRACON TEST GDT 12/4/07


Specimen Identification	Classification	$\gamma_d$ , pcf	WC, %
● BH 12 10.5ft	LEAN CLAY(CL)	88	12

Notes:

**Terracon**

#### SWELL CONSOLIDATION TEST

Project: Laboratory Testing  
 Site: Fort Collins, Colorado  
 Job #: 20075108  
 Date:



TC CONSOLIDATION TEST 20045108.GPJ TERRACON TEST.GDT 12/10/07

Specimen Identification	Classification	$\gamma_d$ ,pcf	WC, %
● BH 12 10.5ft	LEAN CLAY(CL)	88	12

Notes:

#### CONSOLIDATION TEST

**Terracon**

Project: Laboratory Testing  
Site: Fort Collins, Colorado  
Job #: 20075108

## **8.0            LABORATORY RESULTS**

### **8.2            MAY 2008 RESULTS**

- Summary Table
- Atterberg Limits
- Consolidation
- Proctor Compaction
- Resistance R-Value

Specific Gravity	ASTM D854-06
Natural Moisture Content	ASTM D2216-98
Natural Dry Density	ASTM D2216-98
Grain Size Analysis	ASTM D422-63R02
Atterberg Limits	ASTM D4318-00
Consolidation	ASTM D2435-02
Proctor Compaction (Modified)	ASTM D1557-02
Resistance R-Value	ASTM D2844-01
Water Soluble Sulfate	AASHTO T290-95-UL (2003)
Resistivity	AASHTO T288-91-UL (2004)
pH	AASHTO T289-91-UL (2004)


Borehole	Depth	Liquid Limit	Plasticity Index	% < #200 Sieve	AASHTO Classification	USCS Classification	Water Content (%)	Dry Unit Weight (pcf)	Swell (%) / Shrinkage (psi)	Unconfined Compressive Strength (psf)	Water Soluble Sulfate (ppm)	Resistivity (Ohm-Cm)	pH	Oxidation Reduction Potential	Specific Gravity
22	5.0														
23	1.0	36	12	89	A-6	CL	16.3								
23	5.0	33	14	87	A-6	CL					100	1229	8.36	2.69	
25	5.5	42	24	86	A-7-6	CL	14.9				1700	245	8.36	2.70	
28	5.0						10.6								
29	5.5						13.0	81.2	-3.0/500						
29	10.0						16.0								
30	5.5	35	16	97	A-6	CL	10.7	90.4	-0.4/500						
30	10.5						12.7								
30	15.5						14.7								
30	20.5						19.0								


PC LAB SUMMARY 2007108.GPJ BORING 022208.GDT 6/17/08

**Terracon**

**SUMMARY OF LABORATORY RESULTS**

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108  
 Date: 6-17-08





TC CONSOL STRAIN 20075108.GPJ BORING.GDT 6/13/08


Specimen Identification	Classification	$\gamma_d$ , pcf	WC, %
● 29 5.5ft	LEAN CLAY (CL)	81	13

Notes:

**Terracon**

#### SWELL CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108  
 Date:




TC CONSOL STRAIN 20075108.GPJ BORING.GDT 6/1/08

Specimen Identification		Classification		$\gamma_d$ ,pcf	WC,%
●	30	5.5ft	LEAN CLAY(CL)	90	11

Notes:

**Terracon**

**SWELL CONSOLIDATION TEST**  
 Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108  
 Date:



TC CONSOL VOID RATIO 20075108.GPJ BORING GDT 6/13/08


Specimen Identification		Classification		$\gamma_d$ , pcf	WC, %
●	29 5.5ft	LEAN CLAY (CL)		81	13

Notes:

**Terracon**

#### CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108




Specimen Identification		Classification		$\gamma_d$ ,pcf	WC, %
●	30	5.5ft	LEAN CLAY(CL)	90	11

Notes:

**Terracon**

#### CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108



TC CONSOL STRAIN 20075108.GPJ BORING.GDT 6/13/08


Specimen Identification	Classification	$\gamma_d$ , pcf	WC, %
● 29 5.5ft	LEAN CLAY (CL)	81	13

Notes:

**Terracon**

#### SWELL CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108  
 Date:



TC CONSOL STRAIN 20075108.GPJ BORING.GDT 6/1/08


Specimen Identification		Classification		$\gamma_d$ ,pcf	WC, %
●	30	5.5ft	LEAN CLAY(CL)	90	11

Notes:

**Terracon**

#### SWELL CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108  
 Date:



TC CONSOL VOID RATIO 20075108.GPJ BORING GDT 6/13/08


Specimen Identification		Classification		$\gamma_d$ ,pcf	WC, %
●	29 5.5ft	LEAN CLAY (CL)		81	13

Notes:

**Terracon**

#### CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108




Specimen Identification		Classification		$\gamma_d$ ,pcf	WC, %
●	30	5.5ft	LEAN CLAY(CL)	90	11


Notes:

**Terracon**

#### CONSOLIDATION TEST

Project: AREVA Idaho Falls Site-Laboratory Testing  
 Site: AREVA Idaho Falls Site Idaho Falls, Idaho  
 Job #: 20075108







301 North Howes Street  
FORT COLLINS, COLORADO 80521  
(970) 484-0359 FAX (970) 484-0454

**RESISTANCE R-VALUE & EXPANSION  
PRESSURE OF COMPACTED SOIL  
ASTM D2844**

CLIENT:  
PROJECT:  
LOCATION:  
TERRACON NO.

MWH  
AREVA Idaho Falls Project  
BH23 @ 1'  
20075108

DATE OF TEST: 29-May-08


CLASSIFICATION: lean clay (CL)

**SAMPLE DATA TEST RESULTS**

TEST SPECIMEN NO.	1	2	3
COMPACTION PRESSURE (PSI)	80	145	230
DENSITY (PCF)	104.9	109.5	110.7
MOISTURE CONTENT (%)	21.6	19.0	18.2
EXPANSION PRESSURE (PSI)	-0.31	-0.12	-0.16
HORIZONTAL PRESSURE @ 160 PSI	136	130	127
SAMPLE HEIGHT (INCHES)	2.64	2.56	2.56
EXUDATION PRESSURE (PSI)	150.4	241.8	316.6
CORRECTED R-VALUE	9.8	13.5	17.8
UNCORRECTED R-VALUE	9.2	13.2	17.4

R-VALUE @ 300 PSI EXUDATION PRESSURE =

17





301 North Howes Street  
FORT COLLINS, COLORADO 80521  
(970) 484-0359 FAX (970) 484-0454

**RESISTANCE R-VALUE & EXPANSION  
PRESSURE OF COMPACTED SOIL  
AASHTO T-190**

CLIENT: MWH DATE OF TEST: 29-May-08  
PROJECT: AREVA Idaho Falls Project  
LOCATION: BH23 @ 5'  
TERRACON NO. 20075108 CLASSIFICATION: lean clay (CL)

**SAMPLE DATA TEST RESULTS**

TEST SPECIMEN NO.	1	2	3
COMPACTION PRESSURE (PSI)	85	170	220
DENSITY (PCF)	105.4	110.3	111.8
MOISTURE CONTENT (%)	21.0	18.6	18.2
EXPANSION PRESSURE (PSI)	-0.31	-0.31	-0.31
HORIZONTAL PRESSURE @ 160 PSI	139	129	123
SAMPLE HEIGHT (INCHES)	2.61	2.54	2.52
EXUDATION PRESSURE (PSI)	200.5	286.4	326.2
CORRECTED R-VALUE	8.8	14.6	19.0
UNCORRECTED R-VALUE	8.5	14.6	19.0

R-VALUE @ 300 PSI EXUDATION PRESSURE =

16

