

Legend

- Limits of Grout Curtain
- ⊕ Existing Monitoring Well Couplet (Shallow and Deep Bedrock)

D-03




Figure 3 - Existing Monitoring Wells and Grout Curtain

Davis-Besse Nuclear Power Station,
Oak Harbor, OH



\\c:\erms\GIS\Drawings\Monitoring\Figures\3 - October 2006