Fission Product Barriers

- Containment
  - Local Leak Rate Test results (PNSC)
  - SGR containment opening plan
    - Full ILRT
  - Concrete cracking identified during hydro demolition
    - Planar delamination in horizontal tendon plane
    - 3 Phase Plan to address following initial characterization and scoping:
      1. Mode 6 current operability of liner
         - NCON – SGR Engineering / Sargent & Lundy (S&L)
      2. Assess load bearing capacity to support SG lifting device
         - SGR Engineering / S&L / MPR / Bechtel
         - EC change – PNSC review
      3. Establish Mode 4 operability
         - Pri 1 Root Cause INV – CR3 Engineering / S&L / CES

19 NGG Progress Energy

Horizontal Tendon Cross Section

20 NGG Progress Energy

P/91