

## PITTSBURGH TESTING LABORATORY

ROTABLISHED IBBI

## PITTSBURGH, PA.

AS A MUTUAL PROTECTION TO CLIENTS. THE PUBLIC AND DURSELVES, ALL REPORTS ARE SUSMITTED AS THE CONFIDENTIAL PROPERTY OF CLIENTS, AND AUTHORIZATION FOR PUBLICATION OF STATEMENTS, CONCLUSIONS OR SYTRACTS FROM OR RESARDING OUR REPORTS IS RESERVED PENDING OUR WRITTEN APPROVA

Order No	. ТА-7732
Report N	0
Date	7-28-72

## REPORT

## of CONCRETE PLACEMENT

Arch-Engine		VER PLANT UNIT NO. 3 oncrete, Inc.			
Location:		Pour # 528 RB		Date _	25 July 72
SUBGRADE II	NSPECTION: N/A				
JOINT PREPA	ARATION: CIL				
FORMS: Property Control Free From Seams Tig Clean Proper Sho Alignment	Holes 📝	REINFORCEMENTS: Proper Clearance Proper Support Clean No. Tie Rods Location Tie Rods	OK OK		ravin;s
EQUIPMENT:					
No. & Size	e of Vibrators	6 - 10	,500 Freque	ncy Plus	
Placement	t Equipment	2 - 6"	Whitney Co	oncrete Pumps	
Tremie Pir	pes - Number	I/A Size	N/A	Location	N/A
PLACEMENT:	,				
Consolida	ation Procedure	Mecha	nical Vibra	ecton	
Grouted	N/A	Time	N/A	Location	N/A
Concrete	- Lift Depth	13" Max.	Direction	of Pour S.뭐.	to N.E.
REMARKS:	EXCEPTIONS: Fig	mal cleanup, removel	of excess	water. Both Sten	s corrected prior
	to placement of	concrete.			
<u> </u>					
2 - Florida 1 - PTL -	W. T. Hurst E.J. 1	oots  ANISLEY P.E		PITTSBURGH TESTING	ا المستعمل المستعمل المستعمل المستعمل ال