

10

54/10  
P/45

10/25

TA #16

BL 2/8/02  
CRACK ON LEFT RIGHT EDGE OF WALL. CRACK  
BEGAN 22" FROM RIGHT EDGE AND CONTINUED  
FOR 68"

#47

