



plant status daily archives

enter daily plant status

safe in

Oconee Information for 09/04/2009 (Modify/Update)

Outside of Scope

Outside of Scope

Significant TS / Issues:

ASW PIPING LEAK: Work continues on the excavation phase of the restoration of the ASW system to address the OBDN condition. Excavation down to the point where the new piping will come through the SSF wall as and connect to the existing ASW piping is in progress using shoring to protect the workers. Fabrication of the replacement piping is in progress. The current schedule shows installation of the new piping and exiting the OBDN status on or around 9/17/09.

Outside of Scope

Outside of Scope
C/8

Information in this record was deleted in accordance with the Freedom of Information Act.
Exemptions: Outside of Scope
FOIAPA 2-11-00 21

Outside of Scope

Outside of Scope

Outside
of
Scope