



plant status daily archives enter daily plant status in

Oconee Information for 09/10/2009 (Modify/Update)

Outside of Scope

Outside of Scope

Significant TS / Issues:

Exterior Core Bore was completed yesterday and holes are plugged/caulked. The attached photos show the three holes through the exterior wall of the SSF after being sealed and the device used to seal the holes once the core bores were completed. The RI's looked at the sealing process to ensure the SSF was appropriately protected from external flooding once the wall was breached. Excavation to uncover existing ASW Piping will begin today in preparation for tie-in and is expected to take 3 days to complete. The licensee has established contingencies to quickly refill the hole to cover the ASW piping once less than 4.5' of soil covers the pipe in the event of a tornado through the use of prestaged trucks with sand and steel plates. The residents are following.

9:15 mtg. Yes No

delete
Core Drills 003.jpg

delete
Core Drills 001.jpg


[add attachment](#)

Information in this record was deleted in accordance with the Freedom of Information Act Exemptions 2011-0021 FOIA/PA

c/11

Outside of Scope

Outside of Scope



Outside
of
Scope

