

r2

Outside of Scope



plant status daily archives enter daily plant status saf in

Oconee Information for 09/21/2009 (Modify/Update)

Outside of Scope

Outside of Scope

Information in this record was deleted in accordance with the Freedom of Information Act Exemptions
 FOIA/PA 2011-01021
 Outside of Scope

Risk Significant / Emergent Activities:

9/17

Work on the ASW piping replacement was impacted by the severe weather this weekend (heavy rain). Little additional excavation was performed; however, the three pipes through the outer wall in the SSF were installed. All of the piping is in-place inside of the building and final fit-up and welding will take place over the next two days. Eric Michel has provided the RI's with several codes that apply to the planned tie-in work this week regarding the coating of pipes and protection of the buried sections. This will be discussed with the project leads and inspected in the field.

Outside of Scope

outside of scope

(Attached photo shows the new piping coming through the SSF outer wall - penetrations have been sealed to prevent water intrusion)

9:15 mtg. Yes No

 delete

ASW Piping thru SSF wall.jpg

[add attachment](#)

Findings and Observations:

Resident Issue Summary:

=====

We are drafting up the following issues for this inspection report (2009-004) and should have files in for review shortly:

Outside of Scope

Outside of Scope

4) 10CFR50.65(a)(4) issue: Tied to the removal of the SSF from service due to the ASW leak and deficiencies in what equipment was protected during that time. Awaiting risk values from General Office to process and draft up issue in terms of SDP color. Licensee understands the issue and is working with the GO to get us what we need to process.

Outside of Scope

Outside of Scope

Outside of Scope

Outside of Scope

Outside
of
Scope

