



Material Testing Group

36 River Street, Bridgeport, CT 06604 • Phone (203) 362-1552 • Fax: (203) 362-1554 • [www.haks.net](http://www.haks.net)

January 7, 2011

Craig Z. Gordon  
United States Nuclear Regulatory Commission  
Division of Nuclear Materials Safety  
Region 1  
475 Allendale Road  
King of Prussia, PA 19406

*03038262/201001*

**RE: FOLLOW-UP TO ON SITE EVALUATION AND DISCUSSION  
License No. 06-31405-01**

Dear Mr. Gordon;

Based on our discussion concerning the transport boxes containing the Troxler nuclear gauges, we have taken the follow action to correct any possible deficiencies. All four boxes were taken to QC Resources for installation of new clasps and loops. Each box now contains two exterior locks as well as trigger locks. The eye bolts previously installed for security purposes have been removed and the holes filled with epoxy waterproof sealant. Upon my discussions with engineers at Troxler, it was recommended to fill these holes for the purpose of ensuring there would be no chance of moisture intrusion. They referred me to Title 49 to ensure the boxes integrity was not compromised in any way. At this time, we believe that the boxes are satisfactory based on Title 49 and the recommendations of Troxler engineers. I have attached photos of the boxes with the new locks and the filled holes. Look for the small white dots on the case and that is the epoxy. We hope that this will satisfy your requirements and as always we look forward to any suggestions that you may have. Thank you.

Respectfully submitted,

Neil T. Russo, RSO  
HAKS Engineers, P.C.  
36 River St.  
Bridgeport, CT 06604  
203-362-1552

2011 JAN 21 AM 11: 17  
RECEIVED  
REGION 1