## PMComanchePeakPEm Resource

**From:** Otto, Ngola
**Sent:** Tuesday, April 12, 2011 10:23 AM
**To:** Woodlan, Don
**Cc:** ComanchePeakCOL Resource; Monarque, Stephen; LaVera, Ronald
**Subject:** FW: Comanche Peak Chapter 12 Question

Don,

Figure 12.3-1R, “Radiation Zones for Normal Operation/Shutdown Site”, Sheet 1 of 34.

Ngola

---

**From:** Otto, Ngola
**Sent:** Tuesday, April 12, 2011 10:20 AM
**To:** Woodlan, Don
**Cc:** ComanchePeakCOL Resource; Monarque, Stephen; LaVera, Ronald
**Subject:** Comanche Peak Chapter 12 Question

Don,

Figure 12.3-1R shows a Maintenance Building. I there a description in the FSAR for this building and its usage?

Thank you

Ngola Otto
Project Manager, US-APWR Projects Branch
Division of New Reactor Licensing
Office of New Reactors
(301) 415-6695

**Hearing Identifier:** ComanchePeak_COL_Public
**Email Number:** 1302

**Mail Envelope Properties** (6566BAEC3DB131438196538652 4904EC0257A82658)

**Subject:** FW: Comanche Peak Chapter 12 Question
**Sent Date:** 4/12/2011 10:22:31 AM
**Received Date:** 4/12/2011 10:22:44 AM
**From:** Otto, Ngola

**Created By:** Ngola.Otto@nrc.gov

**Recipients:**
"ComanchePeakCOL Resource" <ComanchePeakCOL.Resource@nrc.gov>
Tracking Status: None
"Monarque, Stephen" <Stephen.Monarque@nrc.gov>
Tracking Status: None
"LaVera, Ronald" <Ronald.LaVera@nrc.gov>
Tracking Status: None
"Woodlan, Don" <Donald.Woodlan@luminant.com>
Tracking Status: None

**Post Office:** HQCLSTR02.nrc.gov

| **Files** | **Size** | **Date & Time** |
|---|---|---|
| MESSAGE | 607 | 4/12/2011 10:22:44 AM |

**Options**
**Priority:** Standard
**Return Notification:** No
**Reply Requested:** No
**Sensitivity:** Normal
**Expiration Date:**
**Recipients Received:**