

Three Mile Island Unit 1
Route 441 South, P.O. Box 480
Middletown, PA 17057

Telephone 717-948-8000

TMI-11-055

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

THREE MILE ISLAND UNIT 1 (TMI-1)
OPERATING LICENSE NO. DPR-50
DOCKET NO. 50-289

SUBJECT: REACTOR BUILDING TENDON SURVEILLANCE REPORT

Enclosed is "Topical Report Number 204, "2010 Augmented Reactor Building (IWL) In-Service Inspection", Revision 0, provides a report on the inspection results of the Post-Tensioning System and containment surface. These activities were performed in accordance with ASME Section XI, Subsection IWL, and Technical Specification 4.4.2. The report is required, by Technical Specification 4.4.2.1.6, to be submitted to the NRC within 3 months of completion.

No new regulatory commitments are established by this submittal. If any additional information is needed, please contact Mike Fitzwater at (717) 948-8228

Sincerely,



Richard W. Libra
Plant Manager

RWL/mdf

Attachments

cc: TMI-1 Senior Resident Inspector
Administrator, Region I
TMI-1 Project Manager

A001
NRR