

## **NRR-PMDAPEm Resource**

---

**From:** Stang, John  
**Sent:** Wednesday, December 15, 2010 7:38 AM  
**To:** Todd, Randall P; Meixell, Bob  
**Cc:** Kulesa, Gloria  
**Subject:** RR 10-ON-001

Please give me a call

By letter dated June 9, 2010, Duke Energy Carolinas, LLC (the licensee) submitted Request for Alternative No. 10-ON-001 related to the inspection of specified American Society of Mechanical Engineers Boiler and Pressure Vessel Code Class 2 Residual Heat Removal Heat Exchanger welds (the subject RHR HX welds) at Oconee Nuclear Station, Units 1, 2, and 3. The NRC staff determined that additional information is required to complete its evaluation of the licensee's request. The staff's request for additional information is provided below.

1. Please state whether previous inservice inspections of the RHR HXs have detected any signs of leakage or age-related degradation in the subject RHR HX welds at Oconee Nuclear Station, Units 1, 2, and 3.

John Stang  
301-415-1345

**Hearing Identifier:** NRR\_PMDA  
**Email Number:** 40

**Mail Envelope Properties** (John.Stang@nrc.gov20101215073800)

**Subject:** RR 10-ON-001  
**Sent Date:** 12/15/2010 7:38:08 AM  
**Received Date:** 12/15/2010 7:38:00 AM  
**From:** Stang, John

**Created By:** John.Stang@nrc.gov

**Recipients:**

"Kulesa, Gloria" <Gloria.Kulesa@nrc.gov>  
Tracking Status: None  
"Todd, Randall P" <Randall.Todd@duke-energy.com>  
Tracking Status: None  
"Meixell, Bob" <Bob.Meixell@duke-energy.com>  
Tracking Status: None

**Post Office:**

<b>Files</b>	<b>Size</b>	<b>Date &amp; Time</b>
MESSAGE	836	12/15/2010 7:38:00 AM

**Options**

**Priority:** Standard  
**Return Notification:** No  
**Reply Requested:** No  
**Sensitivity:** Normal  
**Expiration Date:**  
**Recipients Received:**