

HSA BUILDING FACT SHEET

Building Number / Name: 506 / Old Medical Research Lab

Current Tenant / Use: Unoccupied / None

Original / Former Use: Medical Research Lab; DCD&I Department of Hazardous Microorganisms (1984) Biological Research; Hazardous Operations (1963); Hazardous Research Laboratory (1961); Laboratory (1959)

Date of Construction: 1955

Construction Materials: reinforced concrete with brick exterior

Total Sq. Footage: 3403

Renovation Status: Interior remodeling in 1986

Floors: 1

Current Building Status: Existing, currently unoccupied, slated for renovation and future use

Sources of Information: (*References, Interviews*)

Document Reviews – CHAMMP Report, 1997; WRAIR HSA, 1997; Decommissioning/Close-out Documentation (6/8/1999)

Site Visit and Interviews – Interview with Mr. Burton

Radiological Data Summary (*RCOPCs, Impacted Room(s) / Area(s), etc.*):

- Radionuclides Used/Potential RCOPCs: Ra-226
- Potentially Impacted Rooms: back cubicle, chemical room, counting room, main lab sink
- Preliminary Dose Rate Survey (July 31, 2008): Not performed due to building inaccessibility

Current Radiological Status: Radiological close-out as of 6/8/1999

Site Visit Information: (*Date Toured, Site Contact, Security Issues*)

Site Contact – None

A tour of the building exterior was conducted on July 31, 2008 by Paul Valentinelli, Mike Barsa, Dave Burton, and Anne Delp. Building is currently unoccupied and locked. Special permission is required for access to be granted.

Preliminary MARSSIM Classification(s): Non-Impacted

Recommendations: No Further Action

Photograph(s) Taken:
(Interior was inaccessible during site visit)



Floor Plan(s) / As-built Drawing(s): See attached

