



CABRERA SERVICES
RADIOLOGICAL • ENGINEERING • REMEDIATION

June 24, 2011

Br 4

RECEIVED
REGION I
2011 JUN 27 AM 8:15

Regional Administrator
U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406
ATTN: Director, Division of Nuclear Materials Safety

03035316

RE: Completion of job activities at temporary job site utilizing U.S. NRC Radioactive Material License #06-30556-01

Dear Sir or Madam:

Cabrera Services Inc. (CABRERA) is providing this written notification regarding the completion of job activities at a temporary job site utilizing CABRERA Material License #06-30556-01 Amendment 03. The attached information is provided as required by license condition 18B.

If you should have any questions regarding this notification, please contact Henry W. Siegrist at CABRERA (860) 569-0095.

Sincerely,

Henry Siegrist, CHP, P.E.
Radiation Safety Officer

attachment

575462

NMSS/RGN1 MATERIALS-002

**ATTACHMENT
COMPLETION OF 2011 ACTIVITIES FOR
POHAKULOA TRAINING AREA
THE BIG ISLAND, HAWAII (2010)**

(NRC Mail Control 573920)

Cabrera Services, Inc. (CABRERA) provided radiological characterization and scoping surveys, and exposure rate surveys at the Pohakuloa Training Area located on the Big Island, Hawaii. Several exempt radioactive source(s) were utilized to provide daily quality control checks on radiation detection equipment.

The following information is being transmitted to you as required by condition 18B of the CABRERA Materials License.

- (1) Radiological characterization, scoping surveys, and general exposure rate surveys were provided at the site. No material exceeding limits was detected and no contaminated samples, soils, or materials were collected by Cabrera Services. No remediation work was performed.

All CABRERA onsite activities for this work evolution were completed by June 24, 2011.

- (2) No generated IDW had activity exceeding release limits as provided in the Cabrera NRC License. No radioactive materials generated by Cabrera Services remain onsite.
- (3) After completion of work activities, radiological surveys were conducted by CABRERA to ensure the absence of radioactive contamination on equipment associated with project activities. Cabrera took no possession of any radioactive materials derived from the site.
- (4) All exempt quantity check sources and standards used to provide daily QC and efficiency checks of radiological monitoring and measuring equipment were removed from the PTA Site. No CABRERA radioactive sources remain on site after June 24, 2011.

This is to acknowledge the receipt of your letter/application dated

6/24/2011, and to inform you that the initial processing which includes an administrative review has been performed.

NOTIFICATION 06-30556-01
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 575462.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.