

10 CFR 50.55a

JUN 1 7 2011

SERIAL: BSEP 11-0060

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Subject: Brunswick Steam Electric Plant, Unit No. 2 Renewed Facility Operating License No. DPR-62 Docket No. 50-324 Inservice Inspection Program Owner's Activity Report for Unit 2 Refueling Outage 19

Ladies and Gentlemen:

Enclosed is an American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Section XI, Form OAR-1, Owner's Activity Report for the Brunswick Steam Electric Plant (BSEP), Unit No. 2. The report covers inspection activities performed during BSEP, Unit 2 Refueling Outage 19 (i.e., designated as B220R1) for the first inspection period of the fourth 10-year inspection interval. The report has been prepared and is being submitted in accordance with ASME Code Case N-532-4.

No regulatory commitments are contained in this letter. Please refer any questions regarding this submittal to Mr. Lee Grzeck, Acting Supervisor - Licensing/Regulatory Programs, at (910) 457-2487.

Sincerely,

Phyper N. Mentel

Phyllis N. Mentel Manager - Support Services Brunswick Steam Electric Plant

A041

Progress Energy Carolinas, Inc. Brunswick Nuclear Plant P.O. Box 10429 Southport, NC 28461 Document Control Desk BSEP 11-0060 / Page 2

WRM/wrm

Enclosure: Form OAR-1 Owner's Activity Report for B220R1

cc (with enclosure):

U. S. Nuclear Regulatory Commission, Region II ATTN: Mr. Victor M. McCree, Regional Administrator 245 Peachtree Center Ave, NE, Suite 1200 Atlanta, GA 30303-1257

U. S. Nuclear Regulatory Commission ATTN: Mr. Philip B. O'Bryan, NRC Senior Resident Inspector 8470 River Road Southport, NC 28461-8869

U. S. Nuclear Regulatory Commission (Electronic Copy Only) ATTN: Mrs. Farideh E. Saba (Mail Stop OWFN 8G9A) 11555 Rockville Pike Rockville, MD 20852-2738

Chair - North Carolina Utilities Commission P.O. Box 29510 Raleigh, NC 27626-0510

Mr. Jack M. Given, Jr., Bureau Chief North Carolina Department of Labor Boiler Safety Bureau 1101 Mail Service Center Raleigh, NC 27699-1101

Form OAR-1 Owner's Activity Report for B220R1

Form OAR-1 OWNER'S ACTIVITY REPORT

Report Number:
Plant: Brunswick Steam Electric Plant
Unit No.: 2 Commercial Service Date: November 1975 Refueling Outage No.: B220R1
Current Inspection Interrval: Fourth
Current Inspection Period: First Period of the Fourth Interval
Edition and Addenda of Section XI applicable to the inspection plans: <u>2001 edition with 2003 addenda</u>
Date and Revision of Inspection Plans: Fourth Interval Revision 5 Feb. 2011
Edition and Addenda of Section XI applicable to Repair/Replacement activities, if different than the Inspection Plans: <u>None</u>

Code Cases used: <u>N-532-4, N-460, N-613-1, N-624, N-648-1</u>

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the Repair/Replacement activities and evaluations supporting the completion of **B220R1** conform to the requirements of Section XI.

Signed: (Owner or Owner's Designee

Date: 5/27

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of <u>NORTH</u> (<u>ALOLINA</u> and employed by <u>HSB GLOBAL STANDALDS</u> of <u>HARTFORD</u> (<u>DONNETTICULT</u> Have inspected the items described in Repair/Replacement Plan number <u>B226R1</u>, and state that, to the best of my knowledge and belief, the Owner has performed all the activities described in the Repair/Replacement Plan in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector no his employer makes any warranty, expressed or implied, concerning the activities described in the Repair/Replacement Plan. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this

inspection Commissions NB13399 NC1559 Inspector's Signature Date: 31 MAY 2011

FORM OAR-1 OWNER'S ACTIVITY REPORT

Item Description	Evaluation Description
Shell to Flange Weld 2B11-RPV-F	Indication most likely fabrication induced. Acceptable as-is per ASME IWB-3600 through the end of plant licensed life.
	•

TABLE 1

ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE **Repair/Replacement** Code Class **Item Description Description of Work Date Completed** Plan Number 2-B21-F028B Install guide pad 4/09/2009~~ 1382252-01 1 1 2-B21-F022C Install guide pad 4/2/2011 1490276-01 Install guide pad 1 2-B21-F022D 4/2/2011 1490271-01 Refurbish 8/4/2010 1497583-01 1 MSIV Disk-Piston **Replace CRD** 2-B11-CRD(18-1 3/25/2011 1653026-01 43) **Replace Flange** 4/1/2011 1739778-05 1 2-B32-28-RS-A **Replace nuts** 2/5/2010 1629393-03 1 2-E11-F050A 1 2-E11-F050A **Replace nuts** 3/27/2011 1629393-19 Replace CRD Accumulator 2 1-C11-125(46-39) 6/2/2009 1527655-01 1-C11-125(14-19) Replace CRD Accumulator 3/24/2011 1528751-01 2 2 Replace valve and elbow 4/3/2011 1489696-01 2-E11-F046D 2 **Replace valve** 4/8/2011 2-VA-2A-BPV-RB 1531108-01

TABLE 2