

**COMANCHE PEAK B & E
NUCLEAR PLANT UNITS 1 & 2
CPRES TRANSMISSION LINE
RIGHT-OF-WAY ALIGNMENT
FIGURE 3.9-1**

Accident(s) 5/15/74

Lake Granbury

De Cordova S.E.S.

Bent's Bend Junction

Dallas River

Square Creek Reservoir

De Cordova Line (138 kv and 345 kv in 230' ROW)

State Highway 44

Property Sub Lim.

Property Sub Lim.

Property Sub Lim.

Vander Line

Scale 0 to 10 miles

Revision 2

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 3 - Environmental Report




Figure 3.7-1 Existing CPNPP Transmission Lines (Sheet 2 of 3)

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 3 - Environmental Report




Figure 3.7-1 Existing CPNPP Transmission Lines (Sheet 3 of 3)