

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR



- (Purple lines) are overlain of exposed bedding to show the comparison between the LiDAR image (lower) and the photograph (above).
- (Yellow lines) show poor imaging areas due to vegetation.

Figure 2.5.1-227 Ground Based LiDAR Outcrop near CPNPP Dam