



Photo 21. Wetland 10.2



Photo 23. Wetland 10.3 – overflow channel caused by beaver dam



Photo 22. Wetland 10.3 – unnamed tributary near confluence



Photo 24. Wetland 10.3 – backwater from beaver dam



Photo 25. Wetland 10.3 – Walker Run downstream of beaver dam



Photo 27. Wetland 10.3 – post beaver dam removal



Photo 26. Wetland 10.3



Photo 28. Wetland 10.3 – post beaver dam removal



Photo 29. Wetland 10.3 – post beaver dam removal



Photo 31. Headcut on unnamed tributary 2 within Wetland 11



Photo 30. Unnamed tributary 2, upper reach within Wetland 11



Photo 32. Wetland 11 – Unnamed tributary 2