NRC FORM 591M PART 1 (4-2008) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED: Ground Engineering Consulting, Inc. 41 Inverness Drive East Englewood, Colorado 80112-5412 Location: 412 North Fenway. Casper. WY REPORT NO: 2011-002			NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125		
3. DOCKET NUMBER 4. LICENSE NUMBER			5. DATE OF INSPECTION		
030-36550		49-27772-01		June 13	through July 06, 2011
Regulatory Commission procedures and represe X 1. Based on th X 2. Previous vic 3. The violation identified, no	(NRC) rules and regular ntative records, interview e inspection findings, no plation(s) closed.	tions and the conditions we with personnel, and conviolations were identified to you by the inspec	of your license. The inspection observations by the inspector. ed.	n consisted of s The inspection f	findings are as follows:
4. During this	inspection certain of you	r activities, as described	lowing requirement(s) and Cor below and/or attached, were e subject to posting in accorda	in violation of NI	RC requirements and are being
corrective actions is ma	in 30 days, the actions d de in accordance with th ce will be achieved). I ur Printed N	escribed by me to the in e requirements of 10 CF aderstand that no further ame	rective Actions for Item spector will be taken to correct R 2.201 (corrective steps alrewritten response to NRC will Signature	t the violations in	ective steps which will be taken, ess specifically requested. Date 07/06/2011
NRC FORM 591M PART 1	GM VAS	5 40 Z	SHONMSHINMSKRANCHE	ORMS\591M FO	7/2s/2ou RMS\Párt1 Publicly Available.doc
Non-Public	Sensitive – Se	curity-Related		Public	X Non-Sensitive

TRANSMISSION VERIFICATION REPORT

07/06/2011 13:38 USNRC RIV TIME

NAME FAX 8178608263 TEL SER.#: BROL2J847623

DATE, TIME FAX NO./NAME DURATION PAGE(S)

RESULT MODE

07/06 13:38 713075770801 00:00:30 02 COVERPAGE OΚ STANDARD ECM



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

ACSI M

Name:

James Kawalski, P.E., Principal

Licensee:

Ground Engineering Consulting, Inc.

License No.:

49-27772-01

Docket No.:

030-36550

Fax No.: Phone No.: (307) 577-0801 (307) 577-0800 Rick Muñoz

From: Date:

07/06/2011

Subject:

Inspection Report NRC Form 591-M

Pages:

1 + transmittal sheet

I am faxing you a clear NRC Form 591M which documents the NRC inspection conducted at your 412 North Fenway, Casper, Wyoming, office with continued in-office review through July 06, 2011. The inspection verified your prompt corrective actions and long term preventive measures implemented to prevent recurrence of simular type violations that resulted in your escalated enforcement action. The violation was closed during this inspeciton. If you have any questions about the inspection or the inspection report form 591 please feel free to call me at (817) 860-8220.



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

FACSIMILE

Name:

James Kawalski, P.E., Principal

Ground Engineering Consulting, Inc.

License No.: Docket No.: 49-27772-01 030-36550

Licensee:

(307) 577-0801

Fax No.: Phone No.:

(307) 577-0800

From: Date: Rick Muñoz 07/06/2011

Subject:

Inspection Report NRC Form 591-M

Pages:

1 + transmittal sheet

I am faxing you a clear NRC Form 591M which documents the NRC inspection conducted at your 412 North Fenway, Casper, Wyoming, office with continued in-office review through July 06, 2011. The inspection verified your prompt corrective actions and long term preventive measures implemented to prevent recurrence of simular type violations that resulted in your escalated enforcement action. The violation was closed during this inspection. If you have any questions about the inspection or the inspection report form 591 please feel free to call me at (817) 860-8220.

Nuclear Materials Safety Branch A