



— flashboard failure at 6 ft.    ..... no flashboard failure

WILLIAM STATES LEE III  
NUCLEAR STATION UNITS 1 & 2

Discharge Rating Curve,  
Ninety-Nine Islands Dam

FIGURE 2.4.3-213    Rev 0

WLS COL 2.4-2