

Cataldo, Paul C

From: Lubrano, Louis
Sent: Thursday, December 03, 2009 9:33 AM
To: Cataldo, Paul C
Subject: 6.9kv Bus Tie breaker Information
Attachments: DOC001.pdf

Paul,

Following my research to determine the transition from outage PM to Non outage PM for the bus ties breakers, the following information is offered:

Unit 3 transition:

From work management search, 3R11 was the last outage that contained the bus tie breaker PM scope:

52/UT1ST5 - 3R11 - WO 990444000 - 5/01
→ 52/UT2ST5 - 3R11 - WO 990444600 - 5/01
52/UT3ST6 - 3R11 - WO 990444800 - 4/01
52/UT4ST6 - 3R11 - WO 990445000 - 5/01

Unit 2 transition:

From work management search, 2R15 was the last outage that contained the bus tie breaker PM scope:

52/UT1ST5 - 2R15 - WO 01-22947 - 11/02
52/UT2ST5 - 2R15 - WO 01-22942 - 11/02
52/UT3ST6 - 2R15 - WO 01-22936 - 11/02
52/UT4ST6 - 2R15 - WO 01-22943 - 11/02

I have attached the breaker schematic marked up to show the continuity checks performed during the PWT and the Latch Check Switch. See attached.

Lou Lubrano
914-734-6681

A-10