

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 1 of 45

**Enclosure 3**

Florida Power & Light Company Turkey Point Units 6 & 7  
Exploratory Well Project; Permit #0293962-001-UC  
Weekly Construction Summary #42 dated February 24, 2012

## WEEKLY CONSTRUCTION SUMMARY



**McNabb Hydrogeologic Consulting, Inc.**  
601 Heritage Drive, Suite 110  
Jupiter, Florida 33458  
Phone: 561-891-0763  
Fax: 561-623-5469

February 24, 2012

MHCDEP-12-0073

Mr. Joseph May, P.G.  
Florida Department of Environmental Protection  
400 N. Congress Ave, Suite 200  
West Palm Beach, FL 33401

**RE: Florida Power & Light Company Turkey Point Units 6 & 7 Exploratory Well  
Project; Permit #0293962-001-UC  
Weekly Construction Summary #42**

Dear Mr. May:

This is the forty-second weekly construction summary for the above referenced project. The reporting period for this weekly construction summary began at 7:00 AM, Thursday, February 16, 2012 and ended at 7:00 AM, Thursday, February 23, 2012. Consultant and drilling contractor daily reports were prepared for this reporting period. Copies of the consultant and drilling contractor daily construction logs are attached.

During the previous reporting period the drilling contractor performed caliper, gamma ray and video logging of the open hole interval, set up for and performed a formation test over the interval from 3,010 to 3,230 feet bpl. The drilling contractor then reamed the interval from 2,978 to 2,980 feet bpl with a 24-inch diameter drill bit and was in the process of tripping into the well with a 22-inch diameter reaming bit at the end of the reporting period.

During this reporting period, the drilling contractor reamed the interval from 2,980 to 3,230 feet bpl with a 22-inch diameter reaming bit. The drilling contractor then shut down while the final casing setting depth recommendation was prepared and submitted to the Florida Department of Environmental Protection Technical Advisory Committee. A caliper/gamma ray log was performed on the reamed borehole while awaiting approval of the casing setting depth recommendation. A copy of the caliper/gamma ray log is attached. Approval of the final casing setting depth recommendation was received from the Florida Department of Environmental Protection at the end of the reporting period.

There was no casing installation, cementing, or exploratory well development and no lithologic samples were collected during this reporting period. There were no construction related issues during this reporting period.

---

During the next reporting period, it is anticipated that the drilling contractor will install the 24-inch diameter final casing. The 24-inch diameter final casing will then be cemented in place after installation.

In addition, sampling of the pad monitor wells began on April 21, 2011 and has been taking place on a weekly basis since the initial sampling. The pad monitor wells were most recently sampled on February 23, 2012. The most recent set of pad monitoring well sample results available are for samples collected on February 16, 2012. Sampling of the pad monitor wells around EW-1 will continue until drilling and testing of EW-1 has been completed. Copies of the pad monitor well water quality data summary sheets are attached.

Should you have any questions regarding the above weekly construction summary, please contact David McNabb at (561) 891-0763.

Sincerely,

McNabb Hydrogeologic Consulting, Inc.

  
2/24/12  
David McNabb, P.G.

Attachments: Consultant Daily Construction Log  
Layne Christensen Company-Drilling Shift Report  
Pad Monitor Well Water Quality Data Summary Sheets  
Deviation Survey Summary  
Geophysical Log

Cc: George Heuler/FDEP-Tallahassee  
Emily Richardson/SFWMD  
Matthew Raffenberge/FPL  
David Holtz/HCE

Joe Haberfeld/FDEP-Tallahassee  
Ron Reese/USGS  
David Paul/FGS



McNabb Hydrogeologic Consulting, Inc.



## Daily Construction Log

**Date:** February 16, 2012

**FDEP UIC Permit #:**0293962-001-UC

**Project:** FPL Turkey Point EW

**Well No.:** EW-1

**Contractor:** Layne Christensen Company

**Bit Diameter:** 22-inch

**Starting Depth:** 2,980 feet bpl

**Ending Depth:** 3,078 feet bpl

**Weather Day:** Clear, Warm

**Recorded By:** Deborah Daigle/Sally Durall

**Weather Night:** Clear, Cool

**Activity:** Reaming

### CONSTRUCTION ACTIVITIES

- 0700 Yesterday, the drilling contractor completed reaming with the 24-inch bit to a depth of 2,980 feet bpl, tripped out the 24-inch bit, and tripped in with the 22-inch bit.  
0900 The drilling contractor is reaming the borehole with the 22-inch diameter bit at a depth of 2,989 feet bpl.  
1100 The drilling contractor is reaming the borehole with the 22-inch diameter bit at a depth of 2,995 feet bpl.  
1300 The drilling contractor is reaming the borehole with the 22-inch diameter bit at a depth of 3,001 feet bpl.  
1500 The drilling contractor is reaming the borehole with the 22-inch diameter bit at a depth of 3,007 feet bpl.  
1700 The drilling contractor is reaming the borehole with the 22-inch diameter bit at a depth of 3,013 feet bpl.  
1800 The drilling contractor is reaming the borehole at a depth of 3,016 feet bpl.  
2000 The drilling contractor is reaming the borehole at a depth of 3,026 feet bpl.  
2200 The drilling contractor is reaming the borehole at a depth of 3,036 feet bpl.  
2400 The drilling contractor is reaming the borehole at a depth of 3,047 feet bpl.  
0200 The drilling contractor is reaming the borehole at a depth of 3,057 feet bpl.  
0400 The drilling contractor is reaming the borehole at a depth of 3,068 feet bpl.  
0600 The drilling contractor is reaming the borehole at a depth of 3,078 feet bpl.  
0700 The drilling contractor continues to ream the borehole at a depth of 3,078 feet bpl.



## Daily Construction Log

**Date:** February 17, 2012      **FDEP UIC Permit #:**0293962-001-UC  
**Project:** FPL Turkey Point EW      **Well No.:** EW-1  
**Contractor:** Layne Christensen Company      **Bit Diameter:** 22-inch  
**Starting Depth:** 3,078 feet bpl      **Ending Depth:** 3,230 feet bpl  
**Weather Day:** Clear, Warm      **Recorded By:** Deborah Daigle  
**Weather Night:** NA  
**Activity:** Reaming

### CONSTRUCTION ACTIVITIES

- 0700 Yesterday, the drilling contractor began reaming the borehole with the 22-inch diameter bit from a depth of 2,980 feet below pad level (bpl). The drilling contractor continues to ream the borehole at depth of 3,078 feet bpl.
- 0725 The kelly is down at a depth of 2,985 feet bpl and the drilling contractor is circulating the borehole clean in preparation of performing a deviation survey.
- 0734 The drilling contractor trips inside the drill pipe with the deviation survey tool to a depth of 3,030 feet bpl.
- 0800 The deviation survey is complete and the result is 0.3 degree.
- 0805 The drilling contractor adds a pipe joint and lowers the drill bit to a depth of 3,175 feet bpl. The pipe lowers with no obstruction into the cavernous portion of the borehole.
- 0815 The drilling contractor adds a second joint and lowers the pipe into the borehole.
- 0835 The drilling contractor reaches the total depth of 3,230 feet bpl. The drilling contractor will circulate the borehole clean and then prepare for the remaining deviation surveys.
- 0930 The drilling contractor begins breaking out drill pipe in preparation for the remaining deviation surveys.
- 1130 The drilling contractor begins removing the air line from the drill pipe.
- 1200 The drilling contractor trips inside the drill pipe with the deviation survey tool to a depth of 3,210 feet bpl.
- 1223 The deviation survey is complete and the result is 0.5 degree.
- 1224 The drilling contractor trips inside the drill pipe with the deviation survey tool to a depth of 3,150 feet bpl.
- 1243 The deviation survey is complete and the result is 0.5 degree.
- 1244 The drilling contractor trips inside the drill pipe with the deviation survey tool to a depth of 3,090 feet bpl.
- 1306 The deviation survey is complete and the result is 0.4 degree.
- 1310 The drilling contractor begins raising the 22-inch drill bit into the 34-inch casing.
- 1410 The drilling contractor continues raising the 22-inch drill bit into the 34-inch casing.
- 1500 the drilling contractor has pulled the 22-inch bit to a depth of 1,420 feet bpl, and sealed off the top of the drilling pipe. The well will remain idle until the 24-inch casing seat recommendation is approved by FDEP.



McNabb Hydrogeologic Consulting, Inc.



## Daily Construction Log

---

**Date:** February 18, 2012

**FDEP UIC Permit #:**0293962-001-UC

**Project:** FPL Turkey Point EW

**Well No.:** EW-1

**Contractor:** Layne Christensen Company

**Bit Diameter:** NA

**Starting Depth:** 3,230 feet bpl

**Ending Depth:** 3,230 feet bpl

**Weather Day:** Clear, Warm

**Recorded By:** Deborah Daigle

**Weather Night:** NA

**Activity:** No Activity

### CONSTRUCTION ACTIVITIES

There was no construction activity on site today. Construction activity will resume after submittal and subsequent approval of the final casing setting depth recommendation.



McNabb Hydrogeologic Consulting, Inc.



## Daily Construction Log

---

**Date:** February 19, 2012

**FDEP UIC Permit #:**0293962-001-UC

**Project:** FPL Turkey Point EW

**Well No.:** EW-1

**Contractor:** Layne Christensen Company

**Bit Diameter:** NA

**Starting Depth:** 3,230 feet bpl

**Ending Depth:** 3,230 feet bpl

**Weather Day:** Clear, Warm

**Recorded By:** Deborah Daigle

**Weather Night:** NA

**Activity:** No Activity

### CONSTRUCTION ACTIVITIES

There was no construction activity on site today. Construction activity will resume after submittal and subsequent approval of the final casing setting depth recommendation.



McNabb Hydrogeologic Consulting, Inc.



## Daily Construction Log

---

**Date:** February 20, 2012

**FDEP UIC Permit #:**0293962-001-UC

**Project:** FPL Turkey Point EW

**Well No.:** EW-1

**Contractor:** Layne Christensen Company

**Bit Diameter:** NA

**Starting Depth:** 3,230 feet bpl

**Ending Depth:** 3,230 feet bpl

**Weather Day:** Clear, Warm

**Recorded By:** Deborah Daigle

**Weather Night:** NA

**Activity:** No Activity

### CONSTRUCTION ACTIVITIES

There was no construction activity on site today. Construction activity will resume after submittal and subsequent approval of the final casing setting depth recommendation.



McNabb Hydrogeologic Consulting, Inc.



## Daily Construction Log

**Date:** February 21, 2012                    **FDEP UIC Permit #:**0293962-001-UC  
**Project:** FPL Turkey Point EW              **Well No.:** EW-1  
**Contractor:** Layne Christensen Company    **Bit Diameter:** NA  
**Starting Depth:** 3,230 feet bpl            **Ending Depth:** 3,230 feet bpl  
**Weather Day:** Clear, Mild                    **Recorded By:** Marty Clasen  
**Weather Night:** NA  
**Activity:** Geophysical Logging

### CONSTRUCTION ACTIVITIES

- 0700 There was no construction activity at the site yesterday. Today the drilling contractor will run a caliper/gamma ray log on the pilot hole to total depth.  
0715 The geophysical logging truck is onsite and will set up for the caliper/gamma ray log.  
0800 The geophysical logger begins running the caliper/gamma ray tool into the hole.  
0830 The geophysical logger completed a repeat pass over the interval from 3,050 feet to 2,850 feet bpl.  
0900 The logging tool is at the bottom of the hole at a logged depth of 3,232 feet bpl. The geophysical logger begins running the caliper/gamma ray log from the bottom of the hole upwards.  
0945 The caliper/gamma ray log is completed to 1,430 feet bpl, which is inside the 34-inch diameter casing that was set at a depth of 1,535 feet bpl.  
1030 The geophysical logger provided eight field copies of the caliper/gamma ray log and one electronic pdf copy.  
1230 The drilling contractor is preparing the 24-inch diameter steel casing for installation by welding lifting lugs onto the pipe and working on the packer assembly.  
1430 The drilling contractor continues to prepare the 24-inch steel casing for installation.  
1630 The drilling contractor continues to prepare the 24-inch steel casing for installation.  
1800 The drilling contractor continues to prepare the 24-inch steel casing for installation.



McNabb Hydrogeologic Consulting, Inc.



## Daily Construction Log

**Date:** February 22, 2012                    **FDEP UIC Permit #:**0293962-001-UC  
**Project:** FPL Turkey Point EW            **Well No.:** EW-1  
**Contractor:** Layne Christensen Company    **Bit Diameter:** NA  
**Starting Depth:** 3,230 feet bpl            **Ending Depth:** 3,230 feet bpl  
**Weather Day:** Clear, Mild                    **Recorded By:** Marty Clasen  
**Weather Night:** NA  
**Activity:** 24-inch Casing

### CONSTRUCTION ACTIVITIES

- 0700 Yesterday, the drilling contractor ran a caliper/gamma ray log on the pilot hole to total depth. The drilling contractor is preparing the 24-inch diameter casing for installation.
- 0900 The drilling contractor is preparing the packer assembly and attaches the cement basket to the 24-inch casing.
- 1100 The drilling contractor continues to prepare the 24-inch diameter casing, cement basket, and packer assembly.
- 1230 The drilling contractor has completed the preparation of the 24-inch diameter casing, packer assembly and cement basket. The 24-inch pipe has been tallied. A total of 90 individual pipes will be installed.
- 1430 The casing tally was verified and the pipes were numbered from 1 through 90.
- 1600 The casing setting depth recommendation for the 24-inch diameter final casing has been approved by the Florida Department of Environmental Protection.
- 1800 The drilling contractor has been informed of the casing setting depth approval and will begin installing the casing tomorrow morning.





## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT FPLJOBSITE NAME FL2-1

## PERSONNEL EMPLOYED TODAY

Crew Assignment	Employee - Full Name	Per Diem?	Overtime Hours	Overtime Hours	Total Hours
DNLLER	BOSIT GULOMOV	X	12		12
V.I.	VLAD ISHIMOV	X	12		12
A.B.	AKMAL BURKHONOV	X	12		12
V.M.	VICTOR MOISYEV	X	12		12

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 12 of 45DATE 02-16-12

THUR NIGHT

JOB # 11771-1405-10000.

T.R.-

JOBSITE LOCATION

## DAILY ACTIVITIES BY ITEM #

Description	Unit #	Status
FDW-200	28805 W/K	
1989 MACK	10000 S/B	
DUMP TRUCK		

From	To	Circle One	Item #
	AM	PM	

Item #	Cost Code	Labor Activity	Hours
1	10000	Short Duration Job	
2	11100	Onsite Mobil/Demobil	
3	11150	Job Preparation	
4	11200	Safety Meeting	
5	00005	Training - Overhead	
6	00006	Shop - Overhead	
7	00007	Maintenance - Overhead	
8	11250	Training - Job Changeable	
9	11300	Site Clean up	
10	11350	Install Sound Walls	
11	11400	Install Decon Pad	
12	11450	Install Surface Casting	
13	11500	Install Roadway & Drill Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Borehole Abandonment	
18	13050	Production Well Installation	
19	13100	Install Conductor Pipe	
20	13150	Drill Pilot Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	
23	13300	Borehole Abandonment/Cement Plugs	
24	13350	Reaming	
25	13400	Underreaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Washing	
31	14050	Well Development Air Lift and Swab	
32	14100	Dispose of Fluids & Cuttings	
33	14150	Furnish & Install Test Pumpe and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Disinfection and Chlorination	
37	19050	Offsite Activities Mobil/Demobil	
38	19100	Shop	
39	29150	Administrative	
40	19550	Other Activities Standby	
41	19600	Fishing for Lost/Broken Tooling	
42	19650	Change Order Activities	
43	60000	Equipment Repair	
44	90170	Damages	
45	90200	Job Superintendent	
		Search	
		TOTAL HOURS	

## COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

DM

DDII 22' BIT: FROM F-3016' SPL - TO - 3060'  
 Housekeeping, Move the COREPUMP, Side clean up +  
 pick up trash:

02-16-12

Initials  
Signature

Date

Client's Signature

Dayton I

Date

Expenses' Signature

Date



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT FPL  
JOBSITE NAME EN-1

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 13 of 45

DATE 2/17/12  
FRIDAY

JOB # 11771, 1405, 10000  
JOBSITE LOCATION T.P.

## PERSONNEL EMPLOYED TODAY

Crew Assignment	Employee - FullName	Per Diem? <input checked="" type="checkbox"/>	Overtime Hours	Overtime Hours	Total Hours
DRILLER	DANNY KEELEY	<input checked="" type="checkbox"/>	12		12
GRS	GEORGE HAGA	<input checked="" type="checkbox"/>	12		12
DN	JUAN NINO	<input checked="" type="checkbox"/>	12		12
AP	ANDREY POPOV	<input checked="" type="checkbox"/>	12		12

## MATERIALS USED TODAY

Quantity	Description
	<i>SAFETY MEETINGS;</i>
	<i>#1 TEAM WORK</i>
	<i>#2 PAINTING PROCEDURES .</i>
	<i>PPE; LOADER SAFETY, PINCH POINTS,</i>
	<i>TDH,</i>

## EQUIPMENT DEPLOYED TODAY

Description	Unit #	Status
FDW-200	28605	WK
1989 MACK 1B000	SB	
DUMP TRUCK		
Working	WK	Mobileization
Standby	SB	Demobilization
Down In Shop	DS	Available in Yard
Down on Site	DS	Available on Job

## TIME OF ACTIVITY BY ITEM #

From	To	Onsite On	Item #
		AM	PM

## DAILY ACCOUNTING OF ACTIVITIES BY ITEM #

Item #	Cost Code	Labor Activity	Hours
1	10000	Short Duration Job	
2	11100	Drill/Mob/Demob	
3	11150	Tool Preparation	
4	11200	Safety Meeting	
5	0005	Training - Overhead	
6	0006	Setup - Overhead	
7	0007	Maintenance - Overhead	
8	11250	Training - Job Chargeable	
9	11300	Site Clean up	
10	11350	Install/Sound Wall	
11	11400	Install/Decon Pad	
12	11450	Install/Surface Casing	
13	11500	Install/Roadway & Drill Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Holehole Abandonment	
18	13050	Production Well Finalization	
19	13100	Install/Conductor Pipe	
20	13150	Well Plug Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	6
23	13300	Holehole Abandonment/Content Plugs	
24	13350	Reaming	
25	13400	Under Reaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Watching	
31	14050	Well Development Air Lift and Swab	
32	14100	Disposal of Fluids & Cuttings	
33	14150	Furnish & Install Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Disinfection and Chlorination	
37	19050	Offsite Activities Mob/Demob	
38	19100	Shop	
39	19150	Administrations	
40	19550	Other Activities Standby	
41	19600	Fishing for Lost/Broken Tooling	
42	19650	Change Order Activities	
43	88000	Equipment Repairs	
44	90170	Damages	
45	90200	Job Superintendent	
		lunch	
		TOTAL HOURS	

## COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

*REAMED 22" BIT FROM 3060' BPL TO 3230' BPL  
 TRIPPED IN THE CASING; SHUT DOWN AT 3:00 P.M.  
 HALLED OUT FRAK TANKS; CLEAN & PAINT RIG  
 Performed deviation surveys: 3030' = 0.3°, 3090' = 6.4° DM  
 3150' = 0.4°, 3210' = 0.5°*

Installer's Signature  
Layne  
DateClient's Signature  
Date

PAYROLL

Date

Supervisor's Signature  
Date

Date



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CUSTOMER FPL  
JOBSITE NAME EW-1

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 14 of 45

PERSONNEL EMPLOYED TODAY

Crew Assignment	Employee - Full Name	Per Diem? (X)	Overtime Hours	Overtime Hours	Total Hours
D	BOSIT GULOMONOV	X	12		12
V.I	VLAD ISHIMOV	X	12		12
V.M	VICTOR MOISYEV	X	12		12
AIB	AKMAL BURUKHONOV	X	12		12

MATERIALS USED TODAY

Quantity	Description
	<u>SAFETY RTTG:</u>
①	<u>SLIPS, TRIPS - FALLS!</u>
②	<u>PAINT SAFETY!</u>

COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

<u>PAINT - TOP DRIVE, PRESS WASH</u>
<u>RIG + FLOOR</u>

DATE 02-17-2012  
FRI NIGHT

EQUIPMENT DEPLOYED TODAY

Description	Unit #	Status
FDW-200	26605 w/e	
1989 MACK	18000 SB	
DUMP TRUCK		

TIME OF ACTIVITY BY ITEM #

From	To	Circle One	Item #
	AM PM		

JOB # 11771-1405-10000JOBSITE LOCATION TP

DAILY ACCOUNTING OF ACTIVITIES BY ITEM #

Item #	Cost Code	Labor Activity	Hours
1	10000	Short Duration Job	
2	11300	Onsite Mob/Demob	
3	11350	Job Preparation	
4	11200	Safety Meeting	
5	0005	Training - Overhead	
6	0006	Shop - Overhead	
7	0007	Maintenance - Overhead	
8	11250	Training - Job Chargeable	
9	11300	Site Clean up	
10	11300	Install Sound Walls	
11	11400	Install Deco Pad	
12	11450	Install Surface Casing	
13	11500	Install Roadway & Drill Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Borehole Abandonment	
18	13050	Product on Wall Installation	
19	13100	Install Conductor Pipe	
20	13150	Drill Pilot Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	
23	13300	Borehole Abandonment/Cement Plugs	
24	13350	Reaming	
25	13400	Underreaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Watching	
31	14050	Well Development Air Lift and Swab	
32	14100	Disposal of Fluids & Cuttings	
33	14150	Furnish & Install Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Disinfection and Chlorination	
37	19050	Offsite Activities Mob/Demob	
38	19100	Shop	
39	19150	Administration	
40	19550	Other Activities Standby	
41	19600	Fishing for Lost/Broken Towing	
42	19650	Change Order Activities	
43	88000	Equipment Repairs	
44	90170	Damages	
45	90200	Job Superintendent	
		Janitor	
		TOTAL HOURS	

John S.

02-17-12

Date

Start's Signature

PAYROLL

Ken S.

End's Signature

Date



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT FPLJOBSITE NAME Ew-1

Proposed Turkey Point Units 6 and 7

Docket Nos. 52-040 and 52-041

L-2012-087 Enclosure 3 Page 15 of 45

PERSONNEL EMPLOYED TODAY

Crw Assignment	Employee - Full Name	Per Diem? (X)	Onsite Hours	Offsite Hours	Total Hours
Will Incy	Michael A. Ramirez	X	12		12
TN	Juan Nieto	X	12		12
JK	James McDonnell	X	12		12
PFY	Justin Yeomans	X	12		12

MATERIALS USED TODAY

Quantity	Description
	Safety Meeting
1)	Machine Gauging
2)	Blood Borne Pathogens

.	Power tools, Arc welding, High pressure lines, PPE, Loader Safety, chem. spill prevention.
---	--

COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

Rig on Standby. Painting / House Keeping. Unload Casings 24" Delivery 6 pcs. Help Welder. Begin Tripping Back down to Bottom.

W. Perez

Client's Signature

PAYROLL

JOB # 11071.1405.10000  
 JOBSITE LOCATION Turkey Point  
 DAILY ACCOUNTING OR ACTIVITIES BY ITEM #

EQUIPMENT OPERATED TODAY

Description		Unit #	Status
	FDW 200	28605 W/K	
	1484 WATER DUMP	18000 S/B	
	TRUCK		

Working	WK	Mobilization	MB
Standby	SB	Demobilization	DM
Down In Shop	DS	Available In Yard	AY
Down on Site	DN	Available on Job	AV

TIME OF ACTIVITY BY ITEM #

From	To	Crse One	Item #
		AM PM	

Item #	Code/Code	Labor Activity	Hour
1	00000	Initial Condition Job	
2	01100	Drill/Mud/Debris	
3	01150	Drill/Mud/Waste	
4	03800	Safety Meeting	
5	06000	Training-Divisional	
6	06050	Work - Operational	
7	06060	Maintenance - Overall	
8	15200	Training-Job Change/Shift	
9	15400	Site Clean up	
10	21000	Install Standby Water	
11	21100	Install Driller Pad	
12	21100	Install Surface Coating	
13	21100	Install Roadway & Drill Pad	
14	22200	Install Riser	
15	22200	Geophysical Logging & Other Testing	
16	22200	Acoustic/Seismic Testing	
17	22200	Geophysical/Geosounding/Crosswell Tests	
18	22220	Retained by	
19	22220	Water Cleaning	
20	22250	Install Coating	
21	22300	Install Surface	
22	22300	Check/Roll The MVR	
23	22300	Install Riser Seal	
24	22350	Major Welding	
25	23000	Well Development Air Bit and Swab	
26	24300	Planned of Huds & Cullings	
27	24300	Planned & Install Top Pump and Discharge	
28	24300	Development Rigs/Pipe	
29	24300	Test/Plumbing	
30	24300	Drill/Debris and Chlorination	
31	24700	Coring Activities/Rig/Debris	
32	22200	Shut	
33	22200	Well Debris	
34	22200	Extract Activities Debris	
35	23000	Retrieving for Lost/Broken Tooling	
36	24300	Change Underdrill/Illite	
37	24300	Equipment Repair	
38	30300	Drill	
39	30300	Mud Separation	
40	30300	Drill	
41	30300	Drill	
42	30300	Drill	
43	30300	Drill	
44	30300	Drill	
45	30300	Drill	

TOTAL HOURS

Supervisor's Signature

R. Perez

## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT



CLIENT

E.P.L.

JOBSITE NAME

EW-1

PERSONNEL EMPLOYED TODAY

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 16 of 45

Crew Assignment	Employee - Full Name	Per Day? (X)	Onsite Hours	Offsite Hours	Total Hours
DPL/102	PROSIT GULOMOV	X	12		12
V.I.	VLAD ISHIMOV	X	12		12
V.M.	VICTOR MOISYEV	X	12		12
A.B.	ALMAS BURKHANOV	X	12		12

MATERIALS USED TODAY

Quantity	Description
	SAFETY MTG:
①	T.I.H AND - T.O.H.
②	PROTECTING THE HOLE!
	PPE; LI.T.R.A; PINCH POINT; HAND SAFETY; LOADER SAFETY HIGH PRESS LINE;

COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

T.I.H @ 3230' BPL: 22" BIT: Circulate the hole 30min  
T.O.H: 22" BIT AND STABILIZER: T.I.H - 1 Dip  
Robert CAN; Clear the Floor; CAN Rig Hydraulic hose snared,  
take a parts

02-20-12

Client's Signature

PAYROLL

Date \_\_\_\_\_

JOB # 11771-1405-100002

JOBSITE LOCATION

T.I.P

DAILY ACCOUNTING OF ACTIVITIES BY ITEM #

Item #	Cost Code	Labor Activity	Hours
1	30000	Short Duration Job	
2	11100	Onsite Mob/Demob	
3	11150	Job Preparation	
4	11200	Safety Meeting	
5	0005	Training - Overhead	
6	0006	Shop - Overhead	
7	0007	Maintenance - Overhead	
8	12200	Training - Job Chargeable	
9	11200	Site Clean up	
10	11350	Install Sound Walls	
11	11400	Install Decon Pad	
12	11450	Install Surface Casing	
13	11500	Install Roadway & Drill Pad	
14	12050	Drill Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12100	Hydrate Zone Testing	
17	12200	Borehole Abandonment	
18	13050	Production Well Installation	
19	13100	Install Conduit or Pipe	
20	13150	Drill Pilot Hole	
21	13200	Geophysical Logging & Other Testing	
22	13300	Hydrate Zone Testing	
23	13300	Borehole Abandonment/Cement Plugs	
24	13350	Roaming	
25	13400	Under Roaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Watchdog	
31	14050	Well Development Air Lift and Swab	
32	14100	Disposal of Fluids & Cuttings	
33	14150	Unravel & Install Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Hydrafaction and Cut off isolation	
37	19050	Mobile Activities Mob/Demob	
38	19100	Shop	
39	19150	Administration	
40	19550	Other Activities Standby	
41	19600	Hunting for Lost/Broken Tooling	
42	19650	Change Order Activities	
43	88000	Equipment Repairs	
44	90170	Damages	
45	90200	Job Superintendent	
		Unsch.	
		TOTAL HOURS	

*K. Radecoff*

Supervisor's Signature

Date



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT FPL

JOBSITE NAME EW-1

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 17 of 45

PERSONNEL EMPLOYED TODAY

Crew Assignment	Employee - Full Name	Per Diem? (X)	Onsite Hours	Offsite Hours	Total Hours
DRILLING	Michael A. Ramirez	X	12		12
JN	Juan Nieto	X	12		12
JY	James McDonnell	X	12		12
	Justin Yeomans	X	12		12

MATERIALS USED TODAY

Quantity	Description
	Safety Meetings
	1) Employer Safety Responsibilities
	2) Back injury Prevention
	Arc Welder-Torch Safety, Loader Safety, Fire Prevention, PPE, Eyes on Path, overhead dangers, Slip-trip-fall

COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

Log Hole - Help logger. Help welder. Help with Frack Tank  
 Pick up. Help Survey co. Unload delivery 2 stainless flanges fiber-glass coupling 3 way gate valve. Replace Blowout Hose on Can Rig. Removed X-O and pop off stabilizer. Removed X-O off 22" bit. Scrubbed Drill house floor & Can Rig. Housekeeping

MR

2/21/12

Interests Signature  
LCCPSH 082209

Client's Signature

Date

Supervisor's Signature

Date

PAYROLL

DATE 2/21/12  
Tuesday Daytime

JOB # 11721,1405,16000

JOBSITE LOCATION Turkey Point

DAILY ACCOUNTING OF ACTIVITIES BY ITEM #

Item #	Cost Code	Labor Activity	Hours
1	10000	Short Duration Job	
2	11100	Drill Mob/Demob	
3	11150	Job Preparation	
4	11200	Safety Meeting	
5	10005	Training - Overhead	
6	00006	Shop - Overhead	
7	00007	Maintenance - Overhead	
8	11250	Training - Job Chargeable	
9	11300	Site Clean up	
10	11350	Install Sound Walls	
11	11400	Install Decon Pad	
12	11450	Install Surface Casing	
13	11500	Install Roadway & Oil Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Borehole Abandonment	
18	13050	Production Well Installation	
19	13100	Install Conductor Pipe	
20	13150	Oil Field Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	
23	13300	Borehole Abandonment / Cement Plugs	
24	13350	Reaming	
25	13400	Under Reaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Washing	
31	14050	Well Development Air Lift and Swab	
32	14100	Disposal of Fluids & Cuttings	
33	14150	Furnish & Install Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Hydrofracture and Chlorination	
37	19050	Offsite Activities Mob/Demob	
38	19100	Shop	
39	19150	Administrstration	
40	19550	Other Activities Standby	
41	19600	Fishing for Lost/Broken Tooling	
42	19650	Change Order Activities	
43	68000	Equipment Repairs	
44	90170	Damage	
45	90200	Job Superintendent	
		Lunch	
		TOTAL HOURS	

Kev G

Date



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT FPLJOBSITE NAME EW-1

PERSONNEL EMPLOYED TODAY

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 18 of 45

Crew Assignment	Employee - Full Name	Per Diem? (X)	Onsite Hours	Offsite Hours	Total Hours
DRIEYER	<u>DANNY KEELEY</u>	X	12		12
JOB	<u>JUAN NINO</u>	X	12		12
JP	<u>ANDREY POPOV</u>	X	12		12
GM	<u>GEORGE HAGA</u>		4		4

MATERIALS USED TODAY

Quantity	Description
	<u>SAFETY MEETINGS:</u>
	<u>#1 HANDLING GAS &amp; FLAMMABLE LIQUIDS</u>
	<u>#2 CHEMICAL'S SAFETY</u>
	<u>PPE, LOADER SAFETY, PINCH POINTS,</u>
	<u>HAND SIGNALS.</u>

COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

<u>ORGANIZE &amp; TALLY CASING, PREP TOOLS FOR CASING, HOUSEKEEPING.</u>

Employee Signature  
Layne Christensen2/21/12

Employee Signature

Date

Supervisor's Signature

Date

PAYROLL

DATE 2/21/12  
TUE, NIGHT

EQUIPMENT DEPLOYED TODAY:

Description		Unit #	Status
<u>FOW-200</u>	<u>28605</u>	<u>WK</u>	
<u>1989 MACK 13000</u>	<u>SB</u>		
<u>DUMP TRUCK</u>			

TIME OF ACTIVITY BY ITEM #

From	To	Circle One	Item #
		AM	PM

Item #	Cost Code	Labor Activity	Hours
1	10000	Short Duration Job	
2	11100	Onsite Mob/Demob	
3	11150	Job Preparation	
4	11200	Safety Meeting	
5	10005	Training - Overhead	
6	00006	Shop - Overhead	
7	00007	Maintenance - Overhead	
8	11250	Training - Job Changeover	
9	11300	Site Clean up	
10	11350	Install Sound Walls	
11	11400	Install Decon Pad	
12	11450	Install Surface Casing	
13	11500	Install Roadway & Drill Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Corehole Abandonment	
18	13050	Production Wall Installation	
19	13100	Install Conductor Pipe	
20	13150	Drill Pilot Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	
23	13300	Corehole Abandonment/Cement Plugs	
24	13350	reaming	
25	13400	Underreaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Watching	
31	14050	Hole Development, Air Lift and Swab	
32	14100	Dispose of Mud & Cuttings	
33	14150	Furnish & Install Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Installation and Citronalization	
37	14900	Offsite Activities Mob/Demob	
38	19100	Shop	
39	19150	Administration	
40	19550	Other Activities as Standby	
41	19600	Waiting or Lost/Broken Tooling	
42	19650	Change Order Activities	
43	88000	Equipment Repairs	
44	90170	Damages	
45	90200	Job Superintendent	
		Lunch	
		TOTAL HOURS	

Employee Signature  
Layne ChristensenKr H



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT FPL  
JOBSITE NAME E-W-1

PERSONNEL EMPLOYED TODAY

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 19 of 45

Crew Assignment	Employee - Full Name	Per Diem? (X)	Onsite Hours	Offsite Hours	Total Hours
Driller	Michael A. Ramirez	X			
JW	Juan Nieto	X			
JM	James McDonnell	X			
JY	Justin Young	X			
AKB	AKmal Burkhanov	X			

MATERIALS USED TODAY

Quantity	Description
	Safety Meetings
	1) Spill Reporting/Control Procedures
	2) ARC WELDING SAFETY

\* PPE, Hand tool Safety, eye protection, Slip-trip-fall  
Ladder safety,

COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

Waiting on orders. Helped Welder Make up 24" BHA Packer  
for Casing Run. Helped Welder. Tally casing with engineer. Change  
out Ian Rig Dies.

DATE 2/22/12  
WED Day

EQUIPMENT DEPLOYED TODAY

Description		Unit #	Status
Working	WK	Demobilization	DM
Standby	SB	Available in Yard	AY
Down in Shop	DS	Available in Yard	AY
Down on Site	DN	Available on Job	AV

TIME OF ACTIVITY BY ITEM #

From	To	Order One	Item #
		AM	PM

Item #	Cost Code	Labor Activity	Hours
1	10000	Shop Duration Job	
2	11100	Onsite Mobil/Demob	
3	11150	Job Preparation	
4	11200	Safety Meeting	
5	0005	Training - Overhead	
6	0006	Shop - Overhead	
7	0007	Maintenance - Overhead	
8	11250	Training - Job Chargeable	
9	11300	Site Clean up	
10	11350	Install Sound Walls	
11	11400	Install Decon Pad	
12	11450	Install Surface Casing	
13	11500	Install Railway & Drill Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Borehole Abandonment	
18	13050	Production Well Installation	
19	13100	Install Conductor Pipe	
20	13150	Drill Pilot Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	
23	13300	Borehole Abandonment/Cement Plugs	
24	13350	Reaming	
25	13400	Under Reaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Travel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Valve Welding	
31	14050	Well Development Air Lift and Swab	
32	14100	Disposal of Fluids & Cuttings	
33	14150	Brush & Infield Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Hydration and Classification	
37	19050	Mobile Additives Mobil/Demob	
38	19100	Shop	
39	19150	Administration	
40	19550	Other Activities Standby	
41	19600	Waiting for Lost/Broken Tooling	
42	19650	Change Order Activities	
43	88000	Equipment Repairs	
44	90170	Damages	
45	90200	Job Superintendent	
		Lunch	
		TOTAL HOURS	

MAR. Rein

2/22/12

Client's Signature

PAYROLL

K. G.

Foreman's Signature

Date:



## LAYNE CHRISTENSEN COMPANY - DRILLING SHIFT REPORT

CLIENT  
FPL  
JOBSITE NAME  
EW-1Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 20 of 45

## PERSONNEL EMPLOYED TODAY

Crew Assignment	Employee - Full Name	Per Diem? (X)	Onsite Hours	Offsite Hours	Total Hours
DRILLER	DANNY KEELEY	X	12		12
CH	GEORGE HAGA	X	12		12
JN	JUAN NINO	X	12		12
AP	ANDREY POPOV	X	12		12

DATE

2/23/12

JOB #

11731.1405.10000

WED. NIGHT

JOBSITE LOCATION

T.P.

## EQUIPMENT DEPLOYED TODAY

Description	Unit #	Status
FDW-200 28605	WK	
1989 MACK 18000	SB	
DUMP TRUCK		

## TIME OF ACTIVITY BY ITEM #

From	To	Circle One	Item #
		AM PM	

## MATERIALS USED TODAY

Quantity	Description
	SAFETY MEETINGS :
	#1 LAYING DOWN COLLARS
	#2 LAYING DOWN DRILL PIPE / TEAMWORK
	PPE, LOADER SAFETY, TORCH SAFETY
	PINCH POINTS

## COMMENTS - EVENTS - CONDITIONS - CHANGES - OTHER INFORMATION

BREAK & LAY DOWN COLLARS
BREAK & LAY DOWN DRILL PIPE

J.C.

2/23/12

Client's Signature

DAYROLL

Date

Supervisor's Signature

Comments

Date

## DAILY ACCOUNTING OF ACTIVITIES BY ITEM #

Item #	Cost Code	Labor Activity	Hours
1	10000	Short Duration Job	
2	11100	Onsite Mob/Demob	
3	11150	Job Preparation	
4	11200	Safety Meeting	
5	0005	Training - Overhead	
6	0006	Hop - Overhead	
7	0007	Maintenance - Overhead	
8	11250	Training - Job Chargeable	
9	11300	Site Clean up	
10	11350	Install Sound Walls	
11	11400	Install Decon Pad	
12	11450	Install Surface Casing	
13	11500	Install Roadway & Oil Pad	
14	12050	Test Hole Drilling	
15	12100	Geophysical Logging & Other Testing	
16	12150	Aquifer Zone Testing	
17	12200	Wellbore Abandonment	
18	13050	Production Wall Installation	
19	13100	Install Conductor Pipe	
20	13150	Drill Pilot Hole	
21	13200	Geophysical Logging & Other Testing	
22	13250	Aquifer Zone Testing	
23	13300	Wellbore Abandonment/Cement Plugs	
24	13350	Cleaning	
25	13400	Underreaming	
26	13450	Install Casing	
27	13500	Install Screen	
28	13550	Gravel Pack The Well	
29	13600	Install Annular Seal	
30	13650	Water Watching	
31	14050	Well Development Air Lift and Swab	
32	14100	Disposal of Fluids & Cuttings	
33	14150	Furnish & Install Test Pump and Discharge	
34	14200	Development Pumping	
35	14250	Test Pumping	
36	14300	Direction and Calibration	
37	19050	Offsite Activities Mob/Demob	
38	19100	Shop	
39	19150	Administration	
40	19550	Other Activities Standby	
41	19600	Shuttle or Lost/Broken Tooling	
42	19650	Change Order Activities	
43	89000	Equipment Repairs	
44	90170	Damages	
45	90200	Job Superintendent	
		Lunch	
		TOTAL HOURS	

Project: Florida Power & Light Company  
Miami-Dade County, Florida  
Exploratory Well EW-1



**EW-1 Pad Monitoring Well Water Quality Data**  
**Northeast Pad Monitoring Well**  
**(NE-EW PMW)**

Date	Time (hours)	Depth to Water (ft. btoc)	Water Elevation (ft. NAVD 88)	Specific Conductance (umhos/cm)	Chloride (mg/L)	TDS (mg/L)	Temperature (degrees C)	Remarks
4/21/2011	1108	10.49	-1.61	78,700	32,200	57,000	29.8	Background Sampling
4/29/2011	1157	10.68	-1.80	80,400	29,900	53,800	30.4	
5/5/2011	1157	11.40	-2.52	81,400	27,500	52,350	31.2	
5/11/2011	1309	11.00	-2.12	76,800	31,600	51,200	29.7	
5/19/2011	0958	10.48	-1.60	72,600	35,600	51,200	29.5	
5/26/2011	1050	10.76	-1.88	71,360	29,500	52,900	29.7	
6/2/2011	1134	10.78	-1.90	71,700	29,000	55,700	29.6	
6/9/2011	1128	10.61	-1.73	69,700	32,300	50,650	29.3	
6/16/2011	0958	10.35	-1.47	69,300	33,000	53,450	29.5	
6/23/2011	1028	10.41	-1.53	69,400	30,600	55,600	29.5	
6/30/2011	0928	10.15	-1.27	70,300	27,600	51,950	29.2	
7/8/2011	1210	9.00	-0.12	72,570	30,100	54,150	29.9	
7/14/2011	1338	9.75	-0.87	76,400	27,200	54,550	29.9	
7/21/2011	1039	9.35	-0.47	72,200	32,600	49,760	29.7	
7/28/2011	1119	9.51	-0.63	71,600	30,200	54,250	29.7	
8/4/2011	1249	9.70	-0.82	64,400	31,500	53,850	27.5	
8/11/2011	1059	9.25	-0.37	73,900	29,500	57,150	29.6	
8/18/2011	1039	9.45	-0.57	71,900	29,400	54,850	30.0	
8/25/2011	1039	9.45	-0.57	69,800	31,300	55,550	29.7	
9/1/2011	1109	9.15	-0.27	71,700	29,500	56,300	29.9	
9/8/2011	1049	9.15	-0.27	70,700	31,400	49,800	30.3	
9/16/2011	1233	9.30	-0.42	5320*	1260*	2668*	27.8	
9/23/2011	1129	9.10	-0.22	72,900	31,200	52,750	30.1	
9/29/2011	1330	9.16	-0.28	11,500*	3,200*	7,010*	27.8	
10/6/2011	1119	9.30	-0.42	72,600	30,000	56,200	30.1	
10/13/2011	1058	10.15	-1.27	75,200	32,500	51,600	30.1	
10/20/2011	1049	8.40	0.48	68,400	29,100	57,450	29.9	
10/27/2011	1109	8.95	-0.07	80,200	27,700	54,950	30.0	
11/3/2011	1049	8.91	-0.03	80,200	31,100	55,700	29.9	
11/10/2011	0958	9.67	-0.79	75,500	28,700	59,600	30.0	
11/17/2011	1058	10.81	-1.93	68,400	34,900	57,500	30.1	
11/25/2011	0939	9.51	-0.63	69,300	26,500	52,750	30.0	
12/1/2011	1138	9.67	-0.79	66,000	29,800	55,200	29.8	
12/8/2011	1058	10.31	-1.43	63,800	30,100	57,050	27.5	
12/15/2011	1109	9.61	-0.73	75,400	28,300	53,700	30.0	
12/22/2011	1038	9.67	-0.79	69,300	29,500	51,800	30.7	
12/29/2011	0918	9.87	-0.99	76,900	30,800	51,300	29.7	
1/5/2012	1118	10.41	-1.53	70,400	28,100	52,200	29.5	
1/12/2012	1058	10.21	-1.33	75,200	28,200	50,900	29.9	
1/19/2012	0958	10.30	-1.42	75,200	27,700	49,300	29.8	
1/26/2012	1048	10.22	-1.34	72,300	29,400	55,300	30.0	
2/2/2012	1048	10.21	-1.33	71,300	28,400	50,700	29.9	
2/10/2012	1029	9.15	-0.27	71,400	30,400	52,400	30.0	
2/16/2012	1219	9.47	-0.59	72,300	27,000	53,300	29.9	

ft. btoc: feet below top of casing

TOC: Top of Casing

ft. NAVD 88: North American Vertical Datum of 1988

umhos/cm: micromhos per centimeter

mg/L: milligrams per liter

C: Celsius

\*Results appear to be anomalous and are suspected to be related to a sampling error. Countermeasures to prevent reoccurrence have been implemented.

Note: TOC elevation is: 8.88 feet NAVD 88

## Proposed Turkey Point Units 6 and 7

Docket Nos. 52-040 and 52-041

L-2012-087 Enclosure 3 Page 22 of 45

Project: Florida Power & Light Company  
 Miami-Dade County, Florida  
 Exploratory Well EW-1

MHC



**EW-1 Pad Monitoring Well Water Quality Data**  
**Southeast Pad Monitoring Well**  
**(SE-EW PMW)**

Date	Time (hours)	Depth to Water (ft. btoc)	Water Elevation (ft. NAVD 88)	Specific Conductance (umhos/cm)	Chloride (mg/L)	TDS (mg/L)	Temperature (degrees C)	Remarks
4/21/2011	1311	10.10	-1.51	81,600	30,200	57,800	29.9	
4/29/2011	1349	10.40	-1.81	86,700	33,100	55,000	30.4	
5/5/2011	1008	11.10	-2.51	83,000	29,500	54,700	29.9	
5/11/2011	1228	10.65	-2.06	78,200	30,100	52,600	30.1	
5/19/2011	1039	10.12	-1.53	75,200	30,000	51,100	29.8	
5/26/2011	1235	10.47	-1.88	73,890	31,200	53,800	29.9	
6/2/2011	1056	10.50	-1.91	74,200	29,400	57,400	29.6	
6/9/2011	1210	10.32	-1.73	72,200	32,100	51,000	29.6	
6/16/2011	1035	10.00	-1.41	71,300	32,200	54,000	29.8	
6/23/2011	1109	10.10	-1.51	71,900	31,600	55,650	29.8	
6/30/2011	1009	9.85	-1.26	72,800	27,600	53,050	29.5	
7/8/2011	1138	9.12	-0.53	73,150	29,800	54,450	29.9	
7/14/2011	1414	9.48	-0.89	79,700	29,000	55,350	29.8	
7/21/2011	1119	9.36	-0.77	74,100	34,000	54,100	30.0	
7/28/2011	1229	9.55	-0.96	74,300	30,200	56,300	29.8	
8/4/2011	1224	9.50	-0.91	72,700	31,500	53,000	27.7	
8/11/2011	1209	9.37	-0.78	77,400	30,000	56,800	29.7	
8/18/2011	1149	9.45	-0.86	74,100	30,100	55,500	30.0	
8/25/2011	1149	9.38	-0.79	73,300	31,200	57,450	29.6	
9/1/2011	1224	9.10	-0.51	72,700	30,700	57,300	29.8	
9/8/2011	1159	9.21	-0.62	73,200	32,200	51,800	30.1	
9/16/2011	1303	9.40	-0.81	70,280	29,600	50,550	27.7	
9/23/2011	1239	9.20	-0.61	75,200	29,000	55,550	29.8	
9/29/2011	1300	9.10	-0.51	68,500	30,700	53,600	27.4	
10/6/2011	1229	9.25	-0.66	79,100	31,300	54,050	30.0	
10/13/2011	1209	9.95	-1.36	76,900	30,200	52,250	30.1	
10/20/2011	1200	8.60	-0.01	69,900	28,000	57,150	29.8	
10/27/2011	1218	8.81	-0.22	82,400	28,000	56,500	30.0	
11/3/2011	1159	9.56	-0.97	82,900	31,000	56,400	30.1	
11/10/2011	1109	9.96	-1.37	78,300	27,900	60,500	30.1	
11/17/2011	1208	10.90	-2.31	69,700	34,000	57,800	30.2	
11/25/2011	1049	9.36	-0.77	69,900	26,900	53,600	30.0	
12/1/2011	1248	10.85	-2.26	71,800	33,900	57,000	30.2	
12/8/2011	1209	9.87	-1.28	68,900	29,500	61,500	27.0	
12/15/2011	1219	9.53	-0.94	76,600	28,000	55,100	30.1	
12/22/2011	1149	9.65	-1.06	72,300	29,000	52,400	30.0	
12/29/2011	1029	9.96	-1.37	77,600	29,800	52,200	30.1	
1/5/2012	1229	10.31	-1.72	72,800	27,700	53,400	30.1	
1/12/2012	1204	10.10	-1.51	76,000	30,800	52,900	30.1	
1/19/2012	1139	10.38	-1.79	76,500	28,100	50,800	30.0	
1/26/2012	1229	10.18	-1.59	73,200	29,900	56,300	30.1	
2/2/2012	1229	10.23	-1.64	72,400	27,900	52,000	30.1	
2/10/2012	1209	9.21	-0.62	72,000	29,800	55,400	30.2	
2/16/2012	1359	9.45	-0.86	72,700	27,700	57,200	30.2	

ft. btoc: feet below top of casing

TOC: Top of Casing

ft. NAVD 88: North American Vertical Datum of 1988

umhos/cm: micromhos per centimeter

mg/L: milligrams per liter

C: Celsius

Note: TOC elevation is: 8.59 feet NAVD 88

## Proposed Turkey Point Units 6 and 7

Docket Nos. 52-040 and 52-041

L-2012-087 Enclosure 3 Page 23 of 45

Project: Florida Power & Light Company  
 Miami-Dade County, Florida  
 Exploratory Well EW-1

MHC



**EW-1 Pad Monitoring Well Water Quality Data**  
**Northwest Pad Monitoring Well**  
**(NW-EW PMW)**

Date	Time (hours)	Depth to Water (ft. btoc)	Water Elevation (ft. NAVD 88)	Specific Conductance (umhos/cm)	Chloride (mg/L)	TDS (mg/L)	Temperature (degrees C)	Remarks
4/21/2011	1221	10.50	-1.66	84,300	33,500	59,900	30.8	
4/29/2011	1120	10.65	-1.81	86,300	33,700	56,400	30.0	
5/5/2011	1051	11.40	-2.56	87,400	31,300	57,650	31.1	
5/11/2011	1034	12.40	-3.56	79,100	33,500	55,650	30.4	
5/19/2011	1113	13.90	-5.06	80,000	36,000	53,700	30.4	
5/26/2011	1125	10.73	-1.89	75,130	32,300	55,450	30.4	
6/2/2011	1215	10.75	-1.91	75,900	30,700	59,500	30.3	
6/9/2011	1248	10.60	-1.76	72,500	32,200	51,950	29.9	
6/16/2011	1118	10.25	-1.41	72,500	31,500	54,550	30.0	
6/23/2011	1143	10.37	-1.53	73,300	31,600	57,750	30.3	
6/30/2011	1049	10.10	-1.26	75,700	27,400	54,300	30.0	
7/8/2011	1112	9.38	-0.54	74,100	30,700	53,950	30.3	
7/14/2011	1524	9.75	-0.91	79,900	27,600	56,350	30.3	
7/21/2011	1226	9.60	-0.76	76,200	32,600	54,500	29.7	
7/28/2011	1154	9.80	-0.96	74,900	32,200	57,050	30.5	
8/4/2011	1317	9.85	-1.01	78,000	30,500	59,300	28.7	
8/11/2011	1134	9.61	-0.77	77,600	31,100	58,150	30.4	
8/18/2011	1114	9.68	-0.84	73,100	30,000	55,350	30.6	
8/25/2011	1114	9.61	-0.77	72,300	31,800	56,950	30.0	
9/1/2011	1149	9.33	-0.49	71,900	29,300	56,000	30.4	
9/8/2011	1124	9.45	-0.61	73,800	30,100	52,300	30.5	
9/16/2011	1203	9.60	-0.76	67,200	23,400	51,650	28.2	
9/23/2011	1204	9.43	-0.59	73,800	30,800	54,450	30.4	
9/29/2011	1205	9.35	-0.51	68,700	27,500	50,800	27.6	
10/6/2011	1154	9.50	-0.66	78,400	30,000	56,550	30.2	
10/13/2011	1133	10.21	-1.37	75,800	29,300	50,500	30.2	
10/20/2011	1124	8.81	0.03	70,200	27,500	56,850	30.1	
10/27/2011	1143	10.39	-1.55	81,500	28,800	54,600	30.2	
11/3/2011	1123	10.50	-1.66	80,500	30,400	55,900	30.1	
11/10/2011	1033	10.37	-1.53	77,800	27,800	58,700	30.1	
11/17/2011	1133	10.71	-1.87	67,900	30,500	57,000	30.3	
11/25/2011	1014	9.58	-0.74	71,700	27,400	53,300	30.2	
12/1/2011	1214	9.80	-0.96	68,500	33,500	53,650	30.1	
12/8/2011	1133	10.37	-1.53	68,700	27,600	57,850	27.7	
12/15/2011	1144	9.75	-0.91	75,500	28,200	52,000	30.0	
12/22/2011	1114	9.87	-1.03	70,600	27,700	52,100	29.9	
12/29/2011	0954	9.97	-1.13	77,700	29,500	51,600	29.9	
1/5/2012	1153	10.52	-1.68	71,800	28,000	52,800	29.6	
1/12/2012	1133	10.35	-1.51	75,400	30,400	51,900	30.0	
1/19/2012	1033	10.42	-1.58	75,600	29,800	50,200	29.9	
1/26/2012	1123	10.35	-1.51	73,200	29,500	56,000	29.9	
2/2/2012	1123	10.35	-1.51	71,100	27,400	51,200	29.9	
2/10/2012	1104	9.38	-0.54	70,300	28,800	54,900	29.8	
2/16/2012	1254	9.67	-0.83	71,100	27,800	55,200	29.8	

ft. btoc: feet below top of casing

TOC: Top of Casing

ft. NAVD 88: North American Vertical Datum of 1988

umhos/cm: micromhos per centimeter

mg/L: milligrams per liter

C: Celsius

Note: TOC elevation is:

8.84 feet NAVD 88

## Proposed Turkey Point Units 6 and 7

Docket Nos. 52-040 and 52-041

L-2012-087 Enclosure 3 Page 24 of 45

Project: Florida Power & Light Company  
 Miami-Dade County, Florida  
 Exploratory Well EW-1

MHC



**EW-1 Pad Monitoring Well Water Quality Data**  
**Southwest Pad Monitoring Well**  
**(SW-EW PMW)**

Date	Time (hours)	Depth to Water (ft. btoc)	Water Elevation (ft. NAVD 88)	Specific Conductance (umhos/cm)	Chloride (mg/L)	TDS (mg/L)	Temperature (degrees C)	Remarks
4/21/2011	1414	10.50	-1.62	72,500	26,400	51,500	30.6	Background Sampling
4/29/2011	1025	10.60	-1.72	77,400	28,300	51,600	29.8	
5/5/2011	0930	11.85	-2.97	75,200	29,000	49,400	28.7	
5/11/2011	1124	16.40	-7.52	78,100	28,300	51,050	31.6	
5/19/2011	1202	15.95	-7.07	73,100	29,700	48,450	32.6	
5/26/2011	1155	11.20	-2.32	66,630	27,800	48,350	29.4	
6/2/2011	1035	11.25	-2.37	68,500	26,000	52,600	29.4	
6/9/2011	1319	11.05	-2.17	65,400	26,300	44,150	29.5	
6/16/2011	1154	10.75	-1.87	64,900	27,000	48,450	29.5	
6/23/2011	1214	10.85	-1.97	65,500	30,400	50,800	29.6	
6/30/2011	1119	10.60	-1.72	68,500	24,300	46,650	29.4	
7/8/2011	1045	9.85	-0.97	64,950	25,600	47,650	29.6	
7/14/2011	1445	10.22	-1.34	69,900	24,800	48,300	29.6	
7/21/2011	1154	10.10	-1.22	67,800	27,400	47,900	29.6	
7/28/2011	1259	10.26	-1.38	67,000	26,600	48,650	27.7	
8/4/2011	1157	10.30	-1.42	68,420	25,600	51,350	27.5	
8/11/2011	1243	9.21	-0.33	67,800	26,400	51,150	29.7	
8/18/2011	1219	10.15	-1.27	66,300	25,400	47,500	29.8	
8/25/2011	1219	10.31	-1.43	66,000	26,900	50,150	29.4	
9/1/2011	1254	9.87	-0.99	65,400	25,700	49,450	29.8	
9/8/2011	1229	9.97	-1.09	66,800	26,300	46,500	29.9	
9/16/2011	1329	10.10	-1.22	64,000	25,700	46,800	28.0	
9/23/2011	1309	9.95	-1.07	66,200	25,800	47,500	29.6	
9/29/2011	1230	9.80	-0.92	64,100	25,400	46,150	27.7	
10/6/2011	1259	9.97	-1.09	76,200	25,800	45,800	29.7	
10/13/2011	1239	10.67	-1.79	69,100	26,100	46,700	29.8	
10/20/2011	1229	9.31	-0.43	64,700	23,800	51,100	29.6	
10/27/2011	1249	10.87	-1.99	75,600	26,500	50,000	29.7	
11/3/2011	1229	10.93	-2.05	75,600	27,700	49,750	29.7	
11/10/2011	1139	10.91	-2.03	73,500	25,500	53,300	29.7	
11/17/2011	1238	11.41	-2.53	63,800	26,900	50,400	29.7	
11/25/2011	1119	10.05	-1.17	65,800	24,900	48,950	29.7	
12/1/2011	1323	11.42	-2.54	65,900	29,600	51,100	29.6	
12/8/2011	1239	10.98	-2.10	64,900	24,800	52,450	27.3	
12/15/2011	1247	10.27	-1.39	70,100	24,800	49,700	29.4	
12/22/2011	1219	10.27	-1.39	66,800	24,900	45,600	29.7	
12/29/2011	1059	10.67	-1.79	71,100	26,400	46,300	29.5	
1/5/2012	1259	11.03	-2.15	64,800	24,900	47,600	29.3	
1/12/2012	1234	10.87	-1.99	69,000	25,700	47,000	29.6	
1/19/2012	1104	11.00	-2.12	69,100	24,900	44,200	29.4	
1/26/2012	1154	10.85	-1.97	67,500	25,900	50,100	29.4	
2/2/2012	1154	10.97	-2.09	65,300	25,200	46,200	29.5	
2/10/2012	1134	9.91	-1.03	65,300	25,400	48,900	29.6	
2/16/2012	1324	10.15	-1.27	64,600	24,100	50,500	29.4	

ft. btoc: feet below top of casing

TOC: Top of Casing

ft. NAVD 88: North American Vertical Datum of 1988

umhos/cm: micromhos per centimeter

mg/L: milligrams per liter

C: Celsius

Note: TOC elevation is: 8.88 feet NAVD 88

<b>Florida Power &amp; Light Company</b> <b>Turkey Point</b> <b>Exploratory Well EW-1</b> <b>Deviation Survey Summary</b>								
Pilot Hole			42-Inch Reamed Hole			32-Inch Reamed Hole		
Date	Depth (feet bpl)	Inclination (degrees)	Date	Depth (feet bpl)	Inclination (degrees)	Date	Depth (feet bpl)	Inclination (degrees)
5/13/2011	90	0.2	5/20/2011	90	0.5	1/21/2012	1,950	0.2
5/14/2011	180	0.4	5/24/2011	180	0.4	1/22/2012	2,010	0.5
6/3/2011	270	0.5	6/6/2011	270	0.0	1/22/2012	2,070	0.3
5/29/2011	345	0.3	6/8/2011	360	0.1	1/31/2012	2,130	0.5
5/29/2011	435	0.4	6/9/2011	450	0.2	1/31/2012	2,190	0.5
5/30/2011	524	0.4	6/10/2011	540	0.3	1/31/2012	2,250	0.3
5/30/2011	614	0.0	6/12/2011	630	0.5	2/1/2012	2,310	0.3
5/31/2011	704	0.2	6/14/2011	720	0.4	2/1/2012	2,370	0.2
5/31/2011	794	0.3	6/15/2011	810	0.4	2/1/2012	2,430	0.4
5/31/2011	884	0.3	6/16/2011	900	0.3	2/1/2012	2,490	0.4
6/1/2011	974	0.5	6/18/2011	990	0.4	2/1/2012	2,550	0.1
6/1/2011	1,064	0.5	7/23/2011	1,080	0.1	2/1/2012	2,610	0.4
7/1/2011	1,154	0.6	7/25/2011	1,170	0.4	2/2/2012	2,670	0.2
7/1/2011	1,244	0.3	7/26/2011	1,260	0.5	2/2/2012	2,730	0.0
7/1/2011	1,334	0.4	7/27/2011	1,350	0.2	2/2/2012	2,790	0.0
7/2/2011	1,424	0.4	7/29/2011	1,440	0.3	2/4/2012	2,850	0.3
7/2/2011	1,514	0.5	8/10/2011	1,530	0.5	2/6/2012	2,910	0.1
7/3/2011	1,604	0.5	<b>28-Inch Reamed Hole</b>			2/7/2012	2,970	0.3
8/13/2011	1,664	0.1				2/17/2012	3,030	0.3
8/15/2011	1,724	0.0	12/7/2011	1,590	0.5	2/17/2012	3,090	0.4
8/15/2011	1,784	0.1	12/8/2011	1,650	0.5	2/17/2012	3,150	0.5
8/16/2011	1,844	0.4	12/9/2011	1,710	0.5	2/17/2012	3,210	0.5
8/16/2011	1,904	0.4	12/10/2011	1,770	0.5			
8/17/2011	1,964	0.1	12/11/2011	1,830	0.5			
8/19/2011	2,024	0.3	12/13/2011	1,890	0.3			
8/19/2011	2,084	0.5	12/29/2011	1,950	0.5			
8/20/2011	2,144	0.2	1/2/2012	2,010	0.4			
8/20/2011	2,204	0.0	1/2/2012	2,070	0.3			
8/22/2011	2,264	0.0	1/3/2012	2,130	0.5			
8/25/2011	2,324	0.1	1/4/2012	2,190	0.4			
8/25/2011	2,384	0.1	1/5/2012	2,250	0.3			
8/26/2011	2,444	0.2	1/10/2012	2,310	0.0			
8/26/2011	2,504	0.0	1/11/2012	2,370	0.3			
8/29/2011	2,564	0.4	1/11/2012	2,430	0.1			
8/31/2011	2,624	0.3	1/12/2012	2,490	0.3			
9/4/2011	2,684	0.4	1/12/2012	2,550	0.4			
9/4/2011	2,744	0.4	1/13/2012	2,610	0.4			
9/4/2011	2,804	0.3	1/13/2012	2,670	0.3			
9/5/2011	2,864	0.4	1/13/2012	2,730	0.3			
9/5/2011	2,924	0.3	1/14/2012	2,790	0.4			
9/5/2011	2,984	0.4	1/14/2012	2,850	0.3			
9/6/2011	3,044	0.1						
9/6/2011	3,104	0.5						
9/7/2011	3,164	0.4						

bpl = below pad level



# X-Y CALIPER GAMMA RAY LOG

Company: FP&L Well: TURKEY POINT EW-1 Field: FLORIDA CITY County: MIAMI-DADE State: FLORIDA  Company: FP&L Well: TURKEY POINT EW-1 Field: FLORIDA CITY County: MIAMI-DADE State: FLORIDA	Country: USA		Proposed Turkey Point Units 6 and 7 Docket Nos. 52-040 and 52-041 L-2012-087 Enclosure 3 Page 26 of 45				
	Location: API #: FPL TURKEY POINT POWER PLANT MCNABB HYDROGEOLOGIC CONSULTING, INC. LAT: 25 25' 19" N LONG: 80 20' 08" W SEC TWP RGE				Other Services: NONE		
					Elevation: K.B. D.F. G.L.		
	Permanent Datum	PAD LEVEL	Elevation				
	Log Measured From	PAD LEVEL					
	Drilling Measured From	PAD LEVEL					
	Date	21-FEB-2012					
	Run Number	FOURTEEN					
	Depth Driller	3230'					
	Depth Logger	3232'					
Bottom Logged Interval	3232'						
Top Log Interval	CASING						
Open Hole Size	32"						
Type Fluid	WATER						
Density / Viscosity	NA						
Max. Recorded Temp.	NA						
Estimated Cement Top	NA						
Time Well Ready	0800						
Time Logger on Bottom	0830						
Equipment Number	GEO1						
Location	FT. MYERS						
Recorded By	J. CATHEY						
Witnessed By	M. CLASEN						
Borehole Record				Tubing Record			
Run Number	Bit	From	To	Size	Weight	From	To
	32.5"	CASING	2978'				
	24"	2978'	2980'				
	22"	2980'	3230'				
Casing Record		Size		Wgt/Ft		Top	
Surface String						Bottom	
Prot. String		34"		.375" W.T.		SURFACE	
Production String						1535'	
Liner							

^  
^  
^  
<<< Fold Here

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

### Comments

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 27 of 45


## BOREHOLE VOLUME IN BARRELS CALCULATED FOR 24" CASING






## MAIN PASS


Database File: fp&lew1.db  
Dataset Pathname: run14/XYCM  
Presentation Format: xycream  
Dataset Creation: Tue Feb 21 12:24:21 2012 by Calc SOC 111108  
Charted by: Depth in Feet scaled 1:1200


0	GAMMA RAY (GAPI)	100	20	X-CALIPER (in)	60
		ABHV (bbl)	20	Y-CALIPER (in)	60
			20	BIT SIZE (in)	60
			TBHV (bbl)		
























































# REPEAT PASS

Database File: fp&lew1.db  
Dataset Pathname: run14/XYCR  
Presentation Format: xycream  
Dataset Creation: Tue Feb 21 12:20:36 2012 by Calc SOC 111108  
Charted by: Depth in Feet scaled 1:240

Proposed Turkey Point Units 6 and 7  
Docket Nos. 52-040 and 52-041  
L-2012-087 Enclosure 3 Page 43 of 45

0	GAMMA RAY (GAPI)	100	20	X-CALIPER (in)	60
		ABHV (bbl)	20	Y-CALIPER (in)	60
			20	BIT SIZE (in)	60
			TBHV (bbl)		





#### Calibration Report

Database File: fp&lew1.db  
 Dataset Pathname: run14/XYCM  
 Dataset Creation: Tue Feb 21 12:24:21 2012 by Calc SOC 111108

#### XY Caliper Calibration Report

Serial Number/Model: 120118-GOI  
 Performed: Tue Feb 21 08:35:00 2012

	Ring		X Caliper		Y Caliper	
1:	23	in	490	cps	492	cps
2:	33.25	in	600	cps	606	cps
3:	40	in	678.5	cps	683	cps
4:	52	in	830	cps	836	cps
5:	60	in	899	cps	897	cps
6:		in		cps		cps

#### Gamma Ray Calibration Report

Serial Number:	120116
Tool Model:	PTS_OH
Performed:	Tue Feb 21 07:11:13 2012
Calibrator Value:	300.0 GAPI
Background Reading:	231.1 cps
Calibrator Reading:	1930.6 cps
Sensitivity:	0.3000 GAPI/cps

Sensor	Offset (ft)	Schematic	Description	Len (ft)	OD (in)	Wt (lb)
			Proposed Turkey Point Units 6 and 7 Docket Nos. 52-040 and 52-041 L-2012-087 Enclosure 3 Page 45 of 45			
GR	7.08		GR-PTS_OH (120116) Open Hole Gamma Ray	3.50	3.38	47.00
YCAL	1.58					
XCAL	1.50					
			XYC-GOI (120118) 4 Arm X-Y Caliper	6.25	3.25	45.00

Dataset:  
 Total Length:  
 Total Weight:  
 O.D.

fp&lew1.db: field/well/run14/XYCMP1  
 9.75 ft  
 92.00 lb  
 3.38 in