

Table 1. Comparison of Matrix, Fracture and Conduit Porosity

Setting	Porosity (%)		
	Matrix	Fractures	Conduit/Channels
Mammoth Cave, Kentucky, USA ¹	2.4	0.02	0.003
Nohoch Na Chich, Yucatan, Mexico ¹	17	0.1	0.5
The Chalk, UK ¹	30	0.01	0.02
Woodville Karst Plain, Florida, USA	27	0.1	0.02

¹ Worthington et al., 2000