

**SONGS Unit 3 Steam Generators
Wear Depths Summary**

| Steam Generator SG3E88 (Through- Wall Wear) | Anti-Vibration Bar | Tube Support Plate | Tube-to-Tube Wear | Retainer Bar | Foreign Object | Total Indications | Tubes with Indications (out of 9727 total per SG) |
|--|-------------------------------|-------------------------------|------------------------------|-------------------------|---------------------------|------------------------------|--|
| ≥ 50% | 0 | 117 | 48 | 0 | 0 | 165 | 74 |
| 35 - 49% | 3 | 217 | 116 | 2 | 0 | 338 | 119 |
| 20 - 34% | 156 | 506 | 134 | 1 | 0 | 797 | 197 |
| 10 - 19% | 1380 | 542 | 98 | 0 | 0 | 2020 | 554 |
| < 10% | 1818 | 55 | 11 | 0 | 0 | 1884 | 817 |
| TOTAL | 3357 | 1437 | 407 | 3 | 0 | 5204 | 919* |

* This value is the number of tubes with wear indications at any depth and at any location. Since many tubes have indications in more than one depth and locations, the total number of tubes is less than the total number of indications.

| Steam Generator SG3E89 (Through- Wall Wear) | Anti-Vibration Bar | Tube Support Plate | Tube-to-Tube Wear | Retainer Bar | Foreign Object | Total Indications | Tubes with Indications (out of 9727 total per SG) |
|--|-------------------------------|-------------------------------|------------------------------|-------------------------|---------------------------|------------------------------|--|
| ≥ 50% | 0 | 91 | 26 | 0 | 0 | 117 | 60 |
| 35 - 49% | 0 | 252 | 102 | 1 | 0 | 355 | 128 |
| 20 - 34% | 45 | 487 | 215 | 0 | 0 | 747 | 175 |
| 10 - 19% | 940 | 590 | 72 | 0 | 0 | 1602 | 450 |
| < 10% | 2164 | 94 | 1 | 0 | 0 | 2259 | 838 |
| TOTAL | 3149 | 1514 | 416 | 1 | 0 | 5080 | 887* |

* This value is the number of tubes with wear indications at any depth and at any location. Since many tubes have indications in more than one depth and locations, the total number of tubes is less than the total number of indications.