



— flashboard failure at 2 ft. no flashboard failure

WLS COL 2.4-2

WILLIAM STATES LEE III
 NUCLEAR STATION UNITS 1 & 2
 Discharge Rating Curve, Gaston Shoals Dam

FIGURE 2.4.3-212 Rev 0