

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Southgate Radiology 15300 Trenton Road Southgate, MI 48195 REPORT NUMBER(S) 2012-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-17665	4. LICENSE NUMBER(S) 21-20030-01	5. DATE(S) OF INSPECTION 09/12/2012
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 3.01-3.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Dennis Vollman, M.D.	4. TELEPHONE NUMBER (313) 281-6600
-----------------------------	------------------	---	---------------------------------------

Main Office Inspection Next Inspection Date: 09/2017

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine inspection of a small cardiology clinic located in Southgate, Michigan. The licensee had a small nuclear medicine program conducting routine imaging and diagnostic procedures. The licensee had one tech who performed approximately 30 procedures per month using unit doses. The clinic received its unit doses from a local nuclear pharmacy.

Performance Observations

The inspection consisted of a tour of the facility, independent measurements, and interviews with staff members. Staff members were knowledgeable in radiation safety and isotope handling techniques. The licensee demonstrated package receipt, dose calibrator constancy check, radioactive waste handling techniques, and area survey techniques. The inspector also reviewed selected records such as dosimetry records, employee training, annual audits, and waste disposals.

No violations of NRC requirements were identified for this inspection.