



**Exelon** Generation®

**LaSalle Station**

2601 North 21st Road  
Marseilles, IL 61341

815 415 2000 Telephone  
www.exeloncorp.com

10 CFR 50.55a(g)

RA12-052

October 26, 2012

United States Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

LaSalle County Station, Unit 1  
Facility Operating License No. NPF-11  
NRC Docket No. 50-373

**Subject:** Amended Post-Outage 90-Day Inservice Inspection (ISI) Summary Report

**Reference:** Letter from David P. Rhoades (Exelon) to the U.S. Nuclear Regulatory Commission, "Post-Outage 90-Day Inservice Inspection (ISI) Summary Report," dated June 5, 2012

Exelon Generation Company, LLC (EGC), submitted the above referenced letter associated with the LaSalle County Station (LSCS) Unit 1 fourteenth refueling outage (L1R14). The documentation for an American Society of Mechanical Engineers (ASME) Section XI replacement activity was omitted in error. The required documentation is enclosed, which includes the Amended Table E for the referenced summary report, and the associated Form NIS-2 "Owner's Report for Repair/Replacement Activity."

To the best of our knowledge and belief, the statements made in this report are correct, and the examinations and corrective measures, as applicable, conform to the rules of the ASME Boiler and Pressure Vessel Code, Section XI.

Should you have any questions concerning this letter, please contact Mr. Stephen T. Shields, Acting Regulatory Assurance Manager, at (815) 415-2811.

Respectfully,

Peter J. Karaba  
Site Vice President  
LaSalle County Station

Attachment

cc: NRC Senior Resident Inspector - LaSalle County Station

A047  
INRR

**UNIT 1  
AMENDED TABLE E  
REPAIR/REPLACEMENT ACTIVITIES**

The following Unit 1 Owner's Report of Repair or Replacement, form NIS-2, has been prepared by the LaSalle County Station (LSCS) ISI Program Owner and certified by Mr. Adam M. Prine, ANII, State of Illinois #2146 IC:

**CLASS-2**

**WORK PACKAGE #**

**DESCRIPTION**

1. 1515404

Replace Double Block Valves

**FORM NIS-2 OWNER'S REPORT FOR REPAIR/REPLACEMENT ACTIVITY**  
As Required by the Provisions of ASME Code Section XI

1. Owner Exelon Generation Company (EGC) LLC Date 02/29/2012  
(Name)  
200 Exelon Way, Kenneth Square, PA, 19348 Address Sheet 1 of 1
2. Plant LaSalle County Nuclear Station Unit 01  
Name  
2601 N. 21<sup>st</sup> Rd, Marseilles, IL 61341 Address W.O. # 1515404  
Repair Organization, P.O. No., Job No., etc.
3. Work Performed by Mechanical Maintenance Type Code Symbol Stamp N/A  
(Name)  
Mechanical Maintenance Address Authorization No. N/A  
(Address) Expiration Date N/A
4. Identification of System RHR (Residual Heat Removal)
5. (a) Applicable Construction Code 1974 Edition No Addenda, Code Cases none  
(b) Applicable Edition of Section XI Used for Repair/Replacement Activity 2001 Ed., 2003 Ad.  
(c) Applicable Section XI Code Case(s) none
6. Identification of Components

Name of Component	Name of Mfr.	Mfrs. Ser. No.	Nat'l Bd. No.	Other Identification	Year Built	Corrected Removed, or Installed	ASME Code Stamped (Yes or No)
1-1/2"x 3/4" Reducing Insert	Chicago Tube & Iron	HT. 0881	N/A	UTC# 2908589	1980	Installed	No

7. Description of Work : Class 2 Replacement, \* = per N-5 or NIS-2 Code Data Report on file at LaSalle Station
8. Tests Conducted: Hydrostatic  Pneumatic  Normal Operating Pressure  Exempt  Other   
Pressure 1032 psig Test Temp. Ambient Deg. F
9. Remarks, Original Code of Construction of Reducing Insert is ASME Section III, Class 2, 1974 Edition, Summer of 1975 Addenda. Reconciled per Eval NCS 8934.


(Applicable Manufacturer's Data Report to be Attached)

**CERTIFICATION OF COMPLIANCE**

I certify that the statements made in the report are correct and that this conforms to the requirements of the ASME Code, Section XI.

Type Code Symbol Stamp none

Certificate of Authorization No. N/A Expiration Date N/A

Signed Andrew L. Kochis  ISI Coordinator Date October 2, 2012  
Owner or Owner's Designee, Title

**CERTIFICATE OF INSERVICE INSPECTION**

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Illinois and employed by The Hartford Steam Boiler Insp. & Ins. Co. of Connecticut have inspected the components described in this Owner's Report during the period L1R14 to L1R15

and state that to the best of my knowledge and belief, the Owner has performed examinations and taken corrective measures described in this Owner's Report in accordance with the requirements of the ASME Code, Section XI. By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations and corrective measures described in this Owner's Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

 \_\_\_\_\_  
Inspector's Signature Commissions NB 13411, ANI, IL 2146 IC  
National Board, State, Province, and Endorsements

Date 10.3.2012