



3/2/12

Krupp Drive Facility Survey Scan Results

Instrument: Biodex Model 14c Survey Meter #051-014; Serial # 110522

Background (average): 0.01-0.04 mR/hr

Area/Section	mR/hr
1 – Restricted Area (RA) unit dose counter	0.01-0.04
2 – RA DOT table	0.01-0.04
3 – RA DOT table	0.01-0.04
4 – RA Gen table	0.01-0.04
5 – RA Gen Box	0.01-0.04
6 – RA Iodine room counter	0.01-0.04
7 – RA Shipping counter	0.01-0.04
8 – RA Shipping counter	0.01-0.04
9 – RA breakdown room counter	0.01-0.04
10 – RA breakdown room counter	0.01-0.04
11 – RA breakdown room counter	0.01-0.04
12 – RA QC table	0.01-0.04
13 – RA sink and drain	0.01-0.04
14 – RA processing counter	0.01-0.04
15 – RA prescription table	0.01-0.04
16 – RA prescription table	0.01-0.04
17 – RA compounding area floor	0.01-0.04
18 – RA compounding area floor	0.01-0.04
19 – RA gen room floor	0.01-0.04
20 – RA iodine room floor	0.01-0.04
21 – RA breakdown room floor	0.01-0.04
22 – RA ship area floor	0.01-0.04
23 – RA DOT area floor	0.01-0.04
24 – Non restricted area(NRA) desk	0.01-0.04
25 – NRA breakroom table	0.01-0.04
26 – NRA front office desk	0.01-0.04

PharmaLogic Ltd

1191 S Brownell Rd, Ste 30 ♦ P.O. Box 786 ♦ Williston, VT 05495

802-862-9944 ♦ Fax: 802-863-1633

27 – RA backroom floor	0.01-0.04
28 – NRA bathroom sink	0.01-0.04
29 – NRA floor	0.01-0.04
30 – NRA floor	0.01-0.04
A – Fume hood exhaust (FHE) lower section	0.01-0.04
B – FHE middle section	0.01-0.04
C – FHE upper section	0.01-0.04