




— flashboard failure at 6 ft. no flashboard failure

WLS COL 2.4-2

WILLIAM STATES LEE III
NUCLEAR STATION UNITS 1 & 2

Discharge Rating Curve,
Ninety-Nine Islands Dam

FIGURE 2.4.3-213

Rev 0