

From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1

From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1

Annotated Photographs from CAP 01291889



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1

Annotated Photographs from CAP 01291889



From CAP 01291889,
Bottom Inspection of Cask #1

From CAP 01291889,
Bottom Inspection of Cask #1

From CAP 01291889,
Bottom Inspection of Cask #1

From CAP 01291889,
Bottom Inspection of Cask #1



From CAP 01291889,
Bottom Inspection of Cask #1