

Rio Algom Mining LLC

July 30, 2014

Mr. Tom McLaughlin
11555 Rockville Pike
Rockville, MD 20852

Re: **Ambrosia Lake Facility**
License SUA-1473, Docket No. 40-8905
License Condition #34
1st Half 2014 Groundwater Stability Monitoring Report

Dear Mr. McLaughlin:


Pursuant to license condition #34 for License SUA-1473, attached is the semi-annual Groundwater Stability Monitoring Report for the 1st Half of 2014. This report describes the results associated with the groundwater stability monitoring plan established by Amendment #56.

A digital copy of the report is also included in the package.

If you have any questions or need additional information, please call me at (520)208-1014

Sincerely,

Rio Algom Mining LLC


Anthony Baus
Site Manager

Attachment: As stated

cc: NRC – Document Control (certified mail)
NMED, David Mayerson (provide by email)
T. Ballaine, RAML
D. Murray, RAML